

PERFORATION RECOMMENDATION SHEET

FIELD: HAPPY VALLEY MORROW LEASE: HAPPY VALLEY FED. COM WELL No: 1
 LOCATION: 1780' FNL 1830' FEL, SEC. 28, T-22S, R-26E, EDDY COUNTY, N.M.

ZERO POINT: _____ TYPE OF PERF: _____ SHOTS/FOOT: 4 SRF
 SERVICE COMPANY: _____ CASING SIZE: 3405 SHOTS TOTAL

PERFORATIONS (add formation/zone names as required)				CORRECTED COLLARS
MORROW				
11556 -	11561	5'		
11476 -	11480	4'		
11434 -	11442	8'		
11400 -	11424	24'		
11380 -	11384	4'		
11362 -	11372	10'		
11294 -	11304	10'		
11278 -	11286	8'		
11258 -	11270	12'		
		85'	340 SHOTS	

REFERENCE LOG: Run Gamma-ray/CCL/Neutron log prior to job and fax to Midland office.

CORRELATION TIE-IN POINT: _____

REMARKS: _____

RES. ENGR/DATE: [Signature] 12/11/89 SUBSURF ENGR/DATE: [Signature] GEOLOGIST/DATE: W.L. Tice/12/11/89

