

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions
verse side)

Budget Bureau No. 1004-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

NM-0554771

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

T.O.G. Federal

9. WELL NO.

5

10. FIELD AND POOL OR WILDCAT

East Burton Delaware

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 16: T20S, R29E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Siete Oil and Gas Corporation

3. ADDRESS OF OPERATOR

P.O. Box 2523

Roswell, NM 88202-2523

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below)

At surface 2310' FNL & 1650' FEL, SW $\frac{1}{4}$ NE $\frac{1}{4}$, Unit Letter G

14. PERMIT NO.

30-015-26261

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3274.3' GR

C. C. D.
ARTESIA, OTHER

12. COUNTY OR PARISH

Eddy

13. STATE

NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

5/22/90

TIH w/abrazijet to 4371', abrazijet slot @ 4371' for 30 min w/20/40 sand, TOH w/abrazijet, TIH w/pkr & tbq, spot 1 bbl acid over abrazijet slot, pull pkr to 4275', acidized w/500 gals 15% HCl, formation broke @2100 PSI, AIR-4.4 BPM @ 1520 PSI, ISIP-1000, @ 5 min-810, @ 10 min-730, @ 15 min-630, fraced w/5000 gal 25# XL, 750# 100 mesh, 8750# 20/40 & 2000# 12/20, AIR-6.6 BPM @ 1800, FPIP-2100, ISIP-1150, @ 5 min-900, @ 10 min-840, @ 15 min-740, SION.

5/24/90

RU & began swabbing, IFL 2500' FS, made 40 runs w/2% oil cut, FFL 2500' FS.

5/29/90

TOH w/pkr & tbq, TIH w/RBP, pkr & tbq, RU Schlumberger & perfed 3229'-3245.5' w/12 perfs, spot 2 bbls acid over perfs, set pkr @ 3137', RBP @ 3350', test RBP to 2000#, held ok, acidized w/1000 gal 15% HCl, AIR-3.4 BPM @ 1800 PSI, balled out @ 4200 PSI, ISIP-1160, @ 5 min-1000, @ 10 min-980, @ 15 min-960, fraced w/19000 gal 25# XL, 2000# 100 mesh, 30000# 20/40 & 8000# 12/20 RCS, max-3100, min-1950, ISIP-1400, @ 5 min-1270, @ 10 min-1250, @ 15 min-1200, SION.

5/30/90

ITP-300, began flowback & prep to swab.

18. I hereby certify that the foregoing is true and correct

SIGNED

Cathy Butler-Sieck

TITLE

DrIng. & Prod. Tech.

DATE

6/18/90

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side