

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING  
OFFICE FOR NUM  
OF COPIES REQUIRED  
(Other instructions on re-  
verse side)

BLM Roswell District  
Modified Form No.  
NMD60-3160-4

258

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER		5. LEASE DESIGNATION AND SERIAL NO. NM 81929	
2. NAME OF OPERATOR YATES PETROLEUM CORPORATION		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A	
3. ADDRESS OF OPERATOR 105 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME N/A	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 563' FSL & 2125' FEL (NM-15881) Sec. 11-T20S-R29E Producing zone: 2480' FNL, 1980' FEL (NM-81929) Sec. 14-T20S-R29E		8. FARM OR LEASE NAME Zia ZS Federal Com	
14. PERMIT NO. 30-015-26262		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3295' GR		10. FIELD AND POOL, OR WILDCAT Undes. Morrow	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit 0, Sec. 14-T20S-R29E	
		12. COUNTY OR PARISH Eddy	13. STATE NM

RECEIVED

APR 27 '90

O. C. D.

APR 29 1990

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐

PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☐  
SHOOTING OR ACIDIZING ☒  
(Other) Set CIBP, perforate, treat

REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

3-22-90. WIH and perforated 8 - .40" holes as follows: 12542, 43, 44, and 12615, 16, 17, 18, and 12619' (1 SPF). Acidized perforations 12542-12619' w/1000g. 7½% acid.  
3-29-90. Set CIBP at 12505'. Perforated 12202-12383' w/28 .40" holes as follows: 12202, 03, 04, 05, 06, 07, 08, 09, 12262, 63, 64, 65, 66, 12273, 74, 75, 76, 77, 78, 79, 12346, 47, 48, 49, 12380, 81, 82 and 12383'. Acidized perfs in three (3) stages w/4500 gals 7½% Morrow acid + 1000 scf N2/bbl.

ACCEPTED FOR RECORD

APR 24 1990

18. I hereby certify that the foregoing is true and correct

CARLSBAD, NEW MEXICO

SIGNED [Signature]  
(This space for Federal or State office use)

TITLE Production Supervisor

DATE 4-6-90

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side