

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enr , Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26586
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-1673
7. Lease Name or Unit Agreement Name Lost Tank AIS State
8. Well No. 3
9. Pool name or Wildcat Wildcat Delaware
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3564' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator YATES PETROLEUM CORPORATION (505) 748-1471
3. Address of Operator 105 South 4th St., Artesia, New Mexico 88210	4. Well Location Unit Letter N : 660 Feet From The South Line and 1980 Feet From The West Line Section 36 Township 21S Range 31E NMPM Eddy County
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Perforate, Treat ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-21-91. Drilled out DV tool at 5922'. Perforated 8288, 89 and 8390' (2 SPF-6 shots) .42" holes. Acidized perfs 8288-90' w/500 gals 7½% NEFE acid.
2-23-25-91. Swabbed well dry. No show oil or gas.
2-27-91. Set CIBP 8270' w/15' cement on top. Perforated 6783-7084' w/46 .42" holes as follows: 6783, 84, 85, 92, 93, 99, 6800, 03, 07, 08, 09, 10 (24 holes-2 SPF) and 7055, 60, 62, 64, 68, 70, 72, 74, 76, 81, 84 (22 holes-2 SPF). Acidized perfs 7055-84' w/2000 gals 7½% NEFE acid and eprfs 6783-6810' w/2000 gals 7½% NEFE acid. Swabbed and flowed well.
3-2-91. Set pumping equipment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 3-7-91
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

MAR 13 1991

APPROVED BY SUPERVISOR, DISTRICT II TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: