Submit 3 Copies to Appropriate District Office

State of New Mexico nerals and Natural Resources Department

Form (2.	10	5
Revise	d :	1-1	

		2

OΠ.	CONSERVATION DIVISION

P.O. Box 2088 Fe New Mexico 87504-2088

ELL API NO. 30-015-2675	1	
. Indicate Type of Le	STATE X	FEE

والأرابية وممروأ المدورية والمائم والمجارة الدارمية

DISTRICT	OIL CONSERVAL	TOTA DI ADDICIA	30-015-26751	
P.O. Box 1980, Hobbs, NM 88240	P.O. Box	2000 50 87504-2088		
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic		5. Indicate Type of Lea	STATE A FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		NOV 1 4 1991	6. State Oil & Gas Lea V-1673	se No.
(DO NOT USE THIS FORM FOR PI DIFFERENT RES (FORM	TICES AND REPORTS ON V ROPOSALS TO DRILL OR TO DEE! ERVOIR. USE "APPLICATION FOR C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit	Agreement Name
1. Type of Well: OIL GAS WELL WELL	OTHER		Lost Tank A	IS State
2 Name of Operator YATES PETROLEUM CORPO	DRATION /		6 9. Pool name or Wildo	
3. Address of Operator 105 South 4th St., A			Lost Tank De	laware
4. Well Location	980 Feet From The South	Line and	Feet From Th	e East Line
Unit Letter :		31 E	NMPM Ed	ldy County
Section 36	Township 21S 10. Elevation (Show wh	ether DF, RKB, RT, GR, etc.)	MAILEM	
<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	/////// 3592	' GR	emort or Other D	//////////////////////////////////////
11. Chec	k Appropriate Box to Indic	ate Nature of Notice, h	SEQUENT RE	PORT OF:
NOTICE OF I	NTENTION TO:			TERING CASING
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		LUG AND ABANDONMENT
TEMPOFARILY ABANDON	CHANGE PLANS	COMMENCE DRILLIN		_ocalito , la me el mello
PULL OR ALTER CASING]	CASING TEST AND C	EMENIJUB	
OTHER:	Operations (Clearly state all pertinent det	OTHER:	indian animated date of at	arring any proposed
Spudded 26" hole 11:0 Notified Johnny Robin PM 11-6-91. Reached Guide shoe set 868', Poz W/2% CaCl2 + 1/4#	O AM 11-5-91. Set 40 son, NMOCD, Artesia, 1 TD 3:45 AM 11-7-91. insert float set 824' / xx Celloseal (yield eld 1.32, wt 14.8). sacks cement. WOC. Desi for 30 mins. Red	fo 20" conductor NM, of spud. Resure Ran 20 joints 13 Cemented w/600 1.76, wt 12.9). The PD 10:45 AM 11-7-9	med drilling 1 3/8" 54.5# J-5 sx Pacesetter Tail in w/250 s 01. Bumped plu	17-1/2" hole 1:00 55 casing set 868'. Lite "C" + 65-35/6 sx "C" w/2% CaC12 + ug to 450 psi, float OC 23 hrs and 45 min
I hereby Certify that the information above	re is true and complete to the best of my know	eigo and beief. THIE Production	Supervisor	
SIGNATURE 1 GASTIA	Jandlet	misrouderion		тецерноне NO. 505/748-1
TYPE OR PRINT NAME Jus	anita Goodlett			
(This space for State Use) OR	GINAL SIGNED BY			NOV 2 1 1991
-0.411	(E WILLIAMS PERVISOR, DISTRICT II	тпце		DATE