Submit 3 Copies to Appropriate District Office

DISTRICT II

State of New Mexico
E \_\_\_\_y, Minerals and Natural Resources Department

A 252627262

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL ARIMO. 30-048-00372 303

STATE

sIndicate Type of Lease

State Oil & Gas Lease No.

FEE

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

P.O. Drawer DD, Artesia, NM 88210

| 1000 RO BIAZOS Nu.   | , Aztec, NIVI 07410        |                       |       |                    | ¥ .           |   |      |        |  |
|--|----------------------------|-----------------------|-------|--------------------|---------------|---|------|--------|--|
| SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.) |                            |                       |       |                    |               | 7Lease Name or Unit Agreement Name Airport 35 |      |        |  |
| ₁Type of Well:<br>OfL<br>WELL  | GAS<br>WELL                |                       | OTHER |                    |               |   |      |        |  |
| 2Name of Operate<br>Pogo Producing   |                            |                       | CONF  | neur!              | 39            | ₅Well No.<br>1                                |      | •      |  |
| 3Address of Oper<br>P. O. Box 1034   | ator<br>10, Midland, TX 79 | 702-7340              |       |                    | 3. <b>3.3</b> | ∘Pool name or Wildcat<br>Happy Valley De      |      |        |  |
| 4Well Location Unit Letter   | M : 990                    | Feet From The         | South | Line and           | 990           | Feet From The                                 | West | Line   |  |
| Section  | 35                         | Township              | 228   | Range              | 26E           | NMPM  | Eddy | County |  |
| 1  |                            | ₁₀Elevatio<br>3259' G | •     | DF, RKB, RT, GR, e | tc.)          |   |      |        |  |

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING

TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ANBANDONMENT CASING TEST AND CEMENT JOB

OTHER: Spud, Set Surface & Production Casing Machine Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

work) SEE RULE 1103.

Spud & Set Surface Csg - Spud well @ 1030 hrs CDT 8/31/98 w/ Auger Air. MIRU Key Energy #41 @ 0400 hrs CST 11/22/98. Drld 12-1/4" hole to 670'. TD reached @ 1900 hrs CST 11/24/98. Ran 15 jts 8-5/8" 32# J-55 ST&C csg. TPGS @ 670'. IFV @ 624'. BJ cmt'd w/ 340 sks BJ Lite @ 12.4 ppg followed by 150 sks Cl "C" + 2% CaCl2 @ 14.8 ppg. Circ 100 sks cmt. Plug down @ 2330 hrs CST 11/24/98. WOC 18 hrs. Cmt has compressive strength over 500 psi after 8 hrs. Weld on WH. NU BOP's and test to 2000#.

Production Csg - Drld 7-7/8" hole to 5220'. TD reached @ 0400 hrs CST 12/3/98. Ran 118 jts 5-1/2" 15.50# J-55 LT&C csg. Float shoe @ 5220'. Float collar @ 5172'. DV tool @ 2034'. BJ cmt'd 1st stage w/ 1210 sks Cl "H" + .3% FL52 + .3% CD32 + .15% SMS + .1% R3 @ 15.7 ppg. Circ 150 sks cmt. Cmt 2nd stage w/ 455 sks BJ Lite + .15% FL52 + .1% SMS @ 12.4 ppg followed by 100 sks Cl "C" + .15% FL52 + .5% CD32 + .1% SMS @ 14.8 ppg. Drop plug & displace cmt. Plug down @ 0215 hrs CST 12/5/98. ND BOP's & cutoff WH. CBL ran 12/10/98. TOC @ 900'.

| I hereby certify that the information above is true and complete to the best of SIGNATURE  Of high structure and complete to the best of t | f my knowledge and belief.  ππιε Operations Technician | DATE 01-25-99    |
|--|--|------------------|
| TYPE OR PRINT NAME   |  | TELEPHONE NO.    |
| (This space for State Use)  Jim W Burn  APPROVED BY  | Blutiet Seper  | visov<br>/-76.99 |