aber 1994)

STATES UNIT: DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CHARRY NOTICES	AND	PEPORTS	ON	WFL	1	۶
CHARGO MITHERS	44 174 1	BEFURIO	LJIT			

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996	C\9
---	-----

•	· T	C 1	MI.
•	Lease	Senai	INO.
-	-		•


186	COEC
MM	กกาก

6. If Indian, Allottee or Tribe Name

Do not use this abandoned we	ii. Use Form 3160-3 (AP	D) for such proposals.			
SUBMIT IN TRI	PLICATE - Other Instr	uctions on reverse s	side	7. If Unit or	CA/Agreement, Name and/or No.
Type of Well Gas Well G	Other			8. Well Nam	ne and No. FS FFD 14 # 1
Name of Operator E G L Resources, Inc.			9 % 2	9. API Well	
P.O. POK 371. Midland.	тх 79702	3b. Phone No. (include (915) 682–3502	area code)	· · · · · · · · · · · · · · · · · · ·	Pool, or Exploratory Area
Location of Well (Footage, Sec., 660' FSL & 2210' FWL				11. County o Section	r Parish, State 1 14, T-20-S, R-28-E,NMPM
12. CHECK AP	PROPRIATE BOX(ES) T			EPORT, OR	OTHER DATA
TYPE OF SUBMISSION		TYP	E OF ACTION		
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construction	Production (Star Reclamation Recomplete Temporarily At		Water Shut-Off Well Integrity Other
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Water Disposal		

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is made for final inspection. determined that the site is ready for final inspection.)

SEE ATTACHMENT "A"



14. I hereby certify that the foregoing is true and correct Name (Printed Typed) Denom Printz Signature	Title Secretary Date (/ 4/19	
THIS SPA	ACE FOR FEDERAL OR STATE OFFICE USE	
Approved by	Tide	Daic
Conditions of approval, if any, are attached. Approval of this certify that the applicant holds legal or equitable title to those which would entitle the applicant to conduct operations thereon	t.	
	to any densityment of	agency of the United States any false, fictitious or

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



ATTACHMENT A

E G L RESOURCES, INC.

OXY YATES FEDERAL 14#1

12-2–1998	Building location
12-4-1998	Moving in rig
12-5-1998	Rigged up and set 42' of 8 5/8" conductor pipe. Waiting on air. Drilling to start Tuesday.
12-6-1998	Drilling to start Tuesday
12-7-1998	Drilling to start Tuesday
12-8-1998	TD 176', Notified Carlsbad BLM of spudding.
12-9-1998	TD 288,
12-10-1998	TD 629,
12-11-1998	TD 750' Ran TOTCO. Dev. ¼ deg Laid down drill pipe. Ran 28 Jts 5 ½ " 15.50 lb. J-55 Rng 2 Csg. Set Csg. 1' off btm. Pumped 515 sks class "C" cemented to surface. BLM Jim Amos present for cementing
12-11-1999	TD 835', made 85' air drilling.
12-15-1998	TD 835' GIH w/drill collars and 4 3/4" bit on 2 3/8" tubing, drill.
12-16-1998	TD 876'. Laid down drl. Collars & bit. Ran SN(1"), 25 jts 2 3/8" J-55 4.7# tbj. Made up well head. RDPU & RPU. Released Weatherford. SI well. Waiting on surface facilities.