

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.

RECEIVED
OCD - ARTESIA

38. GEOLOGICAL MARKERS			38. GEOLOGICAL MARKERS		
NAME	TOP		NAME	TOP	
	MEAS. DEPTH	TRUE VERT. DEPTH		MEAS. DEPTH	TRUE VERT. DEPTH
QUEEN	432'				
DELAWARE	1440'				
BONE SPRINGS LIME	3767'				
WOLFCAMP LIME	7182'				
CISCO	8303'				
ATOKA	9475'				
MORROW	9850'				
BARNETT	10200'				