

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
gy, Minerals and Natural Resources Depart

cliff
HP

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-21858
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name Martin
2. Name of Operator Meteor Developments, Inc	8. Well No. 3
3. Address of Operator 511 16th Street, Ste. 400, Denver CO 80202	9. Pool name or Wildcat S. Carlsbad Cherry Canyon
4. Well Location Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>North</u> Line and <u>2000</u> Feet From The <u>West</u> Line Section <u>20</u> Township <u>22 South</u> Range <u>27 East</u> NMPM Eddy County	

10. Elevation (Show whether DF, RRB, RT, GR, etc.)
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/2/98

Ran & set CIBP @ 3216'. Set tubing @ 3216'. Circulated Brine gel to surface. Pulled tubing to 3216'. Pumped 25 Sx cement plug at 3216'-2976'. Pulled tubing to 2046'. Pumped 25 Sx cement plug 2046'-1806'. Pulled tubing. Freepointed and cut 5 1/2" casing @ 1628'. Ran and set tubing at 1669'. Pumped 25 Sx cement plug 1660'-1429' Cut & pulled 5 1/2" casing at 771'. Ran tubing to 821'. Pumped 40 Sx cement plug. W.O.C. ran tubing & tagged TOC @ 352'. Set tubing at 352' & pumped 96 Sx cement. Cement circulated to surface. Cut off wellhead and placed dry hole marker @ edge of farmland with direction on marker to well bore.

Post ID-2
6-11-99
RA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maria S. Swaffield TITLE Field Rep. II DATE Feb 9-99

TYPE OR PRINT NAME _____ TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Maria S. Swaffield TITLE Field Rep. II DATE Feb. 9 99

CONDITIONS OF APPROVAL, IF ANY: