## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

to Appropriate District Office

DISTRICT I P.O. Box 1980, Hobbs, NM \$8240

DISTRICT II P.O. Drawer DD, Artesia, NM \$8210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

P.O. Box 2088 ECciville Santa Fe, New Mexico 87504-2088 APR 2 4 1991 WELL API NO. 30-015-23287 5. Indicate Type of Lease

6. State Oil & Gas Lease No.

FEE X

O. C. U. ARTESIA, OFFICE

7. Lease Name or Unit Agreement Name
Malaga A

Undesignated

STATE

	HIS FORM FOR PROPOSA	AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A USE "APPLICATION FOR PERMIT" OR SUCH PROPOSALS.)
1. Type of Well:	GAS ,	OTHER

WELL X WELL 2. Name of Operator

Southwest Royalties, Inc 3. Address of Operator

Midland, Texas 79702 c/o Box 953, 4. Well Location

North 660\_ Feet From The

24S

Line and 28E

660 Feet From The

8. Well No.

9. Pool name or Wildcat

Township

Range

**NMPM** 

County Eddy

11.

OTHER:

10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

X

## SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK TEMPORARILY ABANDON

PULL OR ALTER CASING

PLUG AND ABANDON CHANGE PLANS

REMEDIAL WORK COMMENCE DRILLING OPNS

OTHER:

ALTERING CASING

CASING TEST AND CEMENT JOB

ل	PLUG AND ABANDONMENT	لــا
_		

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

(1). Casing detail: 18-5/8" @ 407', cemented w/ 705 sx - circulated. 13-3/8" @ 2557', cemented w/ 2550 sx - circulated.

9-5/8" @ 9500', cemented w/ 3300 sx - circulated. 5-1/2" @ 13,050', cemented w/ 1600 sx TOC - 8390.

(2). Cast Iron Bridge Plug to be set @ 11,560' w/ 20' cement on top.

(3). If casing is free @  $6500 \stackrel{+}{-}$ , set CIBP in 5-1/2" 50' below, cut off, cut and pull 5-1/2" casing, spot 100' cement on top of CIBP.

(4). Perforate Bone Springs zone - 6342 - 6373 - 22 holes, run 9-5/8" packer to approximately 6370', spot 150 gals. 7-1/2% acid.

	11		
I hereby certify that the informat	tion above artise and complete in the test of my knowledge and be	Agent	DATE4-22-91
SIGNATURE	Ann E. Ritchie	(9:	5) телетноме мо. 684-6381
TYPE OR PRINT NAME	Aun E. Ricente		

CONDITIONS OF APPROVAL, IP ANY: