

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
30-015-27071

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Fortson Oil Company ✓

3. Address of Operator
3325 W. Wadley, Suite 213, Midland, TX 79707

7. Lease Name or Unit Agreement Name

Pinnacle State

8. Well No.
2

9. Pool name or Wildcat
Herradura Bend, East Delaware

4. Well Location
Unit Letter E : 1650 Feet From The North Line and 330 Feet From The West Line
Section 36 Township 22S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3104' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/2/93 - Rig Up

11/3/93 - POOH w/rods & pump. Shop pump. RU kill trk & kill well. Strip on BOP. Pick up 11 jts 2-7/8" tbg, Tag btm @ 6335'. POOH w/2-7/8" tbg. 190 jts total. Pick up & RIH with 20' M.A. Btm of MA @ 6293'. 33' Jts 2-7/8", 4' Perf sub, 1.10 SN @ 6234.90, 394.92' of 2-7/8" tbg (12 jts) 2.80 TAC @ 5838.18, 5838.18' of 2-7/8" tbg (189 jts) Strip of BOP. Flange up wellhead.

11/4/93 RIH w/following pump & rod assembly: 16' Gas Anchor, 2-1/2 X 1-1/2 X 20' RHAC Pump (top holedown) 50' 2-25' K bars, 3400' 136 -3/4" rods (steel) 2775' 1 1/2-7/8" rods (steel) 4 1/2-4' ponyrod, 16' in hole 1-1/4" X 22' polish rod, (6245') total. Set pump @ 6245' KB, space out & start pumping unit.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Judy Dixon

TITLE

Production Technician

11/11/93

DATE

TYPE OR PRINT NAME

915-520-4341

TELEPHONE NO.

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS

SUPERVISOR, DISTRICT I

TITLE

DATE

NOV 23 1993