Submit 3 Copies to Appropriate District Office	State of New Energy,nerals and Natural		Form C-103 Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240		208RECEIVED	<b>WELL API NO.</b> 30 015 27094
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexic	co 87504-2088 - NOV 1 9 100つ	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		O. C. D.	6. State Oil & Gas Lease No. L-6442
( DO NOT USE THIS FORM FOR PRODIFFERENT RESERVANCE)	PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A SERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name
1. Type of Well: OIL GAS WELL X WELL	OTHER	· · · · · · · · · · · · · · · · · · ·	Poker Lake 32 State
2. Name of Operator			8. Well No.
<u>Enron Oil &amp; Gas Com</u> 3. Address of Operator	ipany	<u> </u>	9. Pool name or Wildcat
P. O. Box 2267. Midl	and, Texas 79702		Wildcat Delaware
NOTICE OF INTERFORM REMEDIAL WORK  EMPORARILY ABANDON  ULL OR ALTER CASING  THER:	Appropriate Box to Indica FENTION TO:  PLUG AND ABANDON  CHANGE PLANS	TE Nature of Notice, R SUE REMEDIAL WORK COMMENCE DRILLING CASING TEST AND C OTHER:	ALTERING CASING  G OPNS. PLUG AND ABANDONMENT  EMENT JOB X
work) SEE RULE 1103.  11-08-92 - TD 8050'	woos (Cleany state all peninent aeial	is, ana give periment aates, incli	uding estimated date of starting any proposed
11-09-92 - Set 5-1/2	" 17# J-55 & S-95 LT	&C & 15.5# J-55 L	T&C production casing at 8049'
Cemented		sacks Halliburto e, 12.4 ppg, 2.06	n light cement + 6/sx salt, cuft/sx.
Cemented	5#/sx gilsonit Mix & pump 165	e, 12.4 ppg, 2.06 sacks Halliburto	
	5#/sx gilsonit Mix & pump 165	e, 12.4 ppg, 2.06 sacks Halliburto f 1% Halad-322, 1	<pre>cuft/sx. n Prem Plus w/8#/sx Silicate + 3.6 ppg, 1.80-cuft/sx.</pre>

Adores		DATE
Gildon		915/686-3714 TELEPHONE NO.
GINAL SIGNED BY		NOV 1 6 1992
	GINAL SIGNED BY	GINAL SIGNED BY  E WILLIAMS  ERVISOR, DISTRICT # mla