

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

CISF
AP

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other	WELL API NO. 30-015-31372
2. Name of Operator OXY USA WTP Limited Partnership	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250	6. State Oil & Gas Lease No. LG1133
4. Well Location Unit Letter <u>F</u> : <u>1650</u> feet from the <u>north</u> line and <u>1650</u> feet from the <u>west</u> line Section <u>36</u> Township <u>23S</u> Range <u>24E</u> NMPM County <u>Eddy</u>	7. Lease Name or Unit Agreement Name: OXY Seets State
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3878'	8. Well No. 192463 1
	9. Pool name or Wildcat Undsg Baldridge Canyon Morrow

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

TD-10660' PBT-10540' PERFS-10016-10493'
CASING: 13-3/8" 48# @ 400', 17-1/2", cmt w/400sx, TOC-Circ
8-5/8" 32# @ 2615', 12-1/4", cmt w/1479sx, TOC-Circ
5-1/2" 17# @ 10659', 7-7/8", cmt w/840sx, TOC-6800'-CALC
1. RIH & set CIBP @ 9966', dump 5sx cmt on top
2. M&P 25sx cmt @ 8900-8800'
3. M&P 25sx cmt @ 7700-7600'
4. Cut & pull 5-1/2" csg at approximately 6800'
5. M&P 30sx cmt @ 6850-6750', WOC-TAG
6. M&P 45sx cmt @ 4100-4000'
7. M&P 40sx cmt @ 2665-2565', WOC-TAG
8. M&P 40sx cmt @ 450-350'
9. M&P 20sx cmt Surface Plug - (10# MLF between plugs)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Sr. Regulatory Analyst DATE 9/4/02

Type or print name David Stewart

Telephone No. 915-685-5717

(This space for State use)

APPROVED BY [Signature] TITLE Wild Sep ID DATE SEP 16 2002
Conditions of approval, if any:

OXY USA WTP LP
OXY SEETS STATE #1
SEC 36 T23S R24E EDDY NM

