

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	MEAS. DEPTH	TRUE VERT. DEPTH
Delaware Bone Spring	4415	-940	ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC., (continued from the front) Frac'd w/ 29,400 gals of 10% KCL + 83,200# 16/30 OTTAWA. Frac'd w/10,300 gals of 2% XE905 + 28,000# 16/30 OTTAWA. Frac'd w/10,300 gals of 2% XF905 + 28,000# 16/30 OTTAWA.	Rustler	809'	
	8269'	-4794		Top Salado	1135'	
				Base Salado	4185'	
				Delaware	4415'	
				Bone Spring	8269'	
		DEPTH				
		8217'-8230'				
		7406'-7421'				
		7105'-7116'				