Form 9-331 (May 1963) DEPART	UNITED STATES ME OF THE INTERIG	SUBMIT IN TRIPT CATE* (Other instructio n re- verse side)	Form approve Budget Burea LEASE DESIGNATION NM-11042	d. u No. 42-R1424. AND BERIAL NO.
SUNDRY NOT (Do not use this form for propo Use "APPLIC.	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
OIL GAS WELL OTHER 2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME ROSS Draw 8. FARM OR LEASE NAME			
Penroc Oil Corporat 3. ADDRESS OF OPERATOR	Ross Draw Unit			
P. O. Drawer 831, M 1. LOCATION OF WELL (Report location of See also space 17 below.) At surface	5 10. FIELD AND POOL, OR WILDCAT Wildcat 11. SEC., T., R., M., OR BLK, AND SURVEY OR AREA			
14. PERMIT NO.	15. ELEVATIONS (Show whether DF.	. , ,	Sec. 27-26S 12 COUNTY OF PARISH Eddy	
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)	ppropriate Box To Indicate N NTION TO: PULL OR ALTER CASING X MULTIPLE COMPLETE ABANDON* CHANGE PLANS	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (NOTE: Report results	Other Data UENT REPORT OF: REPAIRING WALTERING CA ABANDONMEN S of multiple completion of letion Report and Log for	ASING ON Well
7/18 to 7/23/77: Shot 9 5/8", 4	onally drifted, give subsurface locat 7#, N-80 casing off @	details, and give pertinent dates, ions and measured and true vertic	including estimated date al depths for all markers	a of starting one
1. Set 150 stub-en 2. Set 150 3. Set 100 13 3/8"	el by Jim Knauf to set o' cement plug (Class ad of 9 5/8" casing. o' cement plug (Class o' cement plug (Class o' casing set @ 3300'.	H cement) 6556-6406' H cement) 5056-4906' H cement) 3349-3249' of 13 3/8" casing.	in and out of	-
RECEIVED		ſ	RECEIVE	D

NOV 9 1977

J. C. D.

U.S. GEULUGICAL CURVEY ARTESIA, NEW MEXICO

I hereby certify that the foregoing is true and correct	TITLE Pres	ident	DATE	8/8/77
 (This space for Federal or State office use)				
APPROVED BY	TITLE:		DATE	