

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions
verse side)

TE
re

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO

NM 0522A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Bass Enterprises Production Co.

3. ADDRESS OF OPERATOR

P O Box 2760 Midland Texas 79702-2760

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface

1980' FSL & 1980' FWL of Unit Letter K

14. PERMIT NO.

30-015-24190

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3493' GL

3519' KB

O. C. D.
ARTESIA, OFFICE

7. UNIT AGREEMENT NAME

Poker Lake Unit

8. FARM OR LEASE NAME

Poker Lake Unit

9. WELL NO.

58

10. FIELD AND POOL, OR WILDCAT

Big Sinks Wolfcamp (Gas)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 27, 24S 31E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON*

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS

(Other)

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Move in rig up Wireline Co. with 10,000 PSI lubricator.
2. Run in hole with 1 9/16" RTG Deep Jet PML Gun with 4 gm charges.
3. Perforate 2 SPF. (Wolfcamp) interval 12,108' - 12,147' total 40 shots. Acidize with 1500 gals. HCl
4. Clean up around location, turn well to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

[Signature]

TITLE

Senior Prod. Clerk

DATE

3-2-89

(This space for Federal or State office use)

APPROVED BY

[Signature]

TITLE

DATE

3-6-89

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side