(June 1990) DEPARTMEN BUREAU OF I SUNDRY NOTICES Do not use this form for proposals to dri	ترين STATES T OF THE INTERIOR AND MANAGEMENT AND REPORTS ON WELLS Il or to deepen or reentry to a different res PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
KX Oil Well Gas Well Other 2 Name of Operator Other Other		8. Well Name and No. Corral Federal Unit #2
YATES PETROLEUM CORPORATION - (505) 748-1471)		9. API Well No.
3. Address and Telephone No.		30-015-27554
105 South 4th St., Artesia, NM 88210 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		10. Field and Pool, or Exploratory Area North Brushy Draw Delaware
990' FSL & 2310' FWL of Section		Eddy County, New Mexico
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent	X Abandonment Recompletion Plugging Back Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off New Construction Non-Routine Fracturing Non-Routine Fracturing New Construction New Constructio
Final Abandonment Notice	Altering Casing Other	Conversion to Injection 77 Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface locations and measured and true vertice 6-26-95 - Moved in and rigged and pump. Nipple up BOP. PC Rigged up wireline. TIH with TIH with tubing to 5200'. Sp Mix and pump 25 sacks Class C 6-27-95 - Notified Jim Amos w at 2840'. POOH with tubing. 5-1/2" pull nipple. Rigged u free point at 1150'. Rigged 1100'. Rigged down wireline. down casing eqiupment. Nippl C cement from 1150' (in 5-1/2 down for night. 6-28-95 - Notified Jim Amos w tubing and tag top of cement with tubing to 516'. Mix and POOH with tubing to 50'. Mix	c cement from 3100-2550'. POOH w /BLM-Carlsbad of plugs. TIH wit Nippled down BOP and wellhead. up casing jacks. Pulled slips an up wireline. TIH w/4-1/2" jet c Rigged up casing tongs. POOH	pumping unit. POOH with rods perforated sub and mud anchor. Capped CIBP with 35' of cement. 000'. POOH with tubing to 3100'. ith tubing. Shut down for night. h tubing and tag top of cement Rigged up welder. Welded on d took casing stretch. Estimate utter and cut 5-1/2" casing at with 5-1/2" casing. Rigged 150'. Mix and pump 45 sacks Class sing). POOH with tubing. Shut cement plug. TIH with 2-7/8" from 1005' to surface. POOH om 516-416' (in 8-5/8" casing). t from 50' to surface. POOH w/
Signed Husto Hun (This space for Fed (a) public up)	Tite Production Clerk	
Approved by Approval, if any:	Title Title	Date2 6 1995

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.