

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

38. GEOLOGIC MARKERS

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
Delaware MTN. GROUP	4529	8318	SAND, SHALE, LIME	TOP RUSTLER	800	
				TOP SALT	1120	
				BASE SALT	4301	
				TOP DELAWARE	4529	
				MTN. GROUP		
				TOP BONE	8373	
				SPRING LIME		