State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

1. Type of Well GAS State Po Box 4289, Farmington, NM 87499 (505) 326-9760 5. Lease Fee 6. State 7. Lease 8. Well 1158 9. Pool	Sundry Notices and Reports on Wells	
2. Name of Operator BURLINGTON RESCURCES OIL & GAS COMPANY 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9760 4. Location of Well, Footage, Sec., T, R, M 1780'FNL, 1005'FWL, Sec.20, T-32-N, R-6-W, NMPM, San Juan County Type of Submission Notice of Intent Abandonment Recompletion Notice of Intent Recompletion New Construction New Construction New Construction Plugging Back Non-Routine Fractur Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection	ssigned by OCD) 045-31233 Se Number Se Oil&Gas Lease	
8. Well 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9760 4. Location of Well, Footage, Sec., T, R, M 10. Eleva 1780'FNL, 1005'FWL, Sec.20, T-32-N, R-6-W, NMPM, San Juan County Type of Submission Notice of Intent Abandonment Recompletion New Construction Plugging Back Non-Routine Fractur Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection	e Name/Unit Name	
PO Box 4289, Farmington, NM 87499 (505) 326-9760 9. Pool Basin 4. Location of Well, Footage, Sec., T, R, M 10. Eleva 1780'FNL, 1005'FWL, Sec.20, T-32-N, R-6-W, NMPM, San Juan County Type of Submission Type of Action Notice of Intent Abandonment Change of Plans Recompletion New Construction Plugging Back Non-Routine Fracture Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection	son Unit No.	
Type of Submission Notice of Intent X Subsequent Report Final Abandonment Type of Action Abandonment Recompletion Plugging Back Casing Repair Altering Casing Conversion to Injection Altering Casing Conversion Type of Action Change of Plans New Construction Non-Routine Fracture Water Shut off Conversion to Injection Conversion to Injection Type of Action Non-Routine Non-Routine Fracture Casing Repair Conversion to Injection Conversion to Injection Type of Action Abandonment Abandonment Change of Plans New Construction Non-Routine Fracture Casing Repair Conversion to Injection	Name or Wildcat n Fruitland Coal	
Notice of Intent Abandonment Recompletion Y Subsequent Report Casing Repair Final Abandonment Abandonment Abandonment Abandonment Change of Plans New Construction Non-Routine Fractur Casing Repair Water Shut off Conversion to Injection	ation:	
Motice of Intent Abandonment Recompletion X Subsequent Report Casing Repair Final Abandonment Abandonment Abandonment Abandonment Change of Plans New Construction Non-Routine Fractur Casing Repair Water Shut off Conversion to Injection		
X Subsequent Report Plugging Back Non-Routine Fractus Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection		
Final Abandonment Altering Casing Conversion to Injection	ıring	
	ection	
13. Describe Proposed or Completed Operations		
2/8/03 MIRU. ND WH. NU BOP. PT BOP & csg to 600 psi/30 mins, OK. Dr:	cilling	
<pre>ahead. 2/10/03 Drill to intermediate TD @ 3050'. Circ hole clean.</pre>		
2/11/03 TOOH. TIH w/72 jts 7" 20# J-55 ST&C csg, set @ 3050'. Cmtd w, Premium Lite w/3% calcium chloride, 0.25 pps celloflake, 5 0.4% fluid loss, 0.4% sodium metasilicate, 8% gel (897 cu. Tail w/90 sxs Type 3 w/1% calcium chloride, 0.25 pps cellof 0.2% fluid loss (124 cu. ft.). Circ 35 bbls cmt to surface. & csg to 1500 psi/30 mins, OK. Drilling ahead. 2/12/03 Drill 6-1/4" hole to 3183'. Circ hole clean. TIH, underream 6	5 pps LCM-1, ft.). oflake, e. PT BOP	
out to 12" hole @ 3050-3183'. Circ hole clean. TOOH. 2/13/03 TIH w/101 jts 2-3/8" 4.7# J-55 tbg, set @ 3164'. ND BOP. NU wreleased.		
GIGNATURE TAMMY WEST for Regulatory Supervisor_February 27,		
This space for State Use)	W	
DEPUTY OIL & GAS INSPECTOR, DIST. 33	MAR -3 2003	