Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

3.	Lease Serial No.	
	NMMM0608	

Т	If Indian	Allottee or Tribe Name	

abandoned wel	II. Use form 3160-3 (APD) f	for such proposals.	6. If In	dian, Allottee or Tri	be Name	
SUBMIT IN TRI	PLICATE - Other instruction	ns on reverse side.		7. If Unit or CA/Agreement, Name and/or No. NMNM78425A		
1. Type of Well		29 30 29 30 P		Name and No.		
Oil Well Gas Well Oth		The Comment	1-2	32-9 13A		
2. Name of Operator BURLINGTON RESOURCES	GGY COLE lail: pcole@br-inc.com 200:	30-	9. API Well No. 30-045-22912-00-S1			
3a. Address 3401 EAST 30TH FARMINGTON, NM 87499	o. Phone No. (include area code h: 505.326.9727 x: 505.326.9781		10. Field and Pool, or Exploratory BLANCO MESAVERDE			
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)	(C)	11. Co	unty or Parish, and	State	
Sec 14 T31N R10W SESE 11 36.89403 N Lat, 107.84615 W		CONTENSE OF THE PARTY OF THE PA	SAI	N JUAN COUNT	Y, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT	, OR OTHER D	ATA	
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION			
Notice of Intent	☐ Acidize	Deepen	Production (Star	rt/Resume)	Water Shut-Off	
_	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	C	Well Integrity	
Subsequent Report	Casing Repair	☐ New Construction	☐ Recomplete		Other	
Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Temporarily Ab	andon		
	Convert to Injection	□ Plug Back	☐ Water Disposal			
determined that the site is ready for f (11/20/02) MIRU. SDON. (11/21/02) TOOH w/rods. ND (11/24/02) TIH w/tbg, tag up ((11/25/02) TIH w/RBP, set @ mins. Reset RBP @ 4575', se Release pkr & RBP. SDON. (11/26/02) TOOH w/pkr & RBi w/RBP, set @ 4606'. Set pkr (SDON. (11/27/02) PT 4-1/2" csg to 10 set @ 3355'. PT 4-1/2" Inr top Isolate 7" csg leak @ 1602'. S	WH. NU BOP. TOOH w/2-3/	5880 <sup>†</sup> . TOOH w/tbg. SDOI 5'. PT tbg to 2700 psi, lost of to 2700 psi, lost 2000 ps mill @ 4500' to 4675'. TOO si, OK. Release pkr & TOO sx sand on RBP. TOOH w @ 1540'. PT 7" csg to 120	t 1500 psi in 2 ii in 5 mins. DH w/bit & mill. TIH DH. Set pkr @ 3418' /pkr. TIH w/pkr, 0 psi, OK.			
14. Thereby certify that the foregoing is  Con Name (Printed/Typed) PEGGY C	Electronic Submission #169 For BURLINGTON RESC nmitted to AFMSS for process	OURCES O&G CO LP, sent sing by Matthew Halbert on	to the Farmington	397SE)		
Tumou Typedy   Loot C	, OLL	THE REGUL	ZATORT ADMINIOT	TATOR		
Signature (Electronic S	Submission)	Date 12/19/2	2002			
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE USE			
Approved By ACCEPT	ED		W HALBERT EUM ENGINEER		Date 01/27/2003	
Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the su uct operations thereon.	bject lease Office Farming				
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a cri-	me for any person knowingly an	d willfully to make to an	y department or age	ency of the United	

## Additional data for EC transaction #16995 that would not fit on the form

## 32. Additional remarks, continued

(12/2/02) PT lines to 3500 psi, OK. Sqz w/300 sx Class "C" neat cmt (417 cu. ft.). WOC. Rls pkr & TOOH. TIH w/bit. SDON. (12/3/02) Tag cmt @ 1510'. Drill out cmt @ 1510' to 1571'. PT csg to 500 psi, OK. TOOH w/bit. TIH w/bit. PT csg to 500 psi, OK. TOOH w/bit. SDON. (12/4/02) TIH w/bit. Tag up @ 1571'. Drill thru cmt @ 1608'. Circ w/power swivel to 1671'. PT csg to 500 psi/15 mins, OK. TOOH w/bit. TIH w/tbg to 3320'. Blow well. SDON. (12/5/02) TIH to 4606', release RBP. TOOH w/RBP. TIH w/bit. CO to 5873'. Flow well. TOOH w/bit. SDON. (12/6/02) TIH w/188 jts 2-3/8" 4.7# J-55 tbg, set @ 5865'. SN @ 5829'. ND BOP. NU WH. TIH w/pump & rods. PT & pump action, OK. RD. Rig released.