

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.

SF - 081001

6. If Indian, Allottee or tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

8. Well Name and No.

Florance Gas Com E 9

2. Name of Operator

BP America Production Company Attn: Mary Corley

9. API Well No.

30-045-09488

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4491

10. Field and Pool, or Exploratory Area

Blanco Mesaverde

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

990' FSL & 990' FWL Sec. 13 T30N, R09W

11. County or Parish, State

San Juan County, New Mexico

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

Other PayAdd

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

02/19/2004 MIRUSU. Blow down wellhead. NDWH. NU BOPs. Test BOPs to 300#. Test OK. TOH w/production TBG. RU, TIH w/RBP & set @ 1000'. Load hole with 2% KCL. Press Test to 500#. Test ok. TIH, latch onto RBP & TOH. RU & run GR/CCL log. TIH & set RBP @ 4740'. RU & Perforate Menefee formation w/2 JSPF, .340 inch diameter, 15 Shots / 30 Holes: 4480', 4488', 4492', 4500', 4534', 4540', 4549', 4556', 4558', 4590', 4605', 4625', 4637', 4668', 4692'. Spearhead 500 gal 15% HCL, establish injection rate, and frac w/89,185# 16/30 Brady Sand, 70% Quality Foam & N2. RU & flowback frac thru 1/4" choke for 8 hrs. Upsized to 1/2" choke & flowed back for 7 hrs. TIH & tag fill @ 4529'. C/O to top of RBP. TIH & latch onto RBP & TOH. TIH & C/O to PBTD @ 4926'. TOH. TIH w/2-3/8" production TBG & and land @ 4832'. ND BOP's. NUWH
03/12/2004 RDMOSU 17:00 hrs. Return well to production.

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Mary Corley

Title Sr. Regulatory Analyst

Signature

Date 03/17/2004

ACCEPTED FOR RECORD

MAR 24 2003

FARMINGTON FIELD OFFICE

THIS SPACE FOR FEDERAL OR STATE OFFICE USE BY

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or
Certify that the applicant holds legal or equitable title to those rights in the
subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States
any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOC