submitted in lieu of Form 3160-5

UNITED STATES

DEPARTMENT OF THE INTERIOR

BUREAU OF	LAND MANAGE	MENT				
Sundry Notic	ces and Repor	ts on Wells				
1. Type of Well GAS			SF-07	Numbe 8580 dian, Name		. or
2. Name of Operator BURLINGTON RESCURCES OIL & GAS 3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 4. Location of Well, Footage, Sec. 990'FSL, 1650'FWL, Sec. 05, T30	87499 (505)	CSTELLY	8. Well Howel 9. API W 30-04 10. Field Blanc 11. Count	Name & 1 A 2 lell No. 5-1210 land 1 co Mesay and Tuan Co	& Nu o. 65 Pool aver Sta	mber de te
12. CHECK APPROPRIATE BOX TO INDITED Type of Submission Notice of Intent _X_ Subsequent Report Final Abandonment 13. Describe Proposed or Complet Burlington Resources perfort per the attached oper	Abandonmon Recomple Plugging Casing Roman Altering Other - Sted Operation Comed workover	<pre>vpe of Action ent Change of tion New Const. Back Non-Routi: epair Water Shu Casing Conversion ns</pre>	Plans ruction ne Fractu t off n to Inje	ction		
		ACCEPTED FOR I APR 1 9 200 FARMINGTON FIELD BY		. 070 Familiation, NM	231	
14. I hereby certify that the f			D-4- 4/7	/0.4	-	
Signed / Ammulul State (This space for Federal or State APPROVED BY	Office use)Title person knowingly and	Pate Date willfully to make to any department of the state of the st	t or agency of		- - -	

BURLINGTON RESOURCES

San Juan Division - Intranet Well Information System (DIMS)

Thursday, April 1, 20

Logon	By Date	By Well	÷By AFE	-By Rig
Printouts	Production N	Notes 🕶Account	ability 💌Safety	-
	Other	- ¥ APIU	nits	

Export to Excel

Operations Detail Report for: HOWELL A #2 FACILITIES

Entire Well / All Events

Time Breakdown Summary

DAY	FROM	то	HRS	DEPTH (ft)	PHASE	CODE	S	OPERATION
1 (FAC)	11/15/2003 06:00	07:00	1.00		ОВЈЕСТ	MIMO a	N	CREW TRAV TO SEYMOUR # 1B
1 (FAC)	11/15/2003 07:00	07:15	0.25		OBJECT	SRIG a	N	SERVICE & START RIG.
1 (FAC)	11/15/2003 07:15	07:30	0.25		OBJECT	SAFE a		SAFETY MEETING. 4 AZTEC WELL SERV, TOPIC - RIG MOVE W/ MUDDY CONDITIONS.
1 (FAC)	11/15/2003 07:30	09:00	1.50		ОВЈЕСТ	MIMO a	N	CHAIN UP, ROAD RIG TO LOCATION. ROADS MUDDY.
1 (FAC)	11/15/2003 09:00	10:00	1.00		ОВЈЕСТ	RURD a		SPOT RIG, RIG UP RIG # 485. CHANGE OUT TRAVELING BLOCKS.
1 (FAC)	11/15/2003 10:00	11:30	1.50		ОВЈЕСТ	MIMO a		MOVE IN & SPOT EQUIPMENT. RIG UP TEFTELLER, SET TBG PLUG @ 5,308'.
1 (FAC)	11/15/2003 11:30	12:30	1.00		OBJECT	MIMO a	N	MOVE IN FLOW BACK TANK, NIPPLE UP FLOW LINE, SHUT IN TBG & CSG PRESS - 120 PSI. BLEED CSG TO TANK
1 (FAC)	11/15/2003 12:30	13:45	1.25		ОВЈЕСТ	NUND a		NIPPLE DOWN TREE, NIPPLE UP BOP, RIG UP FLOOR
1 (FAC)	11/15/2003 13:45	15:30	1.75		OBJECT	STUK a	N	WORK STUCK PIPE FREE W/ 15,000# OVERPULL, PULLED 2 JTS. TBG PARTED @ 1,120'. THRDS PULLED OUT OF CPLG. TBG WAS BENT.
1 (FAC)	11/15/2003 15:30	15:45	0.25		OBJECT	TRIP a		TRIP OUT W/ 36 JTS 2-1/16" 3.25# J-55 10rd IJ TBG. TBG THRDS WERE NOT TIGHT, AND ALL 36 JTS ARE SLIGHTLY BENT.
1 (FAC)	11/15/2003 15:45	16:00	0.25		OBJECT	SHDN a	N	SHUT WELL IN SECURE LOCATION, SHUT DOWN FOR SUNDAY.
2 (FAC)	11/17/2003 06:00	07:00	1.00		OBJECT	OMIM a	N	CREW TRAV TO LOCATION
							$\overline{\sqcap}$	

2 (FAC)	11/17/2003 07:00	07:15	0.25	OBJE	SI	RIG a	N	SERVICE & START RIG.
2 (FAC)	11/17/2003 07:15	07:30	0.25	OBJE	T S/	AFE a		SAFETY MEETING. 4 AZTEC WELL SERV, TOPIC - FISHING
(FAC)	11/17/2003 07:30		0.50	ОВЈЕ	H	AIT a		WAIT ON WEATHERFORD FISHING TOOLS & TOOL HAND, WEATHERFORD TOOLS OR HAND DID NOT SHOW, THEY WERE NOTIFIED 11/15/2003 WHEN TBG PARTED TO BE ON LOCATION @ 07:00 11/17/2003. MAN ON CALL DID NOT NOTIFY ANY ONE ABOUT JOB. WHEN CALLED THEY ADDMITTED SCREWING UP, BUT DID NOT HAVE ANYONE AVAIABLE. CALLED BAKER.
2 (FAC)	11/17/2003 08:00	09:45	1.75	OBJE	- 11	JLD a		TRIP IN W/ 36 JTS 2-1/16" 3.25# J-55 10rd IJ TBG & LAY DOWN
(FAC)	11/17/2003 09:45			ОВЈЕ	- 11	ISH a		PICK UP OVER SHOT W/ 2" GRAPPLE, JARS & 38 JTS 2-3/8" 4.7# J-55 8rd EUE TBG, CATCH TOP OF FISH @ 1,139', WORK FISH UP HOLE 12'.
2 (FAC)	11/17/2003 13:00	14:15	1.25	OBJE	- 11	ISH a	S	RELEASE OVERSHOT, TRIP OUT W/ 38 JTS 2-3/8" TBG, LAY DOWN JARS, TRIP IN W/ OVERSHOT & JARS, CATCH FISH. WORK STUCK PIPE, NO PROGRESS.
(FAC)	11/17/2003 14:15			ОВЈЕ	ll l	SH a	S	MOVE IN WIRELINE SPECIALTIES & RIG UP, FREE POINT @ 5,135', RUN IN W/ CHEMICAL CUTTER @ CUT @ 5,135'.
2 (FAC)	11/17/2003 16:30	17:15	0.75	ОВЈЕ	- 11	SH a	S	TRIP OUT W/ 25', OVERSHOT RELEASED, LATCHED ON SEVERAL TIMES, PULL FISH W/ 5,000# OVERPULL & OVERSHOT WOULD RELEASE
2 (FAC)	11/17/2003 17:15	17:30	0.25	ОВЈЕС	TSF	IDN a	N	SHUT WELL IN, SHUT DOWN FOR NIGHT.
3 (FAC)	11/18/2003 06:00	07:00	1.00	ОВЈЕС	- 11	MO a	N	CREW TRAV TO LOCATION
3 (FAC)	11/18/2003 07:00	07:15	0.25	ОВЈЕС	TSF	RIG a	N	SERVICE & START RIG.
3 (FAC)	11/18/2003 07:15	07:30	0.25	OBJEC	11	AFE a	N	SAFETY MEETING. 4 AZTEC WELL SERV, TOPIC - COLD WEATHER SAFETY
(FAC)	11/18/2003 07:30			OBJEC	11	SH a	T S	TRIP OUT W/ 38 JTS 2-3/8" 4.7# J-55 8rd EUE TBG & OVERSHOT.
3 (FAC)	11/18/2003 08:00	09:00	1.00	OBJEC	- 11	SH a	[S]	CHANGE GRAPPLE, PICK UP JARS, TRIP IN HOLE W/ 38 JTS 2-3/8" 4.7# J-55 8rd EUE TBG. GRAPPLE WOULD NOT BITE TBG CPLG.
3 (FAC)	11/18/2003 09:00	09:30	0.50	ОВЈЕС	- 11	SH a	T S	TRIP OUT W/ OVERSHOT.
3 (FAC)	11/18/2003 09:30	10:15	0.75	OBJEC	- 11	SH a	T S	PICK UP MILL, TRIP IN TO TOP OF FISH.
3 (FAC)	11/18/2003 10:15	11:45	1.50	ОВЈЕС	- 11	ILL a	S	MILL ON FISH @ 1,120' W/ 850 SCF/M AIR MIST @ 10 BBLS/HR. MILL 1' TO DRESS TOP OF FISH. TRIP OUT W/ MILL.

3 (FAC)	11/18/2003 11:45	13:30	1.75	ОВЈЕСТ	FISH a	T S	TRIP IN W/ OVERSHOT, CATCH FISH, WORK FISH FREE, HAD 10,000# - 15,000# DRAG FIRST 3 JTS PULLED, THEN PULLED FREE, TRIP OUT TO FISH.
3 (FAC)	11/18/2003 13:30	16:15	2.75	ОВЈЕСТ	FISH a	S	LAY DOWN JARS & OVERSHOT, LAY DOWN 175 JTS 2-1/16" 3.25# J-55 10rd IJ TBG. JT 166 HAD LARGE HOLE IN CENTER OF JT.
3 (FAC)					a	S	STRAP, CALIPER & PICK UP 6 ea 3-1/4" DRILL COLLARS, X-OVERS & MILL. STRAP, DRIFT & PICKUP 10 JTS 2-3/8" 4.7# J-55 8rd EUE TBG.
3 (FAC)	11/18/2003 17:15	17:30	0.25	 ОВЈЕСТ	SHDN a		SHUT WELL IN, SECURE LOCATION, DRAIN LINES, SHUT DOWN FOR NIGHT.
4 (FAC)	11/19/2003 06:00	07:00	1.00	ОВЈЕСТ	MIMO a	N	CREW TRAV TO LOCATION
4 (FAC)	11/19/2003 07:00	07:15	0.25	ОВЈЕСТ	SRIG a	N	SERVICE & START RIG.
4 (FAC)	11/19/2003 07:15	07:30	0.25	ОВЈЕСТ	SAFE a		SAFETY MEETING. 4 AZTEC WELL SERV, TOPIC - ICE, WATCH STEP
4 (FAC)	11/19/2003 07:30	09:30	2.00	ОВЈЕСТ	PULD a	N	STRAP, DRIFT & PICK UP 148 JTS 2-3/8" 4.7# J- 55 8rd EUE TBG. TAG @ 5,056'. MEENEFEE PERFS 5,062' TO 5,150'
4 (FAC)	11/19/2003 09:30	11:00	1.50	ОВЈЕСТ	BLOW a		BREAK CIRC W/ 850 SCF/M AIR MIST @ 5 BBLS/HR @ 1,500 PSI.
4 (FAC)	11/19/2003 11:00	16:15	5.25	OBJECT	COUT a	S	CLEAN OUT HARD SCALE & SAND FROM 5,056' TO TOP OF FISH @ 5,135' W/ 850 SCF/M AIR MIST @ 10 BBLS/HR.
4 (FAC)	11/19/2003 16:15	17:00	0.75	ОВЈЕСТ	MILL a	S	DRESS TOP OF FISH W/ MILL. CIRC W/ 850 SCF/M AIR MIST @ 14 BBLS/HR. SWEEP HOLE W/ 5 BBLS.
4 (FAC)	11/19/2003 17:00	17:30	0.50	OBJECT	TRIP a		TRIP OUT W/ 40 JTS 2-3/8" 4.7# J-55 8rd EUE TBG, SHUT WELL IN, SECURE LOCATION, SHUT DOWN FOR NIGHT.
5 (FAC)	11/20/2003 06:00	07:00	1.00	ОВЈЕСТ	MIMO a	N	CREW TRAV TO LOCATION
5 (FAC)	11/20/2003 07:00	07:15	0.25	OBJECT	SRIG a	N	SERVICE & START RIG.
5 (FAC)	11/20/2003 07:15	07:30	0.25	OBJECT	SAFE a		SAFETY MEETING. 4 AZTEC WELL SERV, TOPIC - ICE, WATCH STEP
5 (FAC)	11/20/2003 07:30	08:45	1.25	OBJECT	FISH a		TRIP OUT W/ 120 JTS 2-3/8" 4.7# J-55 8rd EUE TBG, LAY DOWN MILL.
5 (FAC)	11/20/2003 08:45			OBJECT	FISH a	S	PICK UP OVERSHOT, JARS, ACCELERATOR, & 160 JTS 2-3/8" 4.7# J-55 8rd EUE TBG, TAG FISH @ 5,136'.
5 (FAC)	11/20/2003 10:30	13:30	3.00	ОВЈЕСТ		S	CATCH FISH, JAR ON FISH W/ 60,000# TOTAL WT. FIRST HR MADE 8', SECOND HR MADE 12', THIRD HOUR MADE 30', PULLED 120' W/ 30,000# DRAG OVER STRING WT, FISH PULLED FREE IN 160'.
5 (FAC)	11/20/2003 13:30	14:45	1.25	OBJECT	FISH a		TRIP OUT W/ 160 JTS 2-3/8" 4.7# J-55 8rd EUE TBG.
	, 76	- 1	-	 			

5 (FAC)	11/20/2003 14:45	16:00	1.25	ОВЈЕСТ			LAY DOWN 6 ea 3-1/4" DRILL COLLARS, JARS, ACCELERATOR, & 8 JTS 2-1/6" 3.25# J-55 8rd EUE TBG W/ SEATING NIPPLE & EXPENDABLE CHECK. 100% RECOVERY, TBG WAS NOT BENT, BUT WAS FULL OF SAND.
5 (FAC)	11/20/2003 16:00	17:15	1.25	ОВЈЕСТ	TRIP a	N	TRIP IN W/ 3-7/8" BLADE BIT & 140 JTS 2-3/8" 4.7# J-55 8rd EUE TBG.
5 (FAC)	11/20/2003 17:15	17:30	0.25	OBJECT	SHDN a	N	SHUT WELL IN, SECURE LOCATION, SHUT DOWN FOR NIGHT.
6 (FAC)	<u> </u>	<u> </u>	<u> </u>	OBJECT	MIMO a	N	CREW TRAV TO LOCATION
6 (FAC)	11/21/2003 07:00	07:15	0.25	OBJECT	SRIG a	N	SERVICE & START RIG.
6 (FAC)	11/21/2003 07:15	07:30	0.25	OBJECT	SAFE a	N	SAFETY MEETING. 4 AZTEC WELL SERV, TOPIC - ICE, WATCH STEP
6 (FAC)	11/21/2003 07:30	09:00	1.50	OBJECT	TRIP a	N	TRIP IN HOLE W/ 20 JTS OUT OF DERRICK, STAP, DRIFT & PICKUP 26 JTS 2-3/8" 4.7# J-55 8rd EUE TBG, TAG FILL @ 5,151'.
6 (FAC)	11/21/2003 09:00	10:30	1.50	ОВЈЕСТ	CIRC a	N	BREAK CIRC W/ 850 SCF/M AIR MIST @ 14 BBLS/HR.
6 (FAC)	11/21/2003 10:30	12:30	2.00	OBJECT	COUT a	N	CLEAN OUT HARD SAND FROM 5,151, TO 5,214'. RISER PIPE ON UPRIGHT FLOW BANK TANK FLUID CUT @ WELDED ELBOW.
6 (FAC)	11/21/2003 12:30	13:00	0.50	ОВЈЕСТ	TRIP a	N	TRIP OUT W/ 40 JTS 2-3/8" 4.7# J-55 8RD EUE TBG.
6 (FAC)	11/21/2003 13:00	14:00	1.00	ОВЈЕСТ	SHDN a	N	SHUT WELL IN, SECURE LOCATION, EMPTY FLOW BACK TANK. DAWN TO MOVE IN FLOW BACK TANK & HAUL BR TANK IN TO BE REPAIRED. SHUT DOWN FOR WEEK END. NOTE: SHIPPED 5,372' 2-1/16" 3.25# J-55 10rd IJ TBG & 1 DAMAGED JT 2-3/8" 4.7# J-55 8rd EUE TBG TO BR STOCK VIA TRIPLE S TRCKING.
7 (FAC)	11/25/2003 06: 00	07:00	1.00	OBJECT	MIMO a	N	ROAD CREW TO LOCATION,
7 (FAC)	11/25/2003 07:00	07:30	0.50	OBJECT	SAFE a	N	SAFETY MEETING W/ 4 RIG CREW, 1 AIR HAND COMPANY REP, TOPIC SLICK WORK FLOOR.
7 (FAC)	11/25/2003 07:30	08:00	0.50	ОВЈЕСТ	BLOW a	N	160# PSI CSG PRESSURE, BLEED WELL DOWN.
7 (FAC)	11/25/2003 08:00	09:00	1.00	ОВЈЕСТ	CIRC a	N	TIH TAG 30' FILL, P/U SWIVEL, BRK CIRC,
7 (FAC)	11/25/2003 09:00	10:00	1.00	OBJECT	COUT a	N	CLEAN TO PBTD, 850 CFM AIR 12 TO 14 BPH FLUID RATE, RETURNS FRAC SAND.
7 (FAC)	11/25/2003 10:00	12:00	2.00	OBJECT	FLOW a	Z	PULL ABOVE PERFS FLOW WELL NATURALLY.
7 (FAC)	11/25/2003 12:00	13:00	1 .00	OBJECT	COUT a	N	TIH TAG 5' FILL, C/O FILL,
7 (FAC)	11/25/2003 13:00	15:00	2.00	ОВЈЕСТ	TRIP a	N	LAY DOWN SWIVEL, TOOH W/ TBG BIT SUB & BIT, LAY BIT & SUB DOWN,
			1			$\overline{\cap}$	

7 (FAC)	11/25/2003 15:00	17:00	2.00	ОВЈЕСТ	TRIP a		TIH W/ EXP-CHECK, S,N, 1 JT 2-3/8 J-55 4.60 TBG, PUP JT, TAG 5' FILL, PULL ABOVE PERFS SWSD.
8 (FAC)	11/26/2003 06:00	07:00	1.00	OBJECT	BLOW a	N	160# PSI CSG PRESSURE, BLOW WELL DOWN
8 (FAC)	11/26/2003 07:00	07:30	0.50	OBJECT	SAFE a		4 RIG HANDS, AIR HAND & COMPANY REP, DISCUSS CAT WALK SAFETY,
8 (FAC)	11/26/2003 07:30	08:30	1.00	OBJECT	TRIP a		TIH TAG PBTD 5435', NO FILL BLOW WELL AROUND,
8 (FAC)	11/26/2003 08:30	09:30	1.00	OBJECT	NUND a		LAND TBG, 2-3/8 4.6 J-55 8RD 174 JTS, 2' PUP JT, 1 JT 2-3/8 S.N. EXP/ CHECK, 175 TOT JTS IN WELL BORE,
8 (FAC)	11/26/2003 09:30	11:00	1.50	OBJECT	NUND a		N/D BOP, N/U WELL HEAD,, TIH W/ T/T SLICKLINE, TAG PBTD @ 5435' TBG LANDED S.N. @ 5405'. WELL BLOW ING DRY GAS UP TBG,
8 (FAC)	11/26/2003 11:00	12:00	1.00	OBJECT	RURD a		R/D 485, RELEASE UNIT @ 1200 HRS, 11/26/2003 MOVE TO HOWELL J #4, MONDAY AFTER HOLLIDAYS, (TRANSFER 2 JTS 2-3/8 J-55 4.60 8-RD NEW TBG TO HOWELL J #4)

Global Intranet | Comments and Feedback | Legal Notice | Privacy Statement