

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires: July 31, 1996

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE- Other Instructions on the reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Devon Energy Production Company, L.P. Attn: Kenny Rhoades

3a. Address

1751 Hwy. 511 Navajo Dam, New Mexico 87419

3b. Phone No. (include area code)

(505) 632-0244

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

760' FNL & 1820' FWL NW 1/4, NE 1/4, Sec. 25, T 31N R. 8W

Latitude

Longitude

5. Lease Serial No.

SF-79082

6. If Indian, Allottee, or Tribe Name

7. If Unit or CA. Agreement Designation

Northeast Blanco Unit

8. Well Name and No.

NEBU 50A

9. API Well No.

30-045-31199

10. Field and Pool, or Exploratory Area

Blanco Mesaverde Basin Dakota

11. County or Parish, State

San Juan NM

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Altering Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and abandon

☐ Plug back

☐ Production (Start/ Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-off

☐ Well Integrity

☒ Other **Zonal isolation**

13. Describe Proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will be performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in anew interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Work commenced to ensure zonal isolation across Lewis formation.

On 1/30/2003 set RBP @ 6014' to isolate Dakota completion and shot 3 squeeze holes @ 4840' in the 4-1/2" production casing.

On 1/31/2003 pumped 103 BBLS (400 sx) 50/50 Poz w/ Tail of 10 bbls (50 sx) Class "B" w/ 75 cc fluid loss into squeeze holes @ 4840'

On 2/3/2003 pressure test of squeeze holes @ 4840' failed (Leaking @ 100 psi per minute)

On 2/8/2003 pumped 6 bbls 15% HCL, then pumped 10 bbls (50 sx) Class "B" cement into squeeze holes @ 4840'

On 2/9/2003 pressure tested squeeze holes and casing to RBP @ 6014' to 3500 psi- Good test

On 2/10/2003 ran GR-CCL-CBL log from 5512' to 2100'. TOC @ 2440'

RECEIVED
2003 MAR 10 AM 10:58
070 Farmington, NM

14. I hereby certify that the foregoing is true and correct.
Name (Printed/ Typed)

Kenny Rhoades

Title

Company Representative

Signature

Date

3-4-03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

MAR 13 2003

Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)