

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

2003 MAR 25 AM 11:14

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT--" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well  
☐ Oil Well  
☒ Gas Well  
☐ Other

2. Name of Operator

Roddy Production Company, Inc.

3. Address and Telephone No.

P. O. Box 2221, Farmington, New Mexico, 87499 (505)325-5750

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1270' FNL-2020' FEL, Section 19, T31N, R12W, NMPM

5. Lease Designation and Serial No.

SF078243

6. If Indian, Allottee or Tribe Name

NM

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Owen No. 2C

9. API Well No.

30-045-31398

10. Field and Pool, or Exploratory Area

Blanco Mesa Verde

11. County or Parish, State

San Juan, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☐ Recompletion  
☒ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other  
☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Pull out of hole with drill string. Bit in good condition. No sign of drilling into old hole. Run in hole with open end drill pipe to 5045'. Break circulation with full returns. Pump 10 bbl fresh water spacer followed by 100 sacks ( 132.0 cf ) of 50/50 Class B Poz with 2% gel, 6 pps phenoseal, 0.25 pps celloflake and 2% CaCl. Displace with 3.5 bbls fresh water and 62.1 bbls mud to spot plug from 5045' to 4616'. Water spacer from 4646' to 4370'. Good circulation throughout job. Plug on spot at 3:45 AM, 3.4.03. When attempted to pull pipe cement was already set. Pull to 190K. Pump down drill pipe. Pressure to 1700 psi. Back off drill pipe at 4515'. Wash over drill pipe to 4818'. Cement from 4700' to 4818'. Made two attempts to get outside cutter over fish. It hangs up on top tool joint each time. Backed off additional joint of drill pipe to recover wash pipe the first time. Top of fish now at 4545'. Received verbal approval from Jim Lovato with BLM to set whipstock on top of fish and drill around it on 3.8.03

14. I hereby certify the foregoing is true and correct

Signed Robert E. Fulk

Title Agent

Date March 18, 2003

(This space for Federal or State office use)

Approved by \_\_\_\_\_  
Conditions of approval, if any:

Title \_\_\_\_\_

Date \_\_\_\_\_

APR 02 2003

NMOCD

RECEIVED FOR RECORD  
APR 02 2003  
FARMINGTON OFFICE  
Gm