### A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211 COPY

March 31, 2004

**New Mexico Oil Conservation Division Aztec District** 

1000 Rio Brazos Road Aztec, NM 87410 Invoice 3268

2004

1 of 2

Rig #9

For the plug and abandonment of the **HSGU #300**, a Gallup well located and State NW, Section 4, T-30-N, R-16-W, San Juan County, NM. Review report for work details. This work done under NMOCD PA - 41-521-07-00028, Purchase Doc.: 04-199-000490.

### **Cost Summary:**

outilitiai y .						
Date	Item Description	Units	U	nit Cost	Ε	xtension
over Rig,	Travel and Supervision:			,		
3/24/04	Contractors Supervisor / Cementer	0.0	\$	250.00	\$	-
3/25/04	Contractors Supervisor / Cementer	1.0	\$	250.00	\$	250.00
3/26/04	Contractors Supervisor / Cementer	1.0	\$	250.00	\$	250.00
3/24/04	Crew travel, one way	1.0	\$	112.00	\$	112.00
3/25/04	Crew travel, round trip time	2.0	\$	112.00	\$	224.00
3/26/04	Crew travel, one way	1.0	\$	112.00	\$	112.00
3/24/04	Shallow Rig	1.00	\$	140.00	\$	140.00
3/25/04	Shallow Rig	9.00	\$	140.00	\$	1,260.00
3/26/04	Shallow Rig	9.75	\$	140.00	\$	1,365.00
enting Se	rvices: මුම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම්ම					
3/25/04	Cementing equipment on location	1.0	\$	450.00	\$	450.00
3/26/04	Cementing equipment on location	1.0	\$	450.00	\$	450.00
3/26/04	Cement, plug #1, plug #2, sxs	71	\$-	10.50	\$	745.50
3/30/04	Cement, set P&A marker, sxs	24	\$	10.50	\$	252.00
ers, Retai	ners & Casing Scrapers:					
3/25/04	Casing scraper, 5-1/2"	1.0	\$	250.00	\$	250.00
strings &	Miscellaneous Rentals:					
3/25/04	Workstring rental, 2-3/8, feet	1133	\$	0.12	\$	135.96
3/25/04	Companion flange rental, 5-1/2"	1.0	\$	50.00	\$	50.00
3/25/04	Waste fluid container, days used	2.0	\$	30.00	\$	60.00
	Date 3/24/04 3/25/04 3/26/04 3/25/04 3/26/04 3/25/04 3/26/04 3/25/04 3/26/04 3/26/04 3/26/04 3/26/04 3/26/04 3/26/04 3/26/04 3/26/04 3/25/04 3/25/04 3/25/04	Date Item Description  Nover Rig, Travel and Supervision:  3/24/04 Contractors Supervisor / Cementer  3/25/04 Contractors Supervisor / Cementer  3/26/04 Contractors Supervisor / Cementer  3/24/04 Crew travel, one way  3/25/04 Crew travel, round trip time  3/26/04 Crew travel, one way  3/25/04 Shallow Rig  3/25/04 Shallow Rig  3/26/04 Shallow Rig  2/26/04 Cementing equipment on location  3/26/04 Cementing equipment on location  3/26/04 Cement, plug #1, plug #2, sxs  3/30/04 Cement, set P&A marker, sxs  2/25/04 Casing Scrapers:  3/25/04 Casing scraper, 5-1/2"  2/25/04 Workstring rental, 2-3/8; feet  3/25/04 Companion flange rental, 5-1/2"	Date         Item Description         Units           cover Rig, Travel and Supervision:         3/24/04 Contractors Supervisor / Cementer         0.0           3/25/04 Contractors Supervisor / Cementer         1.0           3/26/04 Contractors Supervisor / Cementer         1.0           3/24/04 Crew travel, one way         1.0           3/25/04 Crew travel, round trip time         2.0           3/26/04 Crew travel, one way         1.0           3/25/04 Shallow Rig         9.00           3/25/04 Shallow Rig         9.00           3/26/04 Shallow Rig         9.75           enting Services:         3/25/04 Cementing equipment on location         1.0           3/26/04 Cement, plug #1, plug #2, sxs         71           3/30/04 Cement, set P&A marker, sxs         24           ers, Retainers & Casing Scrapers:         3/25/04 Casing scraper, 5-1/2"         1.0           estrings & Miscellaneous Rentals:         3/25/04 Workstring rental, 2-3/8; feet         1133           3/25/04 Companion flange rental, 5-1/2"         1.0	Date         Item Description         Units         U           cover Rig, Travel and Supervision:           3/24/04         Contractors Supervisor / Cementer         0.0         \$           3/25/04         Contractors Supervisor / Cementer         1.0         \$           3/26/04         Crew travel, one way         1.0         \$           3/25/04         Crew travel, round trip time         2.0         \$           3/26/04         Crew travel, one way         1.0         \$           3/24/04         Shallow Rig         1.00         \$           3/25/04         Shallow Rig         9.00         \$           3/26/04         Shallow Rig         9.75         \$           enting Services:         3/25/04         Cementing equipment on location         1.0         \$           3/26/04         Cementing equipment on location         1.0         \$           3/26/04         Cement, plug #1, plug #2, sxs         71         \$           3/30/04         Cement, set P&A marker, sxs         24         \$           ers, Retainers & Casing Scrapers:         3/25/04         Casing scraper, 5-1/2"         1.0         \$           strings & Miscellaneous Rentals:         3/25/04         Companion flange rental, 5-1/	Date   Item Description   Units   Unit Cost	Date         Item Description         Units         Unit Cost         Exposer Rig, Travel and Supervision:           3/24/04         Contractors Supervisor / Cementer         0.0         \$ 250.00         \$ 3/25/04           3/25/04         Contractors Supervisor / Cementer         1.0         \$ 250.00         \$ 3/26/04           3/26/04         Contractors Supervisor / Cementer         1.0         \$ 250.00         \$ 3/26/04           3/24/04         Crew travel, one way         1.0         \$ 112.00         \$ 3/25/04           3/26/04         Crew travel, one way         1.0         \$ 112.00         \$ 3/26/04           3/25/04         Shallow Rig         1.00         \$ 140.00         \$ 3/25/04           3/26/04         Shallow Rig         9.00         \$ 140.00         \$ 3/26/04           3/25/04         Cementing equipment on location         1.0         \$ 450.00         \$ 3/26/04           25/04         Cement, plug #1, plug #2, sxs         71         \$ 10.50         \$ 3/26/04           26/04         Cement, set P&A marker, sxs         24         \$ 10.50         \$ 250.00           26/04         Cement, set P&A marker, sxs         24         \$ 10.50         \$ 250.00           27/25/04         Casing scraper, 5-1/2"         1.0 <t< td=""></t<>

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

	March 31, 2004		2 of 2
New Mexico Oil Conservation Division  Aztec District			2012
1000 Rio Brazos Road	Invoice 3268	•	Rig #9

For the plug and abandonment of the **HSGU #300**, a Gallup well located in NW, Section 4, T-30-N, R-16-W, San Juan County, NM. Review report for work details. This work done under NMOCD PA - 41-521-07-00028, Purchase Doc.: 04-199-000490.

Trans	sportation	and Miscellaneous Services:					
F1.a	3/24/04	Unit #141, Haul A+ workstring/float #98 to loc.	1.50	\$	74.00	\$	111.00
F1.b	3/25/04	Unit #152, Haul steel pit to location and set	2.25	\$	74.00	\$	166.50
F1.c	3/31/04	Unit #152, Haul rods & tubing to Cave	1.5	\$	74.00	\$	111.00
F1.c	3/31/04	Unit #152, Clean up trash from location	5.5	\$	74.00	\$	407.00
F2.c	3/30/04	Helper for above	7.00	\$	20.00	\$	140.00
F4	3/26/04	Float with workstring, rental	2.0	\$	15.00	\$	30.00
F6.a	3/23/04	Unit #265, Haul 1 load of water to tank	4.5	\$	50.00	\$	225.00
F6.b	3/25/04	Unit #134, Haul 1 load of water to location	1.5	\$	50.00	\$	75.00
F6.c	3/26/04	Unit #13, Haul 1 load of water to location	1.5	\$	50.00	\$	75.00
F7.a	3/30/04	B-hoe, Clean up location and wellhead	1.5	\$	50.00	\$	75.00
F7.b	3/31/04	Unit #24, Clean up area wells	6.0	\$	50.00	\$	300.00
F11	3/26/04	P&A marker, purchase	1.0	\$	120.00	\$	120.00
F14	3/23/04	Purchase water,	1.0	\$	20.00	\$	20.00
Third	Party Ch	narges:					
G1	3/25/04	RW Trucking Co., Invoice #01647		\$	492.50		
		hot oil rods and tubing				,	
G2	3/27/04	C&J Trucking, Invoice # 200403154		\$	234.00		
		haul waste fluid to Basin Disposal		_			
G3	3/27/04	Basin Disposal, Inc., Inv # 88160	Ber J. St. St.	\$	60.00		
		disposal of waste fluid from steel pit;					
	•	· · · · · · · · · · · · · · · · · · ·	Total	\$	786.50	•	0.40-40
		Third Party Handling Charge	8%	\$	62.92	\$	849.42
Salva	age Credi				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
S1		Salvage, 2-7/8" EUE tubing, 43 joints	1333	\$	1.00	\$	(1,333.00)
		Salvage, 7/8" used sucker rods, 51 pieces	51	\$	5.50	\$	(280.50)
		n de karan da aran da a		TO:	TAL" :::	-\$-	7,197.88
	armen .	to Marin	TAX		.3750%	\$	458.86
THAN	K VOUE	CORDINAL SIGNED BY CHAPLIE T. PERREN			TAL DUE		7,656.74
ITAN	K YOU	The same of the sa		10	I AL DUE	Φ.	1,000.14

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells



		5.	Lease Number
1.	Type of Well	6.	SF-081226B If Indian, All. or
2	Oil Name of Operator	7.	Tribe Name Unit Agreement Name Horseshoe Gallup Unit
	Vulcan Minerals & Energy c/o NMOCD Aztec District Office		Tronsolito Gallap Gill
		8.	Well Name & Number
3.	Address & Phone No. of Operator 1000 Rio Brazos Road, Aztec, NM 87410 505-334-6178	9.	HGU #300 API Well No. 30-045-25724
Lo	cation of Well, Footage, Sec., T, R, M	10.	Field and Pool
•	1590' FNL and 1460' FWL, Section 4, T-30-N, R-16-W,	11.	Horseshoe Gallup Unit County & State San Juan County, NM
40	CHECK APPROPRIATE BOY TO INDICATE NATURE OF NOTIC	CE REPORT OTHER D	
12.	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE  Type of Submission  Type of Action	JE, REPORT, OTHER D	AIA
	Notice of Intent  X Abandonment Ch Recompletion Notice of Intent Recompletion Notice of Intent Plugging Back Notice of Intent Recompletion	nange of Plans ew Construction on-Routine Fracturing Vater Shut off	
		onversion to Injection	
13.	Describe Proposed or Completed Operations  A-Plus Well Service Plugged and Abandoned the above Contract Number: 41-521-07-00028.	well NMSA 1978, Sec	etion 13-1-127,
	MOL and spot rig. RU rig. Relief line to steel pit. Pick up to unseat pump. LD hot oil unit. Pump 65 bbls hot water down tubing and circula 52 -3/4" rods and pump. ND wellhead. NU BOP and test. SN. PU A+ workstring and TIH with 5-1/2" casing scraper to	ate out casing. RD hot o TOH and LD 42 joints 2	il unit. PUH and LD -7/8" NU tubing with
	1133'. Pressure test tubing to 500#. Sting out of CR. Circu test casing to 500#, held OK. Dig out bradenhead valve and Sting into retainer and pump fluid under CR. Plug #1 with casing from CR up to 840' to isolate Gallup interval. PUI cement inside casing from 222' to surface, circulate good ce ND BOP. Dig out and cut off wellhead. Found cement at cement to install P&A marker. RD and MOL.	ulate well clean with 30 b d pressure test BH annulous retainer at 1133', spot 3 H with tubing to 222'. Froment out casing valve. I surface in casing and a	bls water. Pressure us to 250#, held OK. 4 sxs cement inside Plug #2 with 37 sxs TOH and LD tubing.
	William F. Clark	·	
ÀΡ	ris space for Federal or State Office use) PROVED BY Title PNDITION OF APPROVAL, if any:		Date

A - PLUS WELL SERVICE P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

	Hans	ESHOE GALLUP UNIT # 300 Com	DINVA	Animori A	ENEDE
				TVIINE ICALS A	( K/VEKU )
FRO	м то	DESCRIPTION OF OPERATIO	<del></del>		
3:30			T EQUIPM	KNT	
1:3	O 5:30	TRAVEL TO YARD			
				,	
			2 .		
				· · · · · · · · · · · · · · · · · · ·	
					•
				···	
·					
-					
-					
				·	
-					
		Water Hauled			
		Cement Retainers			
	nting				
r					1
]	REW	NAME	UNIT#	MILEAGE	НО
ļ	pervisor	MIKE HIGDON #143 IN & FILL	<sup>#</sup> 21		
Ope	erator	JESUS JACOBO	MO7		2.0
Hel	per	SAUL JACOBO			2,0
Hei	nor:	LORENZO RODRIGUEZ			2.0
<b></b>			- <del>  </del>	<del></del>	- · ·

Trainee:

RCI Form - 0801114A

A - PLUS WELL SERVICE P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

•	Rig No_#p		Date <u>03</u>	25/04	Day	husday
:		SGU # 300	Company _			7
:	FROM TO	DESCRIPTION OF	OPERATION	· · · · · · · · · · · · · · · · · · ·		
1	5130 514	5 Lond supplies				
1 h	5:45 6:4					
/ M	6:45 7:19	5 Start equipment a hold	safety o	recting		
	7:15 8:3	RU right spot in equipor	nent			
	8130	RU lines to steel pit. Un	seat pump	10	2 000	ls.
	8!4!	RU RW truling hot oiler	Ing box	<del></del>		
	8:45	KU KW trudeing hot oiler	! tump	65 Hz	la ho	L water
1	1115		_pit			
CA LAN	11:15 12:0		2 roods, 8	pump	<b>)</b>	
9 M	11:00 1:07	NU BOP a function test	07/40	MO .	23/2"	1 / /
	1,00	RU floor. MU 23/8" BX	0 28 F	1000	298	banding
	1132	jt. MV landing it into tu Go to 27/8" equipme	ning nan	ges a u	nseat	same.
	1130 211		` ) // ' \ \( \alpha \) .	n =11	E a	I CAI
	215 213		4 2 2 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	u, au	L a	1 30,
	2130	MU S1/24 SCraper d	TH L	1133		
	3,3	Bear Toyl & bless	nudruli	hase		
	3:30 3:14		, morrando			· · · · · · · · · · · · · · · · · · ·
	3,45 414					
1.1		J		<u>.                                    </u>		1
1 Mi						
		,				
<b>.</b>						
	ļ					
				·		
	11					
			led 😥		A-Plus	
		t N/12 Cement Re	etainers <u>NA</u>	<del></del>		
· /	Cementing _N					
$()$ $\Box$	Wireline N/	<b>-</b>				
1 1	CHEW	NAME	UN	IIT# MIL	EAGE	HOURS
\/all/	Supervisor	Chris Clark	6	3 7	2	1
y	Operator	Jesus Jacobo				11.25
	Helper	Soul Jacobo			t	11.35
	Helper	•			- `	
		Lorenzo Rodriquez				11.35
	Helper	C-ik LAZANO				11,25
	Trainee			4	•	

A - PLUS WELL SERVICE P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

Rig No	9		Date 03/26/04 Day Friden	
Weil Name	e_HSb!	J # 300	Company	
FROM	то	DESCRIPTIO	ON OF OPERATION	
5:30	5:45	Load supplies		
5:45	6:45	Travel to location.		
6145	7100	Start equipment a hold	sodistry meeting	
7,00	71.15	Baraic hudgardie line en	n in	
7115	8,00	POOH W/ SCraper TINA WHY CR @ 1133	J	
8:00	51:45	TIME Set CR @ 1133'		
8:45		Test tubing to soopsi. Sting	unt a seculate well clean w/	3013136
	9130	a pressure test casing to	SOO psi.	
9130		Dig out bradenhead value	a pressure test bradenhead	d
	10:15	to ≈50 pi		
10:15		RU lines, when into CR a	pump HD a Oil from steel pit	below
	11145	CR. Sting out of CR	the second secon	
11:45		Plug#1 Mis 34 sxs t	up II cement w/ 4,2 BRb mix CR & 1835 up to 840. Displace	
	12145	water. Spot Plus above	CR e 153' up to 840. Displace	w/3/3/A
12,45	1:30	LD 29 joints to place		
1:30		Plug 2: Mix 37 sxs f	ype I cement of 4.5 BRIS mix	
ļ	2/2		ment out casing value.	
2/15		LD 1)ts. RD Hoor	a ND BOP Dry aut well her	ad
	3:45	a cut of same to	shall DHM w/ 24 srs	
3145		Note: CMF C surfa	cs in eg.	
7,47	-1.30	RU a MUL,		
		2 8		
Fuel & Mo	otor Oil	Wata	r Hauled 2 loads hauled to l	ocation
Rental Eq			ent Retainers 15% DHS @ 1135	OCOUPION
,	g Phia		DHM: 24 45 95 SKS	40th
Wireline _	·	· · · · · · · · · · · · · · · · · · ·		101.74
CREV		NAME ·	UNIT # MILEAGE H	OURS
Superv		(A) 251 Pl . 1713.		
Operate	<del></del>	T T I	68 78 7 78 1	<del>,  </del>
Helper		S. I T 1	1 78 1	<u> </u>
Helper		Aul Jacobo		!
Helper	-	Lorenzo Kodri quez		L
Trainee			<u> </u>	- 111 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -

RCI Form - 0801114A

RCI Form - 060158A

### A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date: <u>63/24/64</u>

Truck #: 141

•	17uck #: _1		•	
Event: #1	From: HSGU #256 To: HSGU # 300	Hours		••
Start: 3:00	What: LOAD FLOAT #98 AND HAVE TO LOCATION AND SPOT			
Stop: 3:30	Charge to: PLAYA MINERALS & ENERLY % NMOCD			• •
		.5		
Event: #2	From: HSGu #300 To: HSGu #256			
Start: 3:30	What: RUAD TO LOCATION AND LOAD STEEL PIT	_		
Stop: 4:00	Charge to: PLAYA MINERALS & ENERGY YO NMOCO	.5		
Event: #3	From: HSGU # 256 To: ASGU #300			
Start: 9:00	What: ROAD TO LOCATION AND SPOT STEEL PIT	<del> </del>		
1 50	THE TO ABOUTTON AND THE STEEL THE	<b>-</b>		
Stop: 4:30	Charge to: PLAYA MINERALS & ENERGY % NMOCD	.5		
Event: #4	From: To:	1		
Start:	What:			
Stop:	Charge to:			
Event: #5	From: To:	1		
Start:	What:			
·				2 <b>3</b> *
Stop:	Charge to:		•	
Event: #6	From: To:	,		
Start:	What:	<b></b>		
Stop:	Charge to:			
Event: #7	From: To:			
	What:			
Stop:	Charge to:			
Event: #8	From: To:			
Start:	What:			
				,
Stop:	Charge to:			
				7
	Driver: MIKE HIGOON Helper	1.5	/-//	$\alpha$
	NM MILES: 4.5 CO MILES: UT MILES:		1.	
	THE MILES. 17.0 SO MILES. ST MILES.			
Remarks:	#		•	
	HS6'V7# 300			
· · · · · · · · · · · · · · · · · · ·				

### A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date: 3-25-04 Truck #: \_/52 From: A PLUS WELL Event: #1 To: 4/560 300 Hours Start: 57.00 What: DRIVE TO LOCATION Stop: 🖊 ్లస Charge to: STAFF 2.25 Event: #2 From: 4/560 300 TO: A PLUS WELL 1.25 Start: 🔏 🖰 à 🖰 What: ORIVE BACK TOVINO STATE Charge to: To: KLEIN Event: #3 From: A PLUS WELL What: Start: 7 /5 ORIVE TO LOCATION Charge to: ENERGIN From: Kray 22 Event: #4 What: CLEAN & LEVICE LOUNTIED & BACK FILL PLT Start: Q: 45 DNLOAD & LOAD BACK HOS Stop: / 0/10 Charge to: ENERGIN Event: #5 From: KLEIN 35 To: ST 38.7 \* 15/ What: DRIVE TO LOCATION Start: / 0 : 63 Stop: //. 60 Charge to: CONOCO PHILLIPS 28-7 # 151 Event: #6 Start: What: CLEAN & LEVEL LOCATION + BACK FILL Stop: // co Charge to: CONOCO PHILLIPS From: ST 28-7 \* 15/ Event: #7 TO: ERIN STAILS COM What: ORIUS TO Start: / 75 CONOCO PHILLIPS Stop: ブバダゲ Charge to: Event: #8 From: ERIN STAYE COM \*/ TO: What: CLEAN & LEWIS LOGATION I BACK fue PIT HAD BLENDE MIX STILL HAD HED IN PIT Stop: Charge to: CONOCO PHILLIPS Driver: DUANE (TUSTIN) Diesel: /43 Helper Oil: NM MILES: CO MILES: UT MILES: Remarks: MMOUD Haul steel sit

trovel to A-Phis Hard

2.25hu

### A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date: <u>3310V</u> Truck #: 152 Event: #1 From: A PLUS WOLL To: Hours Start: デーテロ What: Do Proce Wram Up 152 Stop: 1 75 Charge to: Event: #2 From: 1 PLUS WOLL To: 4560 300 5 Shu What: DRIVE TO LOUTIUN Start: ビッング Stop: 8,00 Charge to: Event: #3 From: 4560 300 To: Start: 8 00 What: SORT THE PIPE FROM THE ROOS & GOAD CLEAN ELOND ALL THE TRASH-WILLHER TACKENINO Stop: // 200 Charge to: From: 2/560 300 Event: #4 To: 4560 256 Start: // '02 What: OPINE TO LOGITION Stop: /1.30 Charge to: From: 11540 856 To: Event: #5 What: Spat Pipe = Poss & Long - Long were Hosp & Start: // 3つ ALL THE JUNK OH GOLATION Stop: 3:30 Charge to: To: NSGU 230 From: 4560 200 156 Event: #6 What: ORIVE TO LOCATION 5 Start: 330 Stop: 🏒 🍪 Charge to: To: CAUF PIPE From: 2560 320 Event: #7 Start: 3 700 What: UNLONG ALL TOR JUNK Leno THE YOUKS 5 GRIVE TO CAVE Charge to: Stop: 4 30 کرہ ہے Event: #8 From: Cave Pinc TO: APRUS EVEL What: UNLONG PIRE & ROOS & ORIUS TO YARD 75 Start: 🍎 🏂 Stop: 5.30 Charge to: Driver: OUNDE GUSTIN Helper BRAD FORD MOSES Diesel: X NM MILES: 70 MWY CO MILES: Oil: UT MILES: Remarks: 18.7 for BALLHOE In location Lord pipe a 7hy clean up location. Hand Disper & route to come Swamper @ \$20.00/h. RCI Form - 08D158A

## A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date: _ 3 -	<u>23 -∂</u> / Truck #: _ <u></u>	265	
Event: #1	From: A - Phy To:	Hours	
Start: 5:30	What:		
Stop: (2.9)	Pre         Ck         265           Charge to:         N∴1.0 CQ	.5	
Event: #2	From: Famon hydrat, To: Horseshoe Gollup		
Start: & 💬	What: Kauli 1, 1004 Francy Faring Far	<del>                                     </del>	
	have 2 loads from ship rock	8	
Stop: 3"~0	Charge to: Will O.C. D.		
Event: #3	From: Honsogiae Callup To: A - plus		
Start: 💃 ပပ	What: Four Time is	<del>                                     </del>	
Stop: 3:00	Charge to: NM. OCD		
Event: #4	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #5	From: To:		
Start:	What:		
			•
Stop:	Charge to:		
Event: #6	From: To:	,	
Start:	What:		
Stop:	Characteristics	_	·
-	Charge to:		
Event: #7	From: To:		
Start:	What:		1
Stop:	Charge to:		/-/ A
			(1-6.
Event: #8 Start:	From: To: What:		
Otavi.		<del> </del>	
Stop:	Charge to:		
		00	9 his
Diagele	Helper 9 4	9.5	
Diesel: Oil:	NM MILES: 46 CO MILES: UT MILES:	·	41/2-
		<u> </u>	.// -
Remarks:	11mas C1) HC01#200		4/2
	MMOCD #56U#300		•
ļ		<u></u>	
<u> </u>	2 Loads Water to FANK	5 0 L 40 + 20	41/2-
	or comes with 10 / HAMIC		
	Parchase & loads	NA 199 - 1	15-14
<u> </u>		8CI Form - 080158A	

**A-Plus Well Service, Inc.**P.O. Box 1979, Farmington, NM 87499
505-325-2627

Date: 03/25/04 Truck #: 134

:		
Event: #1	From: HSGU # 300 To: A PLUS TANK #302	Hours
Start: 8:40	What: ROAD TO TANK & LOAD / FRESH WATER	
<u> </u>		<u> </u>
Stop: <b>9</b> :00	Charge to: PLAYA MINERALS & ENERLY YO NMOCD	1.0
Event: #2	From: A. PLUS TANK #302 To: HSGy #300	
Start: 9/00	What: ROAD TO LOCATION	
Stop: 9:30	Charge to: PLAYA MINERALS & ENERLY % NMOCD	.5
	I_	T
Event: #3	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #4	From: To:	
Start:	What:	
Stop:	Charge to:	
		· · · · · · · · · · · · · · · · · · ·
Event: #5	From: To:	
Start:	What:	
Stop:	Charge to:	1
Event: #6	From: To:	,
Start:	What:	
Stop:	Charge to:	
Event: #7	From: To:	
Start:	What:	-
<u></u>		
Stop:	Charge to:	<u> </u>
Event: #8	From: To:	
Start:	What:	
<u> </u>		
Stop:	Charge to:	
	Driver: Lolenzo Rodliguez	1.5
Diesel:	Helper	
Oil:	NM MILES: 12.0 CO MILES: UT MILES:	
		- <del> </del>
Remarks:	1	
	HS6U#300	
	1)2000	
		<del> </del>
<del></del>		
		1:
]	!	1

RCI Form - 080158A

**A-Plus Well Service, Inc.**P.O. Box 1979, Farmington, NM 87499
505-325-2627

Date: <u>63/26/64</u>		Truck #: <u>134</u>

From: 115/11 \$ 200 To: A 01111 To: A 01111	Hours
What: POAN TO TANK & LOAN / EDECH WATER	Hours
NORO TO THINK DE -ONOT PRESIDENCE	
Charge to: PLAYA MINERALS & ENERGY % MMOCO	1.0
From: A-PLUS TANK #302 To: 4564 #300	
Charge to: PLAYA MINERALS BENERLY YOU WHUCH	.5
From: To:	
What:	1
Charge to:	
From: To:	T
	+
	<del></del>
Charge to:	<del>                                     </del>
What:	-
Charge to:	
T	T
viriat.	<del> </del>
Charge to:	1
	<del></del>
	<b></b>
what:	-
Charge to:	<del> </del>
	1
	-
vvnat.	<del> </del>
Charge to:	1.
	<u>.l</u>
Driver L. D.	
	1.5
THR WILLS. 12.7 CO WILLS. OT WILES.	<u> </u>
1	
H(6U * 500	
	From: A-PLUS TANK #302 TO: HSGU #300  What: ROAD TO LOCATION  Charge to: PLAYA MINERALS RENERLY 46 MMUCE)  From: To:  What:  Charge to:  From: Lore What:  Charge to:  From: To:  What:  Charge to:  From: To:  What:  Charge to:  From: To:  What:  Charge to:  Driver: Lore Renzo Robrichez Helper  NM MILES: 12.0 CO MILES: UT MILES:

A-Plus Well Service, Inc.
P.O. Box 1979, Farmington, NM 87499
505-325-2627

3 30 04 Date:

Truck #: 152

Date: <u>3 3 </u>	<u> </u>	<u> نہ ن</u>	
Event: #1	From: A Pros Wear To:	Hours	
Start: 5°, 30	What: Oo PARIA		
~		,5	
Stop: 🌠 ರಂ	Charge to:	<u> </u>	
Event: #2	From: A PLUS WALL TO: 4560 233		•
Start: <u>ゟ゚</u> ゚ゟ゚゙゙゙゚	What: LOND BACK HOS & CHAID COME LOND FRONT	1	
Cton, 7:04	Charma to:		
Stop: 7.04	Charge to: ≤7,47°€		
Event: #3	From: A PLUS WOLL TO: 12560 333		
Start: 7, 00	What: ORIUS To LOCATION	1.75	
Stop: <i>8.'4'5</i>	Charge to: NMeCD		
		T	-
Event: #4	From: \(\(\mu(G)\) \(\frac{33}{33}\) To:	1.5	
JIAIL B, 43	What: Con OUT ANCHORS 4 were WERE NEXT TO WELL	1// 3	
Stop: 10:15	HEAD REMOVE A LANGE PIKE 84 DIRT THOM AROSNO Charge to: WELL HEAD STATE		
<del></del>	A CONTRACTOR OF THE CONTRACTOR		
Event: #5	What: DRIVE TO = CLEAN LOCATION WAD TO DEAL	1.5	*
J. C. 10, 15	WITH PUMP PAR "PAR DELLY"	1/.3	Λ
Stop: //, /ら	Charge to: Nmech		1
		1	
Event: #6	From: 12560 300 To: 14560 50	1	
Start: //:45	What: OPINE TO + CLEAN LOCATION - PUR DOWN AROUND WELL HEAD 7' x 12 TO TIND BLACK SANDE CALLED	3.3	
Stop: 3//5	Charge to:	3072	
F 47			
Event: #7 Start: 3//ビ	What: pond BACK HEE & DRIVE TO YARD	1.25	
01411.3773	The police week to the 10 yacco	1, 23	
Stop: 5.00	Charge to: AimacD		
Event: #8	From: To:		$/\sim$
Start:	What:		1///
			P
Stop:	Charge to:		
**************************************			
<del></del>	Driver: DUNNE GUSTIN	11.25	
Diesel:	Helper Band-tono Mostos	11.25	
Oil:	NM MILES: UT MILES:		
· · · · · · · · · · · · · · · · · · ·			
	30 TETAL		
	30 TOTAL 70 HWY - 32 OMT		
	70 HWY - 32 OM7		
Remarks:			
	NMOCD 4500 # 300		1,5hm
	70 HWY - 32 OM7		1,5hm

A-Plus Well Service, Inc. P.O. Box 1979, Farmington, NM 87499

Date: <u>3</u>	2104	505-325-2627		#24
ت ک Date: _ک	7-03	en de la companya de	Truck #:	7 2 4
Event: #1	From: 14560	1 # 300 To:		Hours
Start:	What:		-14/11/a	
<del> </del>	(lean	Up Hrea	weeks	6
Stop:	Charge to:			
Event: #2	From:	To:		·
Start:	What:			
Stop:	Charge to:			
Event: #3	From:	To:		
Start:	What:			
			`	
Stop:	Charge to:		· · · · · · · · · · · · · · · · · · ·	
Event: #4	From:	To:		
Start:	What:			
		·		
Stop:	Charge to:			
Event: #5	From:	To:		
Start:	What:			
Stop:	Charge to:			
Event: #6	From:	To:		
Start:	What:			
Stop:	Charge to:		·	
Event: #7	From:	To:		
Start:	What:			
Stop:	Charge to:			
Event: #8	From:	To:		
Start:	What:			
Cton	Characte			
Stop:	Charge to:			
	Driver			
Diesel:	Driver: Helper	•		
Oil:	NM MILES:	CO MILES:	UT MILES:	
				<del></del>
Remarks:	Almas ON		HOMES	
*	11/11/0 (1)	:	17500 30	00
		·		
·	<u> </u>			

RCI Farm - 060158A



A PLUS WELL SERVICE P.O. BOX 1979 FARMINGTON, NM 87499

DATE	03-31-04	
ORDER NO		

P. O. Box 1208 Cortez, Colorado 81321

Telephone (970) 565-4882

ATTACHED TICKET NO.

WELL NO.

HGU #300

LEASE 01647 INVOICE NO. JOB NO. DESCRIPTION DATE HOURS **RATE AMOUNT** 03-25-04 SEE ATTACHED TICKET # 1344 492.50



1344

Telephone (970) 565-4882

P. O. Box 1208 Cortez, Colorado 81321

Company	At U	Jeli	<u> </u>	بعيان	<i>P</i>				Order N		204	parentamen a see an estate and a	T	
Address	WELL NO.	TUB	CSG.	FLOW	TEST TUB	TREAT	121711 419 (10)114		PRI	2-25 ESSURE FINISH	BBL.	***************************************	RATE	AMOUN
	300			LINE	108	IZIAK	START 0	DO SINISH	START	VAC	65	6	70	¥4,20
							!							
						**								<i>y</i> .
Start Time	6:30 Am			Propane Gallons Used 50 @ 145						725				
Stop Time	· laiso Pm							,	***	: 	т(		Charges HARGES	Lan
OPERATOR  JLE Say Lles  HELPER	Ren	narks		Flu	54	ivel	U 4	or p	lug +	Abajid	-			
										12	0 +	- Separate	incl	uld.
TRUCK NO.	Orc	lered	Ву	miles					Signed _		A COLOR	1	da	a good of
											6			1
	<b>A</b>	å	, 3					a		(		1.		

Showle your Co

invoice

No.

200403154

# C. & J. Trucking Co.

P. O. Box 1246

Farmington, New Mexico 87499

PHONE: (505) 325-7770 1-600-870-0080 In New Mexico

Invoice Date:

03/29/2004

Bill to Location:

HORSESHOE GALLUP#300

A PLUS WELL SERVICE

PO BOX 1979

**FARMINGTON** 

03/27/2004 149020

NM

87499

Job\_Number:

Total

BBLS

er: O

)

Total Total Hours Costs

Ticket Dates Ticket Number

Description

EMFTY RIG PIT

No. 192

Truck

40

4.5

\$234.00

Due to an increase in fuel, we are forced to charge a 10% surcharge. You will see this charge in the Fuel Totals description.

Interest will be charged at the rate of 1.5% per month (18% annual) on accounts not paid within 30 days. In the event the account is placed for collection, purchaser agrees to pay collection or attorney's fees.

40 4.5 \$234.00

MCL Total:

\$0.00

Disposal Total:

\$0.00

Waterload Total:

\$0.00

Other Totals:

\$0.00

Swramper Charge:

\$0.00

Fuel Totals:

Subtotal

\$234.00

NM Gross Receipts Tax:

\$14282

Invoice Total:

\$246.92

Jab\_Number:

0

•

PLEASE PAY FROM THIS INVOICE

Thank You !

Your Satisfaction Is Our Concern

san juan reproduction 30-4

## C. & J. TRUCKING CO.

Road Trucks • Rig Up Trucks • Water Hauling • Kill Truck • Frac Tanks • Heavy Haul Trucks
PHONE (505) 325-7770

149020

PHONE (505) 325-7770 FAX (505) 325-1847

1 (800) 523-6351• 24 HOUR SERVICE OFFICE and TRUCK YARD: 2100 TROY KING ROAD

P.O. Box 1246 • FARMINGTON, NEW MEXICO 87499 ORDERED BY: Salst Energy LOCATION HOS LOAD BBLS. **PUMP** DRIVING OTHER-RECEIVED BY/ HAULED TIME TIME TIME NO. **CUSTOMER COMMENTS** STARTING TIME STOP A.M. TIME STOP STARTING A.M. ΑМ P.M. TIME P.M. TIME STARTING A.M. STOP A.M. TIME P.M. TIME P.M. STOP STARTING A.M. A.M. P.M. TIME P.M. TIME STARTING A.M. STOP A.M. TIME TIME P.M. STOP STARTING A.M. A.M. TIME P.M. TIME P.M. STARTING STOP A.M. A.M. TIME P.M. TIME P.M. STOP STARTING A.M. A.M. TIME P.M. TIME P.M. STOP STARTING A.M. A.M. TIME TIME P.M. STARTING A.M. STOP A.M. TIME TIME P.M. TOTAL HOURS TICKET TOTAL \$ LOW GAUGE HIGH GAUGE


622

INVOICE # 88160

A-PLUS WELL SERVICE P O BOX 1979 FARMINGTON, NM 87499-1979

# BASIN DISPOSAL, INC.

"SPECIALIZING IN KCL AND DISPOSAL OF PRODUCED WATER"
P.O. BOX 100 • AZTEC, NEW MEXICO 87410 • PHONE(505) 334-3013




LOCATION:

HORSESHOE GALLUP #300

DATE:	TICKET NUM	BER	LOADS	RATE	AMOUNT
3/27/04	10563	C & J TRUCKING	1.00	60.00	60.00
			SUB TOTAL		\$60.00
			TOTAL AMOUNT I	DUE	5

THANK YOU

63.1



# BASIN DISPOSAL, INC.

88160

P.O. BOX 100 • AZTEC, NEW MEXICO 87410 • PHONE (505) 632-8936 LOCATED 3 MILES NORTH OF BLOOMFIELD ON WEST SIDE OF NM HWY 550

NO. 205630

DATE .	3-	27-06	CL	JSTOME	R 击	Literan	A-Plus
WELL	NAME & NUMBER_	Horse	Shoe (	act	lup	#300	
		J.	· · · · · · · · · · · · · · · · · · ·		•	•	UNIT NO
, DRIVE	R Bar	ines	<del></del>	···			111000
ORDE	RED BY	·				*****	DEL. TICKET NO. 149020
NO.	WATER	MUD	TIME	AM	PM		DRIVER'S SIGNATURE
41	40		1:00		X	Pay	- Boy
2							
3							
4							
- 5							
6		,					
**************************************	<u> </u>					/_LOADS	e = 60°
				•		LOADS	<del>-</del>
							TOTAL =
ATTEN	IDANT'S SIGNA	TURE	lip Sh	<u>ئ</u>			san juan reproduction form 168-

(632)

## A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211



April 21, 2004

**CAVE Enterprises** 

PO Box 79 Flora Vista, NM 87415

Invoice #3292

Rig #9

For used rods and tubing from **Horseshoe Gallup Unit** wells, located in Section 29, T31N, R16W, San Juan County, NM.

This material was credited to NMOCD on Invoice #3266 and #3268, March 2004.

### **Cost Summary:**

HSGU Well Numb	per Type and Size	 Value	Salvage
#256 145		\$ 1.00	\$ 1,457.00
54		\$ 5.00	\$ 270.00
#300 133	3 feet of 2-7/8" tubing, 43 joints	\$ 1.00	\$ 1,333.00
51	7/8" used sucker rods, plain	\$ 5.50	\$ 280.50
			\$ 3,340.50

NM TAX Exempt - Resale

14W 1700 Exempt - Nesal

THANK YOU



TOTAL DUE \$ 3,340.50