Office •	State of New			Form C-103
District I	Energy, Minerals and	Natural Resources	WELL API NO.	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVAT	TON DIVISION	30-045-32242	
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St.		5. Indicate Type of STATE	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, N		6. State Oil & Ga	
District IV 1220 S. St. Francis Dr., Santa Fe, NM	• • • • • • • • • • • • • • • • • • •		E-4426	244301101
	CES AND REPORTS ON WA		7. Lease Name or	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSED DIFFERENT RESERVOIR. USE "APPLICATION OF THE PROPOSED PROPOSED IN THE PROPOSED PROPOS	SALS TO DRILL OR TO DEEPEN C CATION FOR PERMIT" (FORM C-1	OR YLUG BÁCK FO A 101) FORSUCH / A	State Com	
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well ☐ Gas Well ☒	Other S	JUN 2004	2A	
2. Name of Operator		313.13	9. OGRID Numb	er
Dugan Production Corp.		DIST. 3	006515	
3. Address of Operator	7400 0400		Pool name or Blanco Mesaverdo	
P. O. Box 420, Farmington, NM 8' 4. Well Location	7499-0420	2020	Bianco Mesaverdo	7
4. Wen Location				
Unit Letter F: 18	feet from the <u>North</u>	line and1850f	eet from the Wes	t_line
Section 16	Township 32N		MPM San Juan	County
	11. Elevation (Show whether	er DR, RKB, RT, GR, etc.) 6305' GL		
Pit or Below-grade Tank Application (For	~		<u>l)</u>	
Pit Location: ULSectTwp	Rng Pit type	Depth to Groundwater	Distance from ne	arest fresh water well
Distance from nearest surface water	Below-grade Tank Location	ULSectTwp	Rng ;	
feet from theline and	feet from theline	è		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐				
NOTICE OF IN	TÊNTION TO:	SUB	SEQUENT RE	PORT OF:
NOTICE OF IN	TÊNTION TO:	SUB REMEDIAL WOR	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND
NOTICE OF IN PERFORM REMEDIAL WORK	TENTION TO: PLUG AND ABANDON	SUB REMEDIAL WOR COMMENCE DRI	SEQUENT RE	PORT OF: ALTERING CASING
NOTICE OF IN PERFORM REMEDIAL WORK	TÊNTION TO: PLUG AND ABANDON CHANGE PLANS	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB	SEQUENT RE	PORT OF: ALTERING CASING PLUG AND
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Clearly star	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: te all pertinent details, and	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: te all pertinent details, and	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be char	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cleted operations. (Clearly statork). SEE RULE 1103. For Managed as follows:	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB OTHER: te all pertinent details, and fultiple Completions: At	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be char 9-5/8" 36# surface casing set at	PLUG AND ABANDON PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clearly state) Ork). SEE RULE 1103. For Managed as follows: 200' in 13-3/8" hole cemented	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB OTHER: te all pertinent details, and fultiple Completions: At	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be char	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cleted operations. (Clearly statork). SEE RULE 1103. For Managed as follows: 200' in 13-3/8" hole cemented tapproximately 2100' (Lewis	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB OTHER: te all pertinent details, and fultiple Completions: At to surface Shale) in 8-3/4" mud dril	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be chan 9-5/8" 36# surface casing set at 7" 23# intermediate casing set a 4½" 10.5# production liner set a	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cleted operations. (Clearly statork). SEE RULE 1103. For Managed as follows: 200' in 13-3/8" hole cemented that approximately 2100' (Lewis at 1900-4500' in 6-1/4" air drill	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB OTHER: te all pertinent details, and fultiple Completions: At to surface Shale) in 8-3/4" mud dril	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be char 9-5/8" 36# surface casing set at 7" 23# intermediate casing set a	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cleted operations. (Clearly statork). SEE RULE 1103. For Managed as follows: 200' in 13-3/8" hole cemented at approximately 2100' (Lewis at 1900-4500' in 6-1/4" air drill in unchanged.	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AND CEMENT JOB OTHER: te all pertinent details, and Multiple Completions: At the surface Shale) in 8-3/4" mud dril lied hole, cemented to line	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date am of proposed completion to surface
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be char 9-5/8" 36# surface casing set at 7" 23# intermediate casing set a 4½" 10.5# production liner set a All other portions of APD remain	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cleted operations. (Clearly statork). SEE RULE 1103. For Managed as follows: 200' in 13-3/8" hole cemented to approximately 2100' (Lewis at 1900-4500' in 6-1/4" air drill in unchanged. above is true and complete to	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AND CEMENT JOB OTHER: te all pertinent details, and fultiple Completions: At the surface Shale) in 8-3/4" mud dril alled hole, cemented to line the best of my knowledge.	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date am of proposed completion to surface
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be char 9-5/8" 36# surface casing set at 7" 23# intermediate casing set at 4½" 10.5# production liner set a All other portions of APD remains.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cleted operations. (Clearly statork). SEE RULE 1103. For Managed as follows: 200' in 13-3/8" hole cemented to approximately 2100' (Lewis at 1900-4500' in 6-1/4" air drill in unchanged. above is true and complete to	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AND CEMENT JOB OTHER: te all pertinent details, and fultiple Completions: At the surface Shale) in 8-3/4" mud dril alled hole, cemented to line the best of my knowledge.	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT as, including estimated date am of proposed completion to surface
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be char 9-5/8" 36# surface casing set at 7" 23# intermediate casing set at 4½" 10.5# production liner set at All other portions of APD remain I hereby certify that the information grade tank has been/will be constructed or	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clearly state ork). SEE RULE 1103. For North anged as follows: 200' in 13-3/8" hole cemented that approximately 2100' (Lewis at 1900-4500' in 6-1/4" air drill in unchanged. above is true and complete to closed according to NMOCD guide	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AND CEMENT JOB OTHER: te all pertinent details, and Multiple Completions: At the surface Shale) in 8-3/4" mud dril alled hole, cemented to line the best of my knowledgelines , a general permit	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion to surface Er certify that any pit or belowative OCD-approved plan to 10, 2004
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed wo or recompletion. Request casing program be char 9-5/8" 36# surface casing set at 7" 23# intermediate casing set at 4½" 10.5# production liner set at All other portions of APD remain I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Detected operations. (Clearly state ork). SEE RULE 1103. For North anged as follows: 200' in 13-3/8" hole cemented that approximately 2100' (Lewis at 1900-4500' in 6-1/4" air drill in unchanged. above is true and complete to closed according to NMOCD guide	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB OTHER: te all pertinent details, and fultiple Completions: At to surface Shale) in 8-3/4" mud dril led hole, cemented to line the best of my knowledge elines , a general permit LE Vice-President	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion to surface Er certify that any pit or belowative OCD-approved plan to 10, 2004
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comp of starting any proposed we or recompletion. Request casing program be chan 9-5/8" 36# surface casing set at 7" 23# intermediate casing set at 4½" 10.5# production liner set at All other portions of APD remain I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name John Alexand	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION Cleted operations. (Clearly statork). SEE RULE 1103. For Managed as follows: 200' in 13-3/8" hole cemented that approximately 2100' (Lewis at 1900-4500' in 6-1/4" air drillin unchanged. Above is true and complete to closed according to NMOCD guide Closed according to NMOCD guide E-mail address: john	SUB REMEDIAL WOR COMMENCE DRI CASING TEST AT CEMENT JOB OTHER: te all pertinent details, and fultiple Completions: At to surface Shale) in 8-3/4" mud dril led hole, cemented to line the best of my knowledge elines , a general permit LE Vice-President	SEQUENT RE K	PORT OF: ALTERING CASING PLUG AND ABANDONMENT Es, including estimated date am of proposed completion to surface Er certify that any pit or belowative OCD-approved plan to 10, 2004