Submit 3 Copies To Appropriate District	State o	f New Mexico		/	For	rm C-103
Office # District I		s and Natural Re	sources /	/		arch 4, 2004
1625 N. French Dr., Hobbs, NM 88240	~		[A	WELL API NO.		
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSER	VATION DIVI	SION /		30-045-3215	
District III		th St. Francis D	/ / /	i. Indicate Type of STATE [\neg
1000 Rio Brazos Rd., Aztec, NM 87410 District IV		Fe, NM 87505	/ _	5 State Oil & Ga		
1220 S. St. Francis Dr., Santa Fe, NM		,		E-5382	is Lease 140.	
87505	ES AND DEDODTS	M WELL C			Trait A amagne	mt Names
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	CES AND REPORTS (ALS TO DRILL OR TO DE ATION FOR PERMIT" (FO	EPEN ØR PLUG BACI	к то а	. Lease Name or FC State Com	r Unit Agreeme	ent Name
PROPOSALS.) 1. Type of Well:		JUN ?		. Well Number		
Oil Well Gas Well X	Other	En of the	004 `A		20A	
2. Name of Operator		(a)		. OGRID Numb	or	
ConocoPhillip	s Co.	F		. OOKID Numb	217817	
3. Address of Operator P.O. Box 2	197 WI 3-6054	4.3.	S 7 1	0. Pool name or	Wildcat	
Houston, T	197, WL3-6054 x. 77252	THE PARTY		Basin Fruitland (Coal	
4. Well Location		A COLLUM	Line and the second			
Unit Letter_D : 10	090 feet from the	North 1	ine and 1165	feet from	n the West	line
Omt Letter_B . 1	oso lect nom the	1	me and 1105	leet iioi	ii the west	inte
Section 2	Township 30	N Range 8	W 1	IMPM	County San Ju	uan
A CONTRACTOR OF THE PARTY OF TH	11. Elevation (Show w	vhether DR, RKB, I	RT, GR, etc.)	(# 1	and the same	
Pit or Below-grade Tank Application (For p	6342 GL	suras a form C-144 m	ust be attached)	1		
Pit Location: UL Sect Twp				Distance from no	arast frash water	wall
Distance from nearest surface water			·		arest fresh water	weii
			ct1wp	Kng;		
fact from the line and		lima				
feet from theline and	feet from the	line				
12. Check Ap	opropriate Box to In		•	-		
12. Check Ap NOTICE OF INT	opropriate Box to In	ndicate Nature o	SUBSE	QUENT REF	PORT OF:	T
12. Check Ap	opropriate Box to In	ndicate Nature o	•	QUENT REF		SING □
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ☐	opropriate Box to In	ndicate Nature o	SUBSE EDIAL WORK	EQUENT REF □ NG OPNS.□	PORT OF: ALTERING CA PLUG AND	
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐	opropriate Box to In ENTION TO: PLUG AND ABANDOR	ndicate Nature o	SUBSE EDIAL WORK	EQUENT REF □ NG OPNS.□	PORT OF: ALTERING CA	
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	opropriate Box to In ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	ndicate Nature o	SUBSEEDIAL WORK MENCE DRILLING TEST AND ENT JOB	EQUENT REF □ NG OPNS.□ □	PORT OF: ALTERING CA PLUG AND	□ NT
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	opropriate Box to In ENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	ndicate Nature of REME COMM CASING CEME	SUBSEEDIAL WORK MENCE DRILLING TEST AND ENT JOB	EQUENT REF	PORT OF: ALTERING CA PLUG AND ABANDONMEI	NT 🖂
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	opropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clear)	ndicate Nature of REME COMM CASIN CEME OTHE	SUBSEEDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production States and git	NG OPNS. Start Up ve pertinent date:	PORT OF: ALTERING CA PLUG AND ABANDONMEI	NT X
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work	opropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clear)	ndicate Nature of REME COMM CASIN CEME OTHE	SUBSEEDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production States and git	NG OPNS. Start Up ve pertinent date:	PORT OF: ALTERING CA PLUG AND ABANDONMEI	NT X
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI	opropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clear)	ndicate Nature of REME COMM CASIN CEME OTHE	SUBSEEDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production States and git	NG OPNS. Start Up ve pertinent date:	PORT OF: ALTERING CA PLUG AND ABANDONMEI	NT X
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI Tubing Pressure 0 PSI	opropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clear)	ndicate Nature of REME COMM CASIN CEME OTHE	SUBSEEDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production States and git	NG OPNS. Start Up ve pertinent date:	PORT OF: ALTERING CA PLUG AND ABANDONMEI	NT X
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI Tubing Pressure 0 PSI Meter No. 6633088	opropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearly). SEE RULE 1103.	ndicate Nature of REME COMM CASIN CEME OTHE	SUBSEEDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production States and git	NG OPNS. Start Up ve pertinent date:	PORT OF: ALTERING CA PLUG AND ABANDONMEI	NT X
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI Tubing Pressure 0 PSI Meter No. 6633088 Transporter Williams Field Service	opropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearles). SEE RULE 1103.	ndicate Nature of REME COMM CASIN CEME OTHE y state all pertinen For Multiple Comp	SUBSE EDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production State details, and gibletions: Attack	EQUENT REF	PORT OF: ALTERING CA PLUG AND ABANDONMEI s, including est m of proposed	NT X imated date completion
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK ☐ TEMPORARILY ABANDON ☐ PULL OR ALTER CASING ☐ OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI Tubing Pressure 0 PSI Meter No. 6633088	ppropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearles). SEE RULE 1103.	ndicate Nature of REME COMM CASIN CEME OTHE State all pertinen For Multiple Comp	SUBSE EDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production St details, and gibletions: Attack	EQUENT REF	PORT OF: ALTERING CA PLUG AND ABANDONMEI s, including est m of proposed	NT X
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI Tubing Pressure 0 PSI Meter No. 6633088 Transporter Williams Field Service. I hereby certify that the information about the service of the servi	ppropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearles). SEE RULE 1103.	ndicate Nature of REME COMM CASIN CEME OTHE State all pertinen For Multiple Comp	SUBSE EDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production St details, and gibletions: Attack	EQUENT REF	PORT OF: ALTERING CA PLUG AND ABANDONMEI s, including est m of proposed r certify that any p tive OCD-approve	NT X
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI Tubing Pressure 0 PSI Meter No. 6633088 Transporter Williams Field Service. I hereby certify that the information at grade tank has been/will be constructed or cleaning the same property of th	ppropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearle). SEE RULE 1103. es pove is true and completioned according to NMOCD	REME COMM CASIN CEME OTHE Sy state all pertinen For Multiple Comp	SUBSE EDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production St details, and gibletions: Attack	EQUENT REF	PORT OF: ALTERING CA PLUG AND ABANDONMEI s, including est m of proposed r certify that any particle OCD-approve DATE 06/1	imated date completion
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI Tubing Pressure 0 PSI Meter No. 6633088 Transporter Williams Field Service. I hereby certify that the information at grade tank has been/will be constructed or cleaning pressure.	ppropriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearle). SEE RULE 1103. es pove is true and completioned according to NMOCD	REME COMM CASIN CEME OTHE State all pertinent For Multiple Comp	SUBSE EDIAL WORK MENCE DRILLING TEST AND ENT JOB ER: Production St details, and gibletions: Attack	EQUENT REF	PORT OF: ALTERING CA PLUG AND ABANDONMEI s, including est m of proposed r certify that any parties OCD-approve DATE 06/1	imated date completion pit or belowed plan
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or comple of starting any proposed work or recompletion. Date of First Sales 5/26/2004 Casing Pressure 87 PSI Tubing Pressure 0 PSI Meter No. 6633088 Transporter Williams Field Service I hereby certify that the information at grade tank has been/will be constructed or clessing the same of the same o	propriate Box to In ENTION TO: PLUG AND ABANDOR CHANGE PLANS MULTIPLE COMPLETION ted operations. (Clearle). SEE RULE 1103. es pove is true and completioned according to NMOCD the control of the con	REME COMM CASIN CEME OTHE State all pertinent For Multiple Comp	SUBSECTION SUBSECTION OF TEST AND ENT JOB ER: Production St details, and goletions: Attack The production of the details of	EQUENT REF	PORT OF: ALTERING CA PLUG AND ABANDONMEI s, including est m of proposed r certify that any particle OCD-approve DATE 06/1	imated date completion pit or belowed plan