Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II	OIL CONSERVATION DIVISION	30-045-09669
1301 W. Grand Ave., Artesia, NM 88210		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE 🗵
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOTICE	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
1	LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Harvey
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-104) FOR SUCH		
PROPOSALS.)		8. Well Number
1. Type of Well: Oil Well ☐ Gas Well ☑ Other		1
2. Name of Operator		9. OGRID Number
Burlington Resources Oil & Gas Company LP		14538
3. Address of Operator	E 400 N	10. Pool name or Wildcat
PO Box 4289, Farmington, NM 87499	9 E ONE ON W	Aztec Pictured Cliffs
4. Well Location		I
Unit Letter L : 1718 feet from the South South 923 feet from the West line		
Section 9	Township 3601/1016 Rouge 11W	NMPM San Juan County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
The same (Show mother District Only only)		
Pit or Below-grade Tank Application or Closure		
Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil	Below-Grade Tank: Volumebbls; Co	onstruction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON 🛛 🤇	CHANGE PLANS 🔲 COMMENCE DRI	ILLING OPNS. P AND A
PULL OR ALTER CASING 1	MULTIPLE COMPL CASING/CEMEN	T JOB 🔲
·		_
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
of recompletion.		
It is intended to temporarily abandon the PC formation according to the following:		
1. MIRU completion rig.		
2. Pull tubing. Set cast iron bridge plug at 1,956'.		
3. Test casing and CIBP with chart to 500 psi for 30 minutes. Use 1000# max spring and 24 hr max chart.		
4. TIH with tubing to 1,900' for storage.		
5. RDMO rig.		
		•
	, <i>i</i>	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-		
grade tank has been/will be constructed or clo	sed according to NMOCD guidelines \square , a general permit \square	or an (attached) alternative OCD-approved plan 🔲.
SIGNATURE TAMMINE IM	TITLE Regulatory Specia	llist DATE 7/26/2004
- John Marine	TILL TOGULATORY SPECIA	DAIL_//2012004_
Type or print name Tammy Jones	E-mail address: twimsatt@br-	-inc.com Telephone No. (505) 326-9700
For State Use Only	1	• • • • • • • • • • • • • • • • • • • •
APPROVED BY: Chah The TITLE TITLE OIL & GAS INSPECTOR, DIST. SEE DATE 27 2004 Conditions of Approval (if any):		
APPROVED BY: Viah // Conditions of Approval (if any):	TITLE TITLE GAS INSI	DATE 2 2004
Conditions of Approval (it airy):		