

Submit 3 Copies
to Appropriate
District Office

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210


DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088



PN
Form C-103
Revised 1-1-89

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-031-20812
1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER: _____		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator ROBERT L. BAYLESS		6. State Oil & Gas Lease No. LH-3667
3. Address of Operator P.O. BOX 168 FARMINGTON, NM 87499		7. Lease Name or Unit Agreement Name STATE
4. Well Location Unit Letter L : 1650 Feet from the SOUTH Line and 330 Feet from The WEST Line Section 16 Township 16N Range 6W NMPM McKINLEY County		8. Well No. 7
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 6542' GL		9. Pool name or Wildcat North Miguel Creek Field

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO :		SUBSEQUENT REPORT OF :	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Robert L. Bayless plugged and abandoned this well 6/4/03. The procedure is attached.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Tom McCarthy TITLE ENGINEER DATE 6/25/03

TYPE OR PRINT NAME Tom McCarthy TELEPHONE NO. (505) 327-2659

(This space for State Use) APPROVED BY H. Villanueva DEPUTY OIL & GAS INSPECTOR, DIST. # 3 DATE SEP - 1 2004

CONDITIONS OF APPROVAL, IF ANY: 9-1-04.

Robert L. Bayless
Plug and Abandon Report

State No. 7

1650' FSL & 330' FWL, Section 16, T16N, R6W

McKinley County, NM

6/3/2003: Rig up JC Well Service. Trip out with rods and pump. Trip in tubing and tag PBD at 1216'. Roll hole with water. Mix and spot 16 sack bottom plug at 1216'. Trip out tubing and WOC.

6/4/2003: Trip in and tag plug at 1060'. Pressure test casing to 200 PSI, failed. Perforate squeeze holes at 131'. Mix and pump 64 sacks cement. Circulated cement up casing and up backside. Rigged down. Class B cement was used.

Top off cement in both casings. Installed abandonment marker and backfilled pit. Cleaned up location.