

Office	State of New Me	exico		Form C-	-103
District I	Energy, Minerals and Natu	ral Resources		March 4,	2004
1625 N. French Dr., Hobbs, NM 88240	nch Dr., Hobbs, NM 88240		WELL API NO.		
District II	District II 301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-045-32472		
District III 1220 South St. Francis Dr.		5. Indicate Type of Lease			
1000 Rio Brazos Rd Aztec NM 97410		STATE	FEE		
District IV	Santa Fe, NM 8'	/505	6. State Oil & G	as Lease No.	
/ 1220 S. St. Francis Dr., Santa Fe, NM 87505		ment of which takes you			
	ES AND REPORTS ON WELLS	(303m) > X	7 Lease Name o	or Unit Agreement Na	me
(DO NOT USE THIS FORM FOR PROPOSAL	LS TO DRILL OR TO DEEPEN OR PL	UG BACK TO A		ernaghan B	
DIFFERENT RESERVOIR. USE "APPLICA"	ΓΙΟΝ FOR PERMIT" (FORM Ć-101) FO	OR SUCH : O'		vell NMSF 078387A)	
PROPOSALS.)	[5] J.	2004	(	0,000,000	
1. Type of Well: Oil Well ☐ Gas Well ☒ C	ther S of	19 7 3 a	8. Well Number		
On wen	the the	Aleksan G		8 S	
	150	6101 8 Si		·· · · · · · · · · · · · · · · · · ·	
2. Name of Operator	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		9. OGRID Num		
BP AMERICA PRODUCTION CO	<u> </u>	7 // 01 (5) (5) (5)	10 D1	000778	
3. Address of Operator P.O. BOX 3092 HOUSTON, TX 7	7070 2064	46.31 JL N. 120	10. Pool name o	Fruitland Coal	- 1
4. Well Location	70 / 9-2004		Basin	Fruitiand Coai	
4. Well Location					İ
Unit Letter E · 1470	feet from theNORTH	line and 1160	feet from the \	WEST line	
Offit Letter E : 1470	icet nom the <del>NORTH</del>	_ inic and	icct from the v	WL <u>SI</u> IIIC	
Section 33	Township 31N	Range 08W	NMPM	SAN JUAN Cour	nty
	11. Elevation (Show whether DR	, RKB, RT, GR, etc.)			
	6483'				
Pit or Below-grade Tank Application (For pi	t or below-grade tank closures, a form	C-144 must be attached	<del>D</del>		
Pit Location: UL_E_Sect_33 Twp_31	<u>N_Rng_08W_</u> Pit type_Drilling_De	pth to Groundwater >1	00' Distance from ne	arest fresh water well <u>&gt;10</u>	00'
Distance from nearest surface water_>1000	' Below-grade Tank Location UL E	Sect 33 Twp 31N	Rng 08W :		1
1430 feet from the NORTH line and 117	5 feet from the WEST line PLEAS	F SEE ATTACHED PA	n		l
1430 feet from the NORTH line and 117	'5 feet from the <u>WEST</u> line PLEAS	E SEE ATTACHED PA	D		
1430 feet from the NORTH line and 117	5 feet from the WEST line PLEAS	E SEE ATTACHED PA	D		
	<u>'5 feet from the WEST line PLEAS</u> propriate Box to Indicate N			r Data	
	propriate Box to Indicate N	lature of Notice,	Report or Other		
12. Check Ap	propriate Box to Indicate N	lature of Notice,	Report or Other		
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK	propriate Box to Indicate NENTION TO: PLUG AND ABANDON	Vature of Notice, SUBS	Report or Other SEQUENT RE	EPORT OF: ALTERING CASING	 
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK	propriate Box to Indicate N	Jature of Notice,	Report or Other SEQUENT RE	EPORT OF: ALTERING CASING PLUG AND	
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK  TEMPORARILY ABANDON	propriate Box to Indicate NENTION TO: PLUG AND ABANDON   CHANGE PLANS	Vature of Notice, SUBS REMEDIAL WORK	Report or Other SEQUENT RE C   LLING OPNS.	EPORT OF: ALTERING CASING	
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING	propriate Box to Indicate NENTION TO: PLUG AND ABANDON   CHANGE PLANS   MULTIPLE	Vature of Notice, SUB: REMEDIAL WORK COMMENCE DRING CASING TEST AN	Report or Other SEQUENT RE C   LLING OPNS.	EPORT OF: ALTERING CASING PLUG AND	;
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING	propriate Box to Indicate NENTION TO: PLUG AND ABANDON   CHANGE PLANS	Vature of Notice, SUBS REMEDIAL WORK	Report or Other SEQUENT RE C   LLING OPNS.	EPORT OF: ALTERING CASING PLUG AND	;   ;
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING	propriate Box to Indicate NENTION TO: PLUG AND ABANDON   CHANGE PLANS   MULTIPLE	Vature of Notice, SUB: REMEDIAL WORK COMMENCE DRING CASING TEST AN	Report or Other SEQUENT RE C   LLING OPNS.	EPORT OF: ALTERING CASING PLUG AND	
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK  TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION	Tature of Notice, SUBSTANTIAL	Report or Other SEQUENT RE  LING OPNS.	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT	
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complete	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all	Tature of Notice, SUBSTANDED TO SUBSTANDED T	Report or Other SEQUENT RE  LING OPNS.  ID	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate	ed date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complete	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION	Tature of Notice, SUBSTANDED TO SUBSTANDED T	Report or Other SEQUENT RE  LING OPNS.  ID	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate	ed date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION   ded operations. (Clearly state all ). SEE RULE 1103. For Multip	REMEDIAL WORK COMMENCE DRING CASING TEST AN CEMENT JOB OTHER: pertinent details, and	Report or Other SEQUENT RE  LING OPNS.  ID  I give pertinent dar ach wellbore diag	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp	ed date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all ). SEE RULE 1103. For Multipluan Basin Drilling/Workover	Inture of Notice, SUBS REMEDIAL WORK COMMENCE DRING CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	Report or Other SEQUENT RE  LING OPNS.  D  I give pertinent da ach wellbore diag an on file with th	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp	ed date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.  Please reference BP America's San J	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all ). SEE RULE 1103. For Multipluan Basin Drilling/Workover	Inture of Notice, SUBS REMEDIAL WORK COMMENCE DRING CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	Report or Other SEQUENT RE  LING OPNS.  D  I give pertinent da ach wellbore diag an on file with th	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp	ed date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.  Please reference BP America's San J	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all ). SEE RULE 1103. For Multipluan Basin Drilling/Workover	Inture of Notice, SUBS REMEDIAL WORK COMMENCE DRING CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	Report or Other SEQUENT RE  LING OPNS.  D  I give pertinent da ach wellbore diag an on file with th	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp	ed date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.  Please reference BP America's San 3 Construction Plan issued date of 04/	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION   ed operations. (Clearly state all ). SEE RULE 1103. For Multipluan Basin Drilling/Workover 15/2004. Pit will be closed according to the control of the co	Tature of Notice, SUB: REMEDIAL WORK COMMENCE DRIF CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	Report or Other SEQUENT RE C	EPORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp	d date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion. Please reference BP America's San 3 Construction Plan issued date of 04/	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all.). SEE RULE 1103. For Multiplication See Rule 1103. For Multiplication and Complete to the book ove is true and complete to the book over 15/2004.	REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	Report or Other SEQUENT RE  LING OPNS.  I give pertinent dar ach wellbore diag an on file with the on file	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit	d date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.  Please reference BP America's San 3 Construction Plan issued date of 04/	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all.). SEE RULE 1103. For Multiplication See Rule 1103. For Multiplication and Complete to the book ove is true and complete to the book over 15/2004.	REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	Report or Other SEQUENT RE  LING OPNS.  I give pertinent dar ach wellbore diag an on file with the on file	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit	d date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING   OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion. Please reference BP America's San J Construction Plan issued date of 04/  I hereby certify that the information ab grade tank has been/will be constructed or cleaning the constructed or cleaning and constructed or cleaning the constructed or	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all b). SEE RULE 1103. For Multiple In Basin Drilling/Workover 15/2004. Pit will be closed according to NMOCD guidelines in the based according to NMOCD guidelines in the seed according to NMOCD guidel	SUBSTANCE DRIVERS COMMENCE DRIVERS CASING TEST AND CEMENT JOB OTHER: pertinent details, and ole Completions: Attended to closure played a general permit  est of my knowledged, a general permit	Report or Other SEQUENT RE  LING OPNS.  Igive pertinent datach wellbore diagen on file with the control of the	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit  ther certify that any pit or inative OCD-approved pla	d date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion. Please reference BP America's San 3 Construction Plan issued date of 04/	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all b). SEE RULE 1103. For Multiple In Basin Drilling/Workover 15/2004. Pit will be closed according to NMOCD guidelines in the based according to NMOCD guidelines in the seed according to NMOCD guidel	REMEDIAL WORK COMMENCE DRIC CASING TEST AN CEMENT JOB OTHER: pertinent details, and ole Completions: Att	Report or Other SEQUENT RE  LING OPNS.  Igive pertinent datach wellbore diagen on file with the control of the	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit	d date
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.  Please reference BP America's San & Construction Plan issued date of 04/  I hereby certify that the information ab grade tank has been/will be constructed or cleaning the constructed or	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Ed operations. (Clearly state all 2). SEE RULE 1103. For Multiple In Section 15/2004. Pit will be closed according to NMOCD guidelines of the based according to NMOCD guidelines of the property of the pro	CASING TEST AN CEMENT JOB OTHER:  pertinent details, and ole Completions: Attraction Planting to closure planting to closure planting to general permit  LE Regulatory Ana	Report or Other SEQUENT RE C	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit  her certify that any pit or inative OCD-approved pla  DATE 9/30/04	d date bletion
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion. Please reference BP America's San J Construction Plan issued date of 04/  I hereby certify that the information ab grade tank has been/will be constructed or cleaning the constructed or cleaning and constructed or cleaning the constructed or	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION  ded operations. (Clearly state all b). SEE RULE 1103. For Multiple In Basin Drilling/Workover 15/2004. Pit will be closed according to NMOCD guidelines in the based according to NMOCD guidelines in the seed according to NMOCD guidel	CASING TEST AN CEMENT JOB OTHER:  pertinent details, and ole Completions: Attraction Planting to closure planting to closure planting to general permit  LE Regulatory Ana	Report or Other SEQUENT RE C	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit  ther certify that any pit or inative OCD-approved pla	d date bletion
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.  Please reference BP America's San Construction Plan issued date of 04/  I hereby certify that the information ab grade tank has been/will be constructed or cleaning the constructed or c	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Ed operations. (Clearly state all 2). SEE RULE 1103. For Multiple In Section 15/2004. Pit will be closed according to NMOCD guidelines of the based according to NMOCD guidelines of the property of the pro	CASING TEST AN CEMENT JOB OTHER:  pertinent details, and ole Completions: Attraction Planting to closure planting to closure planting to general permit  LE Regulatory Ana	Report or Other SEQUENT RE C	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit  her certify that any pit or inative OCD-approved pla  DATE 9/30/04	d date bletion
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.  Please reference BP America's San 3. Construction Plan issued date of 04/  I hereby certify that the information ab grade tank has been/will be constructed or cle SIGNATURE Cherry Hlava  Type or print name Cherry Hlava	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE COMPLETION  Ed operations. (Clearly state all 2). SEE RULE 1103. For Multiple In Section 15/2004. Pit will be closed according to NMOCD guidelines of the based according to NMOCD guidelines of the property of the pro	CASING TEST AN CEMENT JOB OTHER:  pertinent details, and ole Completions: Attraction Planting to closure planting to closure planting to general permit  LE Regulatory Ana	Report or Other SEQUENT RE C	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit  her certify that any pit or native OCD-approved pla  DATE 9/30/04  one No. 281-366-40	d date bletion
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion.  Please reference BP America's San 3. Construction Plan issued date of 04/  I hereby certify that the information ab grade tank has been/will be constructed or cle SIGNATURE Cherry Hlava  Type or print name Cherry Hlava	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION   ded operations. (Clearly state all b). SEE RULE 1103. For Multiple Itam Basin Drilling/Workover 15/2004. Pit will be closed according to NMOCD guidelines   MANY ALLOW TITE  E-mail address	SUBSTANCE DRIVERS  COMMENCE DRIVERS  CASING TEST AND CEMENT JOB OTHER:  pertinent details, and ole Completions: Attributed to closure players of my knowledged and general permit □  LE Regulatory Anales:	Report or Other SEQUENT RE (	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit  her certify that any pit or inative OCD-approved pla  DATE 9/30/04  one No. 281-366-40	d date bletion
12. Check Ap NOTICE OF INT PERFORM REMEDIAL WORK   TEMPORARILY ABANDON  PULL OR ALTER CASING  OTHER: Lined Drilling PIT PERMIT  13. Describe proposed or complet of starting any proposed work or recompletion. Please reference BP America's San J Construction Plan issued date of 04/  I hereby certify that the information ab grade tank has been/will be constructed or cle SIGNATURE Cherry Hlava  Type or print name Cherry Hlava  (This space for State use)	propriate Box to Indicate NENTION TO: PLUG AND ABANDON  CHANGE PLANS  MULTIPLE  COMPLETION   ded operations. (Clearly state all b). SEE RULE 1103. For Multiple Itam Basin Drilling/Workover 15/2004. Pit will be closed according to NMOCD guidelines   MANY ALLOW TITE  E-mail address	CASING TEST AN CEMENT JOB OTHER:  pertinent details, and ole Completions: Attraction Planting to closure planting to closure planting to general permit  LE Regulatory Ana	Report or Other SEQUENT RE (	PORT OF: ALTERING CASING PLUG AND ABANDONMENT  tes, including estimate ram of proposed comp e NMOCD. Pit  her certify that any pit or inative OCD-approved pla  DATE 9/30/04  one No. 281-366-40	d date bletion

## PAD LAYOUT PLAN & PROFILE BP AMERICA PRODUCTION COMPANY

Kernaghan B #8S 1470' F/NL 1160' F/WL SEC. 33, T31N, R8W, N.M.P.M. SAN JUAN COUNTY, NEW MEXICO





NOTE: Contractor should call One-Call for location of any marked or unmarked buried pipelines or cables on well pad and/or access road at least two (2) working days

36°51'27"

Lat:

Cuts and fills shown are approximate — final finished elevation is to be adjusted so earthwork will balance. Corner stakes are approximate and do not include additional areas needed for sideslopes and drainages. Final Pad Dimensions are to be verified by Contractor.

> VANN SURVEYS P. O. Box 1306 Farmington, NM