	Submit 3 Copies To Appropriate District Office		New Mexico			Form C	
	District I	Energy, Minerals	and Natural Re	sources	WELL API NO.	March 4,	2004
	1625 N. French Dr., Hobbs, NM 88240 District II			\	30-045- 7	31976	ļ
	1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERV		1210N		of Lease - FEDERAI	
	District III 1000 Rio Brazos Rd., Aztec, NM 87410	Dis Program Dd. Artes NW 97410			STATE	FEE	
/	District IV	Santa Fe	e, NM 87505		6. State Oil & G		
	1220 S. St. Francis Dr., Santa Fe, NM 87505				Federal: NM-17	781	
Γ	SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name of	or Unit Agreement Na	me
	(DO NOT USE THIS FORM FOR PROPOS						
1	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Paul Revere 8. Well Number		
1	1. Type of Well:		AS II		ş. wen number 93S		
L	Oil Well Gas Well	Other	100	- 200a 1	[대		
	2. Name of Operator		- C		9 OGRID Num	ber	
ŀ	Dugan Production Corp.		672		006515 10. Pool name o	n Wildoor	
	 Address of Operator P. O. Box 420, Farmington, NM 87 	7499_0420			Basin Fruitland (}
+	4. Well Location	777-0420		1. 3. 3. 3.	Basin i Talkana (
	4. Well Excation			4.9.5.1			
	Unit Letter F: 215	0 feet from the N	North line an	id 1375	feet from the	West line	
١							
	Section 22	Township 26N			M County	San Juan	
000000		11. Elevation (Show wi	neiner DR, RKB, 6187' GL	KI, GR, etc.)			
	Pit or Below-grade Tank Application (For	pit or below-grade tank clos		nust be attached)			
Pit Location: UL F Sect 22 Twp 26N Rng 13W Pit type Lined Reserve Pit Depth to Groundwater * Distance from nearest fresh water well 3.2 miles							
	Distance from nearest surface water 200					-	
١	feet from theline and						
ŀ							
L							
_						_	
		appropriate Box to Ir	ndicate Nature				
_	NOTICE OF IN	TENTION TO:		SUBS	EQUENT RE	PORT OF:	. [
_		TENTION TO:			EQUENT RE		3 🗆
	NOTICE OF IN	TENTION TO:	I □ REM	SUBS EDIAL WORK	EQUENT RE	PORT OF:	3 🗆
•	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	TENTION TO: PLUG AND ABANDON CHANGE PLANS	REM	SUBS EDIAL WORK	EQUENT RE	EPORT OF: ALTERING CASING	
•	NOTICE OF IN	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE	REM COM CAS	SUBS IEDIAL WORK IMENCE DRIL ING TEST ANI	EQUENT RE	EPORT OF: ALTERING CASING PLUG AND	
	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	TENTION TO: PLUG AND ABANDON CHANGE PLANS	REM COM CAS CEM	SUBS JEDIAL WORK JIMENCE DRIL JING TEST ANI JENT JOB	EQUENT RE	EPORT OF: ALTERING CASING PLUG AND	
•	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	REM COM CAS	SUBS JEDIAL WORK JIMENCE DRIL JING TEST ANI JENT JOB	EQUENT RE	EPORT OF: ALTERING CASING PLUG AND	
_	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD For 13. Describe proposed or complete to the complete	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearly	REM COM CAS CEM OTH y state all pertine	SUBS IEDIAL WORK IMENCE DRIL ING TEST ANI IENT JOB ER: int details, and	LING OPNS.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate	□ □ ed date
-	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Form 13. Describe proposed or complete of starting any proposed wo	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearly	REM COM CAS CEM OTH y state all pertine	SUBS IEDIAL WORK IMENCE DRIL ING TEST ANI IENT JOB ER: int details, and	LING OPNS.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate	□ □ ed date
_	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Formatting any proposed wo or recompletion.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearly	REM COM CAS CEM OTH y state all pertine For Multiple Com	SUBS JEDIAL WORK JEDIAL WORK JEDIAL WORK JEST AND JEST	LING OPNS.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed com-	ed date
	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Formation and proposed or complete of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearly rk). SEE RULE 1103. I	REM COM CAS CEM OTH y state all pertine For Multiple Com	SUBS JEDIAL WORK JEDIAL WORK JEDIAL WORK JEST AND JEST	LING OPNS.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linear	ed date
1	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Formation of Starting any proposed woor recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion.	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearly rk). SEE RULE 1103. I pit tank information for ion, no pits will be neede	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 56 d at the well. Al	SUBS JEDIAL WORK JEDIAL WORK JEDIAL WORK JENT JOB JENT JOB JER: Jent details, and appletions: Atta O compliance. I production w	LING OPNS. Degive pertinent data ach wellbore diagen During drilling at ill be transferred	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan	ed date pletion
]	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Formation and proposed or complete of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearly rk). SEE RULE 1103. If pit tank information for ion, no pits will be needed. Reserve pit will be as	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure	SUBS JEDIAL WORK MENCE DRIL ING TEST AND JENT JOB ER: Int details, and inpletions: Atta 0 compliance. 1 production we requirements	EQUENT RE LING OPNS. D give pertinent da ach wellbore diag During drilling a fill be transferred If appropriate,	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will b	cd date pletion
]	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Formation of Starting any proposed woor recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion Production's Topaz Gathering System	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed. Reserve pit will be as rized disposal site, the pit	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure	SUBS JEDIAL WORK MENCE DRIL ING TEST AND JENT JOB ER: Int details, and inpletions: Atta 0 compliance. 1 production we requirements	EQUENT RE LING OPNS. D give pertinent da ach wellbore diag During drilling a fill be transferred If appropriate,	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will b	cd date pletion
1 1 2	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Form 13. Describe proposed or complete of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon complete production's Topaz Gathering System removed and disposed of at an author guidelines will be followed until a general starting and the production of the production	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed. Reserve pit will be as rized disposal site, the pit ineral permit is secured.	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure t fluids allowed t	SUBS JEDIAL WORK MENCE DRIL ING TEST ANI JENT JOB ER: Int details, and inpletions: Atta 0 compliance. 1 production we requirements o evaporate an	give pertinent da ach wellbore diag During drilling a fill be transferred the pit covered	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will b and contoured. NMC	ed date pletion
1 1 2	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Formation and production and production. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion are production's Topaz Gathering System are moved and disposed of at an authoroguidelines will be followed until a gentlement of the production and disposed of a second production and disposed production are second production and disposed production and disposed production and disposed production are second production are second production are second production are second production and disposed production are second production are second production are second production are second production are	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed. Reserve pit will be as rized disposal site, the pit eneral permit is secured.	REM COM CAS CEM State all pertine For Multiple Com NMOCD Rule 50 d at the well. Alsessed for closure t fluids allowed to	SUBS JEDIAL WORK MENCE DRIL ING TEST ANI JENT JOB ER: Int details, and inpletions: Atta O compliance. I production we requirements o evaporate ani my knowledge	give pertinent da ach wellbore diag During drilling a fill be transferred de the pit covered and belief. I furti	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will b and contoured. NMC	ed date pletion i
1 1 2	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Form 13. Describe proposed or complete of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon complete production's Topaz Gathering System removed and disposed of at an author guidelines will be followed until a general starting and the production of the production	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed. Reserve pit will be as rized disposal site, the pit eneral permit is secured.	REM COM CAS CEM State all pertine For Multiple Com NMOCD Rule 50 d at the well. Alsessed for closure t fluids allowed to	SUBS JEDIAL WORK MENCE DRIL ING TEST ANI JENT JOB ER: Ant details, and apletions: Atta O compliance. I production we requirements o evaporate an	give pertinent da ach wellbore diag During drilling a fill be transferred de the pit covered and belief. I furti	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will b and contoured. NMC	ed date pletion i
1 1 2 2	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Form 13. Describe proposed or complete of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion removed and disposed of at an author guidelines will be followed until a generated tank has been/will be constructed or constructe	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed. Reserve pit will be as rized disposal site, the pit meral permit is secured. above is true and completelosed according to NMOCD	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure t fluids allowed to te to the best of re guidelines \(\times \), a gen	SUBS JEDIAL WORK MENCE DRIL ING TEST ANI JENT JOB ER: Ant details, and apletions: Atta O compliance. I production we requirements o evaporate an	EQUENT RE LING OPNS. D give pertinent da ach wellbore diag During drilling a ill be transferred ill be transferred the pit covered and belief. I furth an (attached) alter	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will b and contoured. NMC	ed date pletion i
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Formation of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion of starting any proposed work or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion of starting System removed and disposed of at an authoroguidelines will be followed until a general formation of the starting starting starting and the starting star	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed in. Reserve pit will be as rized disposal site, the pit eneral permit is secured. The property of the property of the property of the pit eneral permit is secured. The property of the property of the pit eneral permit is secured.	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure t fluids allowed to te to the best of r guidelines \(\text{Q}, \text{ a gen} \)	SUBS JEDIAL WORK MENCE DRIL ING TEST AND JENT JOB ER: Int details, and inpletions: Atta O compliance. I production we requirements o evaporate and injury knowledge peral permit o details and injury compliance.	give pertinent da ach wellbore diag During drilling a fill be transferred. If appropriate, ad the pit covered and belief. I furting an (attached) altered.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will be and contoured. NMC her certify that any pit or mative OCD-approved pla TE July 22, 2004	ed date pletion i
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Form 13. Describe proposed or complete of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion removed and disposed of at an author guidelines will be followed until a generated tank has been/will be constructed or constructe	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed in. Reserve pit will be as rized disposal site, the pit eneral permit is secured. The property of the property of the property of the pit eneral permit is secured. The property of the property of the pit eneral permit is secured.	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure t fluids allowed to te to the best of re guidelines \(\times \), a gen	SUBS JEDIAL WORK MENCE DRIL ING TEST AND JENT JOB ER: Int details, and inpletions: Atta O compliance. I production we requirements o evaporate and injury knowledge peral permit o details and injury compliance.	give pertinent da ach wellbore diag During drilling a fill be transferred. If appropriate, id the pit covered and belief. I further an (attached) after the determinent of the pit covered and belief. I further an (attached) after the determinent of the pit covered and belief. I further an (attached) after the determinent of the pit covered and belief. I further an (attached) after the determinent of the pit covered and belief. I further an (attached) after the pit covered and belief. I further an (attached) after the pit covered and belief.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will be and contoured. NMC her certify that any pit or mative OCD-approved pla TE July 22, 2004	ed date pletion i
	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Form 13. Describe proposed or complete of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon complete Production's Topaz Gathering System removed and disposed of at an authoroguidelines will be followed until a generate tank has been/will be constructed or a stranger or print name John D. Roe	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed in. Reserve pit will be as rized disposal site, the pit eneral permit is secured. The property of the property of the property of the pit eneral permit is secured. The property of the property of the pit eneral permit is secured.	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure t fluids allowed to te to the best of r guidelines \(\text{Q}, \text{ a gen} \)	SUBS JEDIAL WORK MENCE DRIL ING TEST AND JENT JOB ER: Int details, and inpletions: Atta O compliance. I production we requirements o evaporate and injury knowledge peral permit o details and injury compliance.	give pertinent da ach wellbore diag During drilling a fill be transferred. If appropriate, ad the pit covered and belief. I furting an (attached) altered.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will be and contoured. NMC her certify that any pit or mative OCD-approved pla TE July 22, 2004	ed date pletion i
	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Formation of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion of starting any proposed work or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion of starting System removed and disposed of at an authoroguidelines will be followed until a general formation of the starting starting starting and the starting star	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed in. Reserve pit will be as rized disposal site, the pit eneral permit is secured. The property of the property of the property of the pit eneral permit is secured. The property of the property of the pit eneral permit is secured.	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure t fluids allowed to te to the best of r guidelines \(\text{Q}, \text{ a gen} \)	SUBS JEDIAL WORK MENCE DRIL ING TEST AND JENT JOB ER: Int details, and inpletions: Atta O compliance. I production we requirements o evaporate and injury knowledge peral permit o details and injury compliance.	give pertinent da ach wellbore diag During drilling a fill be transferred. If appropriate, ad the pit covered and belief. I furting an (attached) altered.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will be and contoured. NMC her certify that any pit or mative OCD-approved pla TE July 22, 2004	ed date pletion i
	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Form 13. Describe proposed or complete of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon complete Production's Topaz Gathering System removed and disposed of at an authoroguidelines will be followed until a generate tank has been/will be constructed or a stranger or print name John D. Roe	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed. Reserve pit will be as rized disposal site, the pit meral permit is secured. above is true and completelosed according to NMOCD E-mail address:	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure t fluids allowed to te to the best of r guidelines \(\text{Q}, \text{ a gen} \)	SUBS JEDIAL WORK MENCE DRIL ING TEST AND JENT JOB ER: Int details, and inpletions: Atta O compliance. I production we requirements o evaporate and injury knowledge peral permit o details and injury compliance.	give pertinent da ach wellbore diag During drilling a fill be transferred. If appropriate, ad the pit covered and belief. I furting an (attached) altered.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a linea by pipeline to Dugan the excess liner will be and contoured. NMC her certify that any pit or mative OCD-approved pla TE July 22, 2004	ed date pletion i
	NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: Supplement to APD Form 13. Describe proposed or completion of starting any proposed wo or recompletion. APD Dated 10/16/03 did not include reserve pit will exist. Upon completion removed and disposed of at an author guidelines will be followed until a generate tank has been/will be constructed or estrated tank has been/will be constructed to tank	TENTION TO: PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION or Rule 50 Compliance leted operations. (Clearlink). SEE RULE 1103. If pit tank information for ion, no pits will be needed. Reserve pit will be as rized disposal site, the pit meral permit is secured. above is true and completelosed according to NMOCD E-mail address:	REM COM CAS CEM OTH y state all pertine For Multiple Com NMOCD Rule 50 d at the well. Al sessed for closure t fluids allowed t te to the best of re guidelines \(\times \), a gen TITLEEngin johnroe@dugan	SUBS JEDIAL WORK JEDIAL WORK JEDIAL WORK JENT JOB JENT JOB JER: Jent details, and apletions: Atta O compliance. I production we requirements o evaporate and appearance and appear	give pertinent da ach wellbore diag During drilling a fill be transferred. If appropriate, ad the pit covered and belief. I furting an (attached) altered.	PORT OF: ALTERING CASING PLUG AND ABANDONMENT tes, including estimate tram of proposed compand completion a lined by pipeline to Dugan the excess liner will be and contoured. NMC her certify that any pit or mative OCD-approved plane. TE July 22, 2004 No. 325-1821	ed date pletion i