Form	31	60-5	
(Augi	ıst	1999	۱

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED	
OMB No. 1004-0135	
Expires November 30, 200	í

١.	ρ
1	1

-	Lea	Se.	Ser	ial No.			_
				· 603 ·	. 4	908	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.						Indian, A	al No. 603 - 4908 Allottee or Tribe Name 3 Allortee	
and the second	RIPLICATE - Other ins	struction	s on revers	e sia	6 7. If	Unit or C	CA/Agreement, Name and/or No.	
1. Type of Well Zi Oil Well Gas Well	Other		18,1200	A CC	√ -<-/>	Horseshoe Gallup		
2. Name of Operator Velica			APR 2	ງບບ3 ⊛	2	30	1.43	
3a. Address 1000 R10		38 -P	hone No. (includ	le ared	code) 30		10017	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					10. Field and Pool, or Exploratory Area Horse Shoe Gallup			
505/N = 660,	ON., R 16 W.		<u> </u>	۱۰ ۲ شسست	4 37 I	unty or F اں ک	Parish, State	
12. CHECK A	PPROPRIATE BOX(ES)	TO INDIC	CATE NATU	RE C	F NOTICE, REPORT	OR O	THER DATA	
TYPE OF SUBMISSION			TY	TE O	F ACTION			
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	New	pen ture Treat Construction and Abandon	0000	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon	0	Water Shut-Off Well Integrity Other	
Final Abandonment Notice	Convert to Injection	Plug	Back	ā	Water Disposal			
13. Describe Proposed or Complete If the proposal is to deepen dire	d Operation (clearly state all pe	rtinent detail	s, including esti	mated	starting date of any propose	d work a	and approximate duration thereof.	

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

See Attached plugging procedure.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)			
NMOCO CONTract Plugging	Title		
Signature Nm o c 9	Date	4/14/03	
THIS SPACE FOR FEDE	RAL OR	STATE OFFICE USE	
Approved by Original Signed: Stephen Mason		Title	Date 4/16/03
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime fo States any false, fictitious or fraudulent statements or representations as to any matter.	r any perso er within it	on knowingly and willfully to make to siurisdiction.	any department or agency of the United

API WELL # Well Name Well # Operator Name Type Stat County Surf_Owner UL Sec Twp N/S Rng W/E Feet NS Ft EW

Order_No 30-045-10017 HORSESHOE GALLUP UNIT 230 PLAYA MINERALS & ENERGY INC O A San Juan 1 2 30 N 16 W 505

N 660 E

status csg_1 csg_1q csg_1d csg_3 csg_3q csg_3d liner_size liner_quan tubing t_set_dept csg_perf CO 8 5/8 100 103S 5 1/2 1585 103S 4 1/2 1549-1620 2 3/8 1565

1574-1615

Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scrapper if required,

RIH Set CIBP 1475, cap with 325 'cement.

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ 248 '+ - 50' under surface casing shoe or Mesa Verde base whichever is lower..

Establish Circulation; circulate cement to surface inside and outside casing

Cut off well head and install P&A marker

Cut off anchors 2' below ground

Clean and level location

ENTEREN

_

SEC., TWN., RNG. 2-30 Horse shoe Cally Unit

Mesaverle		
Point Lookous		100'
Mancoso 198'		Plus 248
		248/7.483 (1.18) = 28 Set 148/5.7719(1.18) = 22 set 100/5.389 (1.18) = 16 Ses 66 Ses
		Toc = 526' 75% eff.
		i.
		(1475-1150)+50/7: 483(118) = 42 sxs
	-	1 Plus 1475- 1150
Gallup 1200'		1475
		port @ 1574-84'
	/ 	5½" 15.5# 1585' — Carry
SURFACE CASING		- 1620' INTERMEDIATE CASINE
5175 HOLE"		SIZE HOLE" SIZE CASING" Annulur Volume f
nnilar Volume ft /ft. Cement sk		Cements Volumef
Volume fr3		