NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

This form is not to be used for reporting packer leakage tests in Southeast New Mexico

> Page I Revised 11/16/98

÷		NORTHWEST	T NEW MEXICO	, D PACKER-	LEAKAGE TEST		
Opera	ator William	s Produc	tion Leas	se Name	Rosa	Well No 46/	
Location of	Well:Unit Letter	K_Sec_	8 - TWP.3/A	/_Rge_5_/	<u>V</u> api#30-0 392	1698600	
	NAME OF RESE	RVOIR OR POOL		F PROD. or Gas)	METHOD OF PROD. (Flow or Art. Lift)	PROD.MEDIUM (Tbg. or Csg.)	
Upper Completion	on Rosa 46A Mesa Vealle		h CAS		Flub	Tha	
Lower Completion	ROSA 46A	DAHOTA	GAS		Floh	The	
		PRE-	FLOW SHUT-I	N PRESSUR	RE DATA		
Upper Completion	Hour, date shut-in	07 1030	Length of time s	thut-in	SI press. Psig	Stabilized? (Yes or No)	
Lower Completion	Hour, date shut-in	-07 1030	Length of time s	~ *	SI press. Psig	Stabilized? (Yes or No)	
<u></u>		-	FLOW II	T	(Upper or Lower): んのい	0 C	
Commenced at ((hour, date)* 4-14-	-03 1030					
TIME (hour.date)	LAPSED TIME SINCE*	Upper Completion Lower Completion		PROD. ZON TEMP.	Ε	REMARKS	
4-15-03	24601	3624	434 #	420		``	
4-16-03	48 /15	372"	398#	430		Million and the second	
4-17-03	72hp	384	244	420			
		A Sec	830		No.		
					<u> </u>		
						Nice Children	
Production ra	ate during test						
Oil:		BOPD bas	ed on	Bbls. in	nHours	GravGOR	
Gas:	348	мс	CFPD; Tested ti	hru Orifice	r Meter):		
		MID	-TEST SHUT-II	N PRESSUR	E DATA		
Upper Completion	Hour, date shut-in		Length of time	shut-in	SI press psig	Stabilized? (Yes or No)	
Lower Completion	Hour, date shut-in		Length of time	shut-in	SI press. psig	Stabilized? (Yes or No)	

			FLOW T	EST NO. 2	
Commence	d at (hour, date)	**	Zone producing (Upper or Lowr):		
TIME (hour,date)	LAPSED TIME Since**	PRESS Upper Completion	SURE Lower Completion	PROD. ZONE	REMARKS
····					
roduction rat	te during test				
)il: :as:	BOPD	based onMCF	Bbl PD:Tested thru (s. inHours Orfice or Meler):	GravGOF
emarks:					
nereby c ertify	that the inform	alion herein cor	ntained is true an	d complete to the be	s of my knowledge.
JDI OVEU_	Conservation Div	20	Operator	william (ReducTION
Charl	ie Thern		By Title	W:11:AM () TECH TH 4-17-03	
UEPUTY ON lle	. & GAS INSPECT	09. OIST. #7	 Date	4-17-03	

NORTHWEST NEW MEXICO PACKER LEAKAGE TEST INSTRUCTIONS

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.
- 2. At least 72 hours prior to the commencement of any packer leakage test, the operator shall notify the Division in writing of the exact time the test is to be commenced. Offset operators shall also be so notified.
- The packer leakage test shall commence when both zones of the dual completion are shut-in for pressure stabilization. Both zones shall remain shut-in until the well-head pressure in each has stabilized, provided however, that they need not remain shut-in more than seven days.
- 4. For Flow Test No. 1, one zone of the dual completion shall be produced at the normal rate of production while the other zone remains shut-in. Such test shall be continued for seven days in the case of a gas well and for 24 hours in the case of an oil well. Note: if, on an initial packer leakage test, a gas well is being flowed to the almosphere due to the lack of a pipeline connection the flow period shall be three hours.
- 5. Following completion of Flow Test No. 1, the well shall again be shut-in, in accordance with Paragraph 3 above.
- 6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test no. 2 is to be the same as for Flow Test No. 1 except

- 7. Pressures for gas-zone tests must be measured on each zone with a deadweight pressure gauge at time intervals as follows: 3 hours tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and Immediately prior to the conclusion of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test date.
- 24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.
- 8. The result s of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico oil Conservation Division on northwest new Mexico packer leakage Test Form Revised 11-16-98 with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).

that the previously produced zone shall remain shut-in while the zone which was previously shut in is produced.