

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

BCED OPERATING, INC.

3a. Address

3b. Phone No. (include area code)

P.O. Box 1680, Hobbs, NM 88241

505-397-3972

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

M, 1260' FSL, 100' FWL, Sec. 6, T17N, R8W

5. Lease Serial No.

NM 052931

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Hanson Fed. #43

9. API Well No.

30-031-20869

10. Field and Pool, or Exploratory Area

HOSPAA LWR. 3rd

11. County or Parish, State

McKinley, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

* PLEASE SEE ATTACHMENT



14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Donnie Hill

Title

President

Signature

Donnie Hill

Date

11/8/2004

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

ACCEPTED FOR RECORD

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NOV 16 2004

NMOCD

FARMINGTON FIELD OFFICE
BY Jim

HANSON FEDERAL NO. 43

30-031-20869

M, SEC. 06, T17N, R08W

SUMMARY OF PLUGGING OPERATIONS

AUGUST 4, 2004

MIRU PLUGGING EQUIPMENT, CONDUCT SAFETY MEETING, INSTALL BOP, RLS AD-1 PKR., POOH AND LAY DN. 2 3/8" TBG. AND PKR, PU AND TIH WITH 2 7/8" WORK STRING, TAG TD @ 1570.55' (PERFS @ 1524' - 1540'), SDFN

AUGUST 9, 2004

CREW TO LOCATION, CONDUCT SAFETY MEETING, (TBG @ 1550') LOAD HOLE W/ WATER AND CIRCULATE TO REVERSE PIT TO CLEAN UP WELL, MIX AND PUMP 43 SXS. CLASS "B" CMT @ 15.6#/GAL, SPOT BALANCED PLUG @ 1550' - 1000', WASH UP EQUIPMENT, POOH W/ WORK STRING, SECURE WELL SIWOC.

BLM= VIRGIL

NEPA= LEEROY LEE

OCD= BRUCE MARTIN

AUGUST 10, 2004

CREW TO LOCATION, CONDUCT SAFETY MEETING, MIRU WIRELINE TRUCK, TIH W/ WIRELINE, TAG TOC @ 1216', POOH W/ WIRELINE, NIPPLE UP WELL HEAD, PRESSURE TEST CSG TO 500 PSIG, HELD OKAY, TIH W/ PERF GUN, PERF 2 SQUEEZE HOLES @ 609', ATTEMPT TO BREAK DOWN AND PUMP INTO SQUEEZE HOLES @ 609, COULD NOT @ 650 PSIG, REPERF @ 559' COULD NOT PUMP INTO PERFS @ 700 PSIG, REPERF @ 350' COULD NOT PUMP INTO PERFS @ 700 PSIG, REPERF @ 120' BREAK CIRCULATION OUT BRADEN HEAD TO LINED EARTH PIT, RIG DN AND RLS WIRELINE TRUCK, TIH W/ WORK STRING TO 950', MIX AND PUMP 100 SXS CLASS "B" NEAT CMT @ 15.7 #/GAL., CIRCULATE CEMENT TO SURFACE CLOSE BOP, CIRCULATE OUT BRADEN HEAD, CEMENT DID NOT CIRCULATE, MIX AND PUMP AN ADDITIONAL 30 SXS CLASS "B" NEAT CMT @ 15.7 #/GAL., CIRCULATED

SLURRY TO LINED EARTH PIT, POOH W/ TBG. TOP OFF CSG. WASH UP ALL
EQUIPMENT, HOLE STABLE

WELL IS PLUGGED.

BLM= VIRGIL
NEPA= LEEROY LEE

WILL INSTALL P&A MARKER AND RESTORE LOCATION AS REQUIRED.