Form 3160-5	
(August 1995)	

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

rukwi appruved
OMB NO. 1004-0135
Expires: November 30, 2000

SHIP

NDRY NOTICES AND REPORTS ON WELLS

Lease Serial No. NMSF077111

Do not use thi	s form for proposals to drill	or to re-enter an	<b>/</b>		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRII	PLICATE - Other instructions	on reverse side.		7. If Unit or CA/Agreer	ment, Name and/or No.
1. Type of Well				8. Well Name and No. STOREY C 2M	· · · · · · · · · · · · · · · · · · ·
Oil Well Gas Well Oth					
2. Name of Operator Contact: MARY CORLEY BP AMERICA PRODUCTION CO E-Mail: CORLEYML@BP.COM			9. API Well No. 30-045-25322-00-C1		
3a. Address 200 ENERGY CT FARMINGTON, NM 87402	200 ENERGY CT Ph: 281-366-4491			10. Field and Pool, or Exploratory BLANCO MESAVERDE OTERO CHACRA	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, a	nd State
Sec 35 T28N R9W SWNW 18 36.62059 N Lat, 107.76421 W				SAN JUAN COU	NTY, NM
12. CHECK APPE	ROPRIATE BOX(ES) ȚO INI	DICATE NATURE OF N	NOTICE, RI	EPORT, OR OTHER	DATA
TYPE OF SUBMISSION		TYPE OF	FACTION		
— Notice of Intent	☐ Acidize	Deepen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off
☐ Notice of Intent	☐ Alter Casing	Fracture Treat	□ Reclama	ation	☐ Well Integrity
Subsequent Report     ■	Casing Repair	☐ New Construction	Recomp	lete	Other
☐ Final Abandonment Notice	Change Plans	Plug and Abandon	on		
	☐ Convert to Injection	Plug Back	☐ Water Disposal		
from 6430' to 6230'. Balance	operations. If the operation results in pandonment Notices shall be filed onlined inspection.)  a & Mesaverde and restore to NU BOPs. Pressure test BOF& CSG scraper & tag hard spoest the Chacra formation thru of 4137' & reset PKR. Flow test /e RBP & POOH. RIH w/CSG HCL. TIH & tag scale @ 4596. IN SCANT plug from 7264 to 7064 IH & tag CMT @ 6460'. Constrom 6460' to 6660'. TOH. TIH d plug. TOH. TIH & tag CMT @	n a multiple completion or recy after all requirements, including after all requirements and after all requirements and after all requirements after a multiple after a multiple after all requirements after all requirements after all requirements after a multiple after a multipl	ompletion in a signing reclamation of the properties of the proper	new interval, a Form 3160, have been completed, a nly:  st Ok. TOH set RBP @  te 280 TIH to 4550' H. TIH CMT for ne	0-4 shall be filed once and the operator has
14. I hereby certify that the foregoing is	Electronic Submission #5171	1 verified by the BLM Wel	I Information	System	- Manager of the trans
Cor	mmitted to AFMSS for processi	ng by STEVE MASON on 1	12/13/2004 (0	4SXM1787SE)	
Name (Printed/Typed) MARY CC	PRLEY	Title AUTHO	RIZED REF	RESENTATIVE	
Signature (Electronic S		Date 12/09/2			
	THIS SPACE FOR F	EDERAL OR STATE	OFFICE U	5E	
Approved By ACCEPT	ED	STEPHEN TitlePETROLE		EER	Date 12/13/2004
Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to conditions.	uitable title to those rights in the subj		ıton		

## Additional data for EC transaction #51711 that would not fit on the form

## 32. Additional remarks, continued

leave plug as is. TIH w/CMT retainer & set @ 4864'. Mix & pumped 6.7 BBLs CLS B NEAT CMT& displaced to retainer. Sting out of retainer. Let displacement equalize in hole. Mix & pumped a 2.5 BBLs CMT plug to balance on top of CMT for 150' plug.Let plug fall & balance hole. TIH & tag CMT @ 4036'. Notified BLM of CMT top. BLM Okd. Made 12 swab runs. TOH. TIH w/2-3/8" production TBG & land @ 3980', ND BOPs. NUWH. 11/15/2004 RDMOSU.

Return well to production in Chacra formation only.