Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well					
					Horseshoe Gallup
			Oil Well Gas Well Other		
an Minerals & Energy		297 HGU			
Br 201 00	2h Phono No. C. L.	9. API Well No.			
Nm 87410	334-6170	30045 22 097			
ec., T., R., M., or Survey Descript	ion)	10. Field and Pool, or Exploratory Area			
Sec. 4 , T. 30N., R. 16 W.		11. County or Parish, State			
		San Juan NM			
PPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOTICE	CE, REPORT, OR OTHER DATA			
	TYPE OF ACTION				
Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Fracture Treat Reclamation New Construction Recomplet	te Other			
the work will be performed or pr volved operations. If the operation inal Abandonment Notices shall of for final inspection.)	ovide the Bond No. on file with BLM/BIA. on results in a multiple completion or recomplete filed only after all requirements, including	Required subsequent reports shall be filed within 30 day			
CON	ee attached for Diolog of approval	MM 2003			
	Other Ot	Other 30 M/Acals & Energy 35. Phone No. (include area code) 334-6178 30N., R. 16 W., 250/E APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE TYPE OF ACTION Acidize Deepen Production Alter Casing Fracture Treat Casing Repair New Construction Recomplet Change Plans Plug and Abandon Temporari Convert to Injection Plug Back Water Displaced Operation (clearly state all pertinent details, including estimated starting date ectionally or recomplete horizontally, give subsurface locations and measured at the work will be performed or provide the Bond No. on file with BLM/BIA. volved operations. If the operation results in a multiple completion or recomplinal Abandonment Notices shall be filed only after all requirements, including for final inspection.)			

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) NMOCD Contract Plugging	Title		
Signature NM 0 C 9 THIS SPACE FOR FEDE	Date	5/1/03	
Approved by M M. Conditions of approval, if any, are attached. Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	Title		MAY 0 5 2003

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

API WELL # Well Name Well # Operator Name Type Stat County Surf_Owner UL Sec Twp N/S Rng W/E Feet NS Ft EW

Order_No 30-045-22097 HORSESHOE GALLUP UNIT 297 PLAYA MINERALS & ENERGY INC O A San Juan I 4 30 N 16 W

1550 S 1250 E

api_number status csg_1 csg_1q csg_1d csg_2 csg_2q csg_2d csg_3 csg_3q csg_3d liner_size liner_quan tubing t_set_dept csg_perf 30-045-22097 CO 8 5/8 139 120S 5 1/2 1368 225S 2 7/8 1315 1292-1302

Procedure

MIRU, NUBOPE,

POOH Lay Down Rods & Tubing if present,

RIH with Gauge ring,

Pick up work string, Run Scrapper if required,

RIH Set CIBP 1100 ', cap with 215 'cement .

Test casing.

POOH lay down tubing.

RU wire line RIH, perforate @ 189 '+ - 50' under surface casing shoe or Mesa Verde base whichever is lower..

Establish Circulation; circulate cement to surface inside and outside casing

Cut off well head and install P&A marker

Cut off anchors 2' below ground

Clean and level location

Note! Cement reported circulated on 5/2" casing so ferting @ 189' may

SEC, TWH, RNG. 4-3UN-16W

Mancos	85/8" 24#
	139/7.299(1.18) = 16 500
Gallup 935'	(1100 - 885) (1100 - 885) (1100 - 885) (1100 - 885) (1100 - 885)
	1190-1240 Perts @ 1292-1302 51/2 14#
URFACE CASING	1368' INTERMEDIATE CASIN
HOLE"	5128 HOLE

SIZE HOLE ___"

SIZE CASING ___"

Annilar Volume ___ f+3/f+.

Cement ___ sk

Volume ___ f+3

51ZE HOLE ____ "
51ZE HOLE ___ "
51ZE CASING ___ "
Annulur Volume ___ f
Cement ___ s
Volume ___ f

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON FIELD OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of

Re: Permanent Abandonment

Intention to Abandon:

Well: 297 Horseshue Gallup Unit

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:

Office Hours: 7:45 a.m. to 4:30 p.m.