

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

I-22-Ind-2772

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Ute Mountain Tribe of
Indians

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Barker Dome

9. WELL NO.

16

10. FIELD AND POOL, OR WILDCAT

Barker Creek Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREASec. 20, T-32N, R-14E,
N.M.P.M.

12. COUNTY OR PARISH 13. STATE

San Juan

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

Southern Union Production Company

3. ADDRESS OF OPERATOR

P. O. Box 808, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

330 ft. from the South line and 990 ft. from the East line.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6082 ft. D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

The well was plugged and abandoned as follows:

1. Set cement plug over Dakota formation from total depth of 2275 ft. to 1900 ft. using 50 sacks of cement. Job complete 9:00 A.M. April 8, 1970.
2. Set 6 sack cement plug in 5-1/2" casing from 400 to 450 ft. Job complete 10:00 A.M. April 8, 1970.
3. Perforated 2 holes in 5-1/2" casing at 220 ft. Cemented thru holes with 115 sacks of cement. Displaced casing down to 120 ft. leaving 100 ft. of cement above perforations. Job complete 2:00 P.M. April 8, 1970.
4. Set 5 sack cement plug in top of casing from 35 ft. to surface.
5. All intervals between plugs filled with 9.0#/gal. mud.
6. All 5-1/2" casing was left in the well.
7. Erected dry hole marker.
8. Well plugged and abandoned April 8, 1970.

18. I hereby certify that the foregoing is true and correct
Original signed by

SIGNED GILBERT D. NOLAND, JR.

TITLE Drilling Superintendent

DATE June 16, 1970

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

RECEIVED

JUN 18 1970

U. S. GEOLOGICAL SURVEY
DURANGO COLO

APPROVED

JUN 19 1970

E. A. SCHMIDT
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side