A-PLUS WELL SERVICE, INC.

"P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211 ORIGINAL

August 18, 2004

New Mexico Oil Conservation Division Aztec District

1000 Rio Brazos Road Aztec, NM 87410

Invoice #3425

1 of 2

Rig #9

For the plug and abandonment of the HSGU #65, a Gallup well located in Section 33, T-31-N, R-16-W, San Juan County, NM. API #30-045-10136 This work done under NMOCD PA: 41-521-07-00028; Purchase Doc.: 04-199-000613.

Cost Summary:

- JJ3L	Sullilliai y	•					
_ID#	Date	Item Description	Units	U	nit Cost	Е	extension
Worl	kover Rig	, Travel and Supervision:					
A1	8/16/04	Contractors Supervisor / Cementer	1.0	\$	250.00	\$	250.00
A1	8/17/04	Contractors Supervisor / Cementer	1.0	\$	250.00	\$	250.00
A2	8/16/04	Crew travel, round trip	2.0	\$	112.00	\$	224.00
A2	8/17/04	Crew travel, round trip	2.0	\$	112.00	\$	224.00
А3	8/16/04	Shallow Rig	7.5	\$	140.00	\$	1,050.00
А3	8/17/04	Shallow Rig	6.75	\$	140.00	\$	945.00
Cem	enting Se	rvices:					
B1	8/16/04	Cementing equipment on location	1.0	\$	450.00	\$	450.00
B1	8/17/04	Cementing equipment on location	1.0	\$	450.00	\$	450.00
B 3	8/17/04	Cement, plugs, 78 sxs Type III = 87.3 Type II	87.3	\$	10.50	\$	916.65
B 3	8/17/04	Cement, marker, 7 sxs Type III = 7.8 Type II	7.8	\$	10.50	\$	81.90
Wire	line Servi	ces:				•	
C1	8/17/04	Wireline unit on location, used	1.0	\$	250.00	\$	250.00
C3	8/17/04	Perforate squeeze holes at 153	1.0	\$	300.00	\$	300.00
Pack	ers, Retai	iners & Casing Scrapers:					
D3	8/16/04	T 00000000 1000 000 0000 0000 0000 0000	1.0	\$	900.00	\$	900.00
D4	8/16/04	Casing scraper rental, 4-1/2"	1.0	\$	250.00	\$	250.00
Work	strings &	Miscellaneous Rentals:		•		*	
E1.1	8/16/04	Workstring rental, 2-3/8, feet	1049	\$	0.12	\$	125.88
E6.3	8/16/04	Companion flange rental, 4-1/2"	1.0	\$	50.00	\$	50.00
E14	8/16/04	Waste fluid container, days used	2.0	\$	30.00	\$	60.00
						•	

A-PLUS WELL SERVICE, INC.

ORIGINAL

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211

August 18, 2004

New Mexico Oil Conservation Division

2 of 2

Aztec District

Invoice #3425

Rig #9

Aztec, NM 87410

1000 Rio Brazos Road

For the plug and abandonment of the HSGU #65, a Gallup well located in Section 33, T-31-N, R-16-W, San Juan County, NM. API #30-045-10136 This work done under NMOCD PA: 41-521-07-00028; Purchase Doc.: 04-199-000613.

Cost Summary:

ID#	Date	Item Description	Units	U	nit Cost	ı	Extension
Trans	sportatio	n and Miscellaneous Services:					
F1.a	8/16/04	Unit #141, Haul waste pit # 525 and workstring	2.0	\$	74.00	\$	148.00
F1.b	8/17/04	Unit #141, Move workstring into position	2.0	\$	74.00	\$	148.00
F4	8/16/04	Float #99, Hold tubing workstring;	2.0	\$	15.00	\$	30.00
F1.c	8/18/04	Unit #152, haul waste pit to land farm	1.25	\$	74.00	\$	92.50
F2.c	8/18/04	Helper for above	1.25	\$	22.00	\$	27.50
F3.a	8/17/04	Tower Report #22896, Unit #19, haul tubing;	1.00	\$	50.00	\$	50.00
F6.a	8/16/04	Unit #134, Haul 1 load of water to location	2.0	\$	50.00	\$	100.00
F6.b	8/17/04	Unit #134, Haul 1 load of water to location	2.0	\$	50.00	\$	100.00
F6.c	8/16/04	Unit #155, Haul / hold waste water from steel pit	2.0	\$	50.00	\$	100.00
F6.d	8/17/04	Unit #155, Haul / hold waste water from steel pit	2.0	\$	50.00	\$	100.00
- 44	0/47/04						
F11	8/17/04	P&A marker, purchase	1.0	\$	120.00	\$	120.00
Third	l Party Se	rvices:					
G1	8/18/04	Industrial Ecosystems, Inv #4310	1.0	\$	27.00		
		land farm solid material from steel pit				•	
			Total	\$	27.00		
		Third Party Handling Charge	8%	\$	2.16	. \$	29.16
Salva	age Credit						
S1	Salvage, 2	2-3/8" EUE tubing, 36 joints	1116	\$	1.20	\$	(1,339.20)
				TO	TAL	\$	6,483.39
			TAX		3750%	\$	413.32

THANK YOU

TOTAL DUE \$ 6,896.71

ok for layment Charle There

submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



Sundry Notices and Reports on Wells

			•
		5.	Lease Number BIA #14-20-603-734
	pe of Well	6.	If Indian, All. or Tribe Name Navajo
		7.	Unit Agreement Name
	me of Operator		Horseshoe Gallup Unit
V	ulcan Minerals and Energy, C/O NMOCD	0	
3 Δα	dress & Phone No. of Operator	8.	Well Name & Number HSGU #65
	000 Rio Brazos Road, Aztec, NM 87410 505-334-6178	9.	API Well No.
		-	30-045-10136
4. Lo	cation of Well, Footage, Sec., T, R, M	10.	Field and Pool
	000/ FOL and 000/ FIME Operation 00 T 04 N. D. 40 M.	4.4	Horseshoe Gallup Unit
1	980' FSL and 386' FWL, Section 33, T-31-N, R-16-W,	11.	County & State San Juan County, NM
			San Juan County, NW
12. CH	ECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT	, OTHER D	ATA
	pe of Submission Type of Action		
	Notice of Intent X Abandonment Change of Plan		
	Recompletion New Construct		
	X Subsequent Report Plugging Back Non-Routine F		
	Casing Repair Water Shut off Altering Casing Conversion to		
	Other -	injection	
13. De	scribe Proposed or Completed Operations		
	A-Plus Well Service Plugged and Abandoned the above well NMS		
	Purchase Agreement: 04-521-0700028; Purchase Document: 04-19	99-000613.	
8/16/04	MOL and RU. Relief line to steel pit. ND wellhead. Release packer. Notest. TOH and LD 36 joints 2-3/8" tubing and 4-1/2" packer. PU 33 joint 4-1/2" casing scraper to 1049'. TIH with tubing and 4-1/2" DHS cement related to the steel pit. ND wellhead. Release packer. Notes and 4-1/2" packer. PU 33 joint 4-1/2" casing scraper to 1049'. TIH with tubing and 4-1/2" DHS cement related to the steel pit. ND wellhead. Release packer. Notes and 4-1/2" packer. PU 33 joint 4-1/2" casing scraper to 1049'. TIH with tubing and 4-1/2" DHS cement related to the steel pit. ND wellhead. Release packer. Notes and 4-1/2" packer. PU 33 joint 4-1/2" casing scraper to 1049'. TIH with tubing and 4-1/2" DHS cement related to the steel pit.	its A+ works	string and round-trip
8/17/04 SIGN	No pressure. Set CR at 1049'. Sting out of retainer. Establish circulation of water. Pump an additional 14 bbls of water to circulate well clean. If Sting into CR. Inject fluid from pit below CR and displace. Sting out of Type III cement (34 cf) from 1049' to 673' to isolate the Gallup interval. The squeeze holes at 153'. Establish circulation out bradenhead with 1/2 bbls of water to circulate BH annulus clean. Plug #2 with 52 sxs Type III 1/2" casing from 153' to surface, circulate good cement out bradenhead wellhead. Found cement at surface in casing and down 1' in annulus, and install P&A marker. H. Villanueva, NMOCD; W. Ashley, Navajo Minerals; V. Euintillie, Navajo J. Walker, U.S. EPA; and L. Lee, Navajo EPA; were on location. ATURE Milliam F. Clark	Pressure tes f retainer. F OH and LD bl of water. Il cement (69 . ND BOP. Mix 7 sxs of Minerals;	t to 500#; held OK. Plug #1 spot 26 sxs tubing. Perforate 2 Pump additional 9 9 cf) pump down 4- Dig out and cut off
(This s	pace for Federal or State Office use)	·	
APPRO	OVED BY Title		Date
COND	TION OF APPROVAL, if any:		

A - PLUS WELL SERVICE P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

	#a	
Rig No_		

Date 08/16/04 Day MON

Well Name HORSESHOE GALLUP UNIT # 65

COMPANY PLAYA MINERALS & ENERGY

FROM	то	DESCRIPTION OF OPERATION
5:30	5:45	LOAD RIG SUPPLIES
5:45	6:45	TRAVEL TO RIG. (MGH #66)
6:45	8:30	REPAIR AXLES ON RIGES
8:30	9:00	START RIG AND EQUIPMENT, HELD PRE-JOB SAFETY MEETING.
9:00	10:00	ROAD RIL AND EQUIPMENT TO LOCATION.
10:00	11:00	SPOT RIC. RIG UP.
11:00	11:30	NIPPLE UP FLOWLINES TO PIT. BLED WELL DOWN
11:30		MIGPLE DOWN WELLHEAD.
	12:00	RELEASE PACKER.
12:00	1:00	NIPPLE UP BOD/ COMPANION FLANCE. TEST RAMS.
1:00	1:45	LAY DOWN TBG. 36 JTS 23/8"EUE TBC AND 42" AD-1 PACKER
1:45		PICK UP AND THY 41/2" CSC SCRAPER AND 33 JTS 27/8"A-PLUS
	2:30	WORK STRING FOT @ 1049
2:30	3:15	TOH / TBC AND SCRAPER
3:15	4	TIH/ 41/2" DHS CRT AND TRG
	4:00	SECURE WELL
4:00	5:00	TRAVEL TO YARD
	-	
-		
	-	
<u> </u>		rew of
		<i>F</i> /
		Playe
	-	1049 1bg
		Newstern 1
		HENRY YILLANGEVA / MMOCD
		WALLACE ASHLEY / NAVAJO MINERALS ON
		LEROY LEE / NAVASO EPA LOCATION

F١	ıel	ጲ	Motor	Oil	

Water Hauled

Cementing Ouc

Wireline

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	MIKE HIGDON	[#] 21		
Operator	TRAVIS BEGAY	#19	1,	11.5
Helper	LORENZO RODRIGUEZ		***************************************	11.5
Helper	ADAN REYES			11.5
Helper	CHRIS MONTANEZ			11.5
Trainee				1112

P.O. BOX 1979 • FARMINGTON, NM 87499 505-325-2627 • FAX (505) 325-1211

Rig No_	#9	Date <u>08/17/04</u> Day TUE ,
Well Nam	ne Hors	SHOE GALLUP UNIT \$65 COMPANY PLAYA MINERALS & ENERCY
FROM	то	DESCRIPTION OF OPERATION
5:30	5:45	104) 311 61.001.

5:45 6:45 TRAVEL TO LOCATION 6:45 7:15 START RIL AND EQUIPMENT. HELD PRE-JOB SAFETY MERTING 7:15 OPEN WELL (NO PRESSURE) SET CRT @ 1049'. STING ONT. LOAD HOLE / 3 BBLS WATER TO CIRCULATE. CIRCULATE CLEAN/AN ADDITIONAL 14 BBLS WATER. PRESSURE 8:00 TEST CSC TO 500 PSI. HELD PRESSURE 5 MIN. NO PRESSURE LOSS STING IN TO CRT, INISECT FLUID FROM PIT BELOW CRT, DISPLACE! 8:00 FRESH WATER. STING OUT. 9:00 PLUC #1 - MIX AND PUMP 26 5x5 (39.32 FT3) (AT FROM 1049' TO TOCA 9:00 9:30 673' DISPLACE 9:30 19:15 LAY DOWN THE AND STINGER. 19:15 RIC UP WIRELINE, RIH/WIRELINE, PERFORATE/2-11/12" BI-WIRE SHOTS @ 153'. POH/WIRELINE. RIL DOWN WIRELINE 19:30 PUMP 1/2 BBL WATER DOWN CSC TO CIRCULATE OUT BRADENHEAD 19:30 CIRCULATE CLEAN / AN ADDITIONAL 91/2 BOLS WATER 10:45 PLUC = 2 - MIX AND PUMP 52 5x5 (6869 FT3) 19.7 DOWN CSC 19:45 11:15 TU CIRCULATE COOR CANT OUT BRADENHEAD. 11:15 NIPPLE DOWN BOP. 11:45 11:45 DIG OUT AND CUT OFF WELLHEAD CMT (SURFACE IN 41/2" PLACE PLA MARKER/ 1:00 CMT @ 1' /N 85/8" csc 1:00 2:30 RIL DOWN. CHT OFF RIL ANCHORS TRAVEL TO HGU" 26, LOAD TRG. TRAVEL TO YARD / FLOAT "87 2:30 4:30 HENRY VILLANDEVA/NMOCD VAL ELINTILLIE / NAVAJO MINERALS ON LEROY LER / NAVASO EPA LOCATION JIM WALKER / US EPA

1 h F3.

& Motor Oil Rental Equipment

Water Hauled

Cement Retainers

Cementing PLuc*1-26 sxs PLuc*2-52 sx5 Wireline 2-1"/6" BI-WIRE SHOTS @ 153'(5,5,)

PHA MARKER

CREW	NAME	UNIT #	MILEAGE	HOURS
Supervisor	WIKE HICDON	12/		
Operator	TRAVIS BEGAY #221 IN AND FILL	#19		13.5
Helper 	LURENZO RODRIGUEZ \$17 TO YARD			11.0
Helper	ADAN REYES		· · · · · · · · · · · · · · · · · · ·	11.0
lelper	CHRIS MONTANEZ			11.0
Trainee				1110

RCI Form - 0801114A

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Date:	Tr	uck #: <u>/4/</u>	
Event: #1	From: HGu # 66 To: HGu #65	Hours	/11
Start:	What: HAUL FLOAT *98 AND PIT *525		1 / 1
8/16/04	STANDBY		U /
Stop:	Charge to: NMOCD	2.0	
Event: #2	From: 146u # 65 To:		/-1h
Start:	What: STANARY RIG UP TRUCK		1610
8/17/04 Stop:			(//
Stop:	Charge to: NMOCD	2.0	
Event: #3	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #4	From: To:		
Start:	What:		
Ctom	Charmatan		
Stop:	Charge to:		
Event: #5	From: To:		
Start:	What:		
Stoni	Charge to:		
Stop:	Charge to:		
Event: #6	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #7	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #8	From: To:		
Start:	What:		
Stop:	Charge to:		
	Driver: ANIKE HIGDOM	4.0	
Diesel:	Helper	1.0	
Oil:	NM MILES: CO MILES: UT MILES:		
Remarks:			
Nemarks.			- 1
	F11 FL # #99		FY
	1-9/102/1/		/ /
	P. 10		
	flentul		

A-Plus Well Service, Inc.P.O. Box 1979, Farmington, NM 87499
505-325-2627

Date: <u>8-78</u>	*-ov Truck #	: 152	_
Event: #1	From: 1 P d	Hours	7
Start: 5:30	What: SAFETY MEETING	/	1
Stop: 6, 30	Charge to: $A - P - \omega$		
Event: #2	From: p-P-W TO: NSGU#65, 66, 1 What: DRIVE TO LOCATION LONG STEEL PIT #535 5 CHAW CONN	C 3 C	
Start: 6.30	What: DRIVE TO LOCATION LOSS STORY FOR TOS	7.59	1
	5. CHAW COND	- + 4	1/ /2:
Stop: 8,30	Charge to:		4/2h
Event: #3	From: 4560 #65 To: 7 FI		1
Start: B,30	What: Office To Town. IEI & CUMP STOOL &	12 3.5	
Stop: (LOC)	Charge to: NM OC G		
etop: //.CD			
Event: #4	From: A-P-W To: WART OLL & GAS		
Start: ' ()()	What: Talle STEEL PIT 525 OUT TO LOCATION &	Orgo	
Stop: 3:30	DRIVE 10, LOG ELOAD TANK 308 TAKE TO LAND	TCT8 4.5	
Stop. 3.5()	Charge to: HART Oil & Gas		
Event: #5	From: D-PW To: BOUNCK B#1		
Start: ろ、ろつ	What: LONG STEEL POT #515 DRIVE TO LOSATION	5	
Stop: 5,36	ELNEDAD DRIVE BACK TO YARD		
3,38	Charge to: X70		
Event: #6	From: To:		
Start:	What:		
Stop:	Charge to:		
Event: #7	From: To:		
Start:	What:		
Stop:	Charge to:		
	Charge to.		(2)
Event: #8	From: To:		1417
Start:	What:		(H/)
Stop:	Charge to:		
отор.	Charge to:		
	Delicera	- 	
Diesel:	Helper	12	- 1.4
Oil:	NM MILES: CO MILES: UT MILES:	12	175
			1.25 hr
Remarks:	148 HWY 120 DIRT		
	Nmcco 45601 # 65		74
	Take worte pit to IEI		(co C)
·			1267
-	and Unload, letum to gare	/	(')
		RCI Form - 080158A	1.25 hrs
		0 / 22	/· = -

A-Plus Well Service, Inc.

P.O. Box 1979, Farmington, NM 87499 505-325-2627

Event: #1	From: 1464 # 66 To: 1464 # 65	Hours
Start:	What: HAUL I LOAD FRESH WATER	
8/16/04	STANDBY	
Stop:	Charge to: NMOCD	2, 0
Event: #2	From: 1164 # 65 To:	
Start:	What: HAUL I LOAD FRESH WATER	
8/17/04	STANOBY	
Stop:	Charge to: NMOCD	2.0
Event: #3	From: To:	
Start:	What:	
Stop:	Charge to:	
vent: #4	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #5	From: To:	
Start:	What:	
Stop:	Charge to:	
vent: #6	From: To:	
tart:	What:	
stop:	Charge to:	
vent: #7	From: To:	
Start:	What:	
Stop:	Charge to:	
vent: #8	From: To:	
tart:	What:	
top:	Charge to:	
	Driver: MIKE HIGDON	4.0
iesel:	Helper	
il:	NM MILES: CO MILES: UT MILES:	
lemarks:		

A-Plus Well Service, Inc.P.O. Box 1979, Farmington, NM 87499
.505-325-2627

Date:	# : Truck ** Truck ** Truck is the properties and a control of the properties of th	<u> 755</u>
Event: #1	From: HGy #66 To: HGy #65	Hours
Start:	What: STANDBY FOR DISPOSAL	
8/16/04		
Stop:	Charge to: へんのこう	2.0
Event: #2	From: H64 #65 To:	
Start:	What: STANDBY FOR DISPOSAL	
8/17/04		
Stop:	Charge to: NMOCD	2.0
Event: #3	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #4	From: To:	<u> </u>
Start:	What:	
		
Stop:	Charge to:	
Event: #5	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #6	From: To:	
Start:	What:	
Stop:	Charge to:	
Event: #7	From: To:	
Start:	What:	
_		
Stop:	Charge to:	· .
Event: #8	From: To:	
Start:	What:	
Stop:	Charge to:	
	Driver: MIKE HIGDON	4.0
Diesel:	Helper	1.0
Oil:	NM MILES: CO MILES: UT MILES:	
B1		
Remarks:		



AUG 2 0 2004

Invoice Number: 4310

Invoice Date:

Aug 20, 2004

Page:

4

Industrial Ecosystems Inc.

P.O. Box 2043

Farmington, NM 87499

PH: (505) 632-1782

Fax: (505) 632-1876

TAX I.D. #94-3200034

PLEASE REMIT PAYMENT TO:

Industrial Ecosystems, Inc.

c/o John J. Kiely

401 S. Lasalle St., Suite 606

Chicago, Illinois 60605

Sold To: A PLUS WELL SERVICE

PO BOX 1979

FARMINGTON, NM 87499

Location: WILLIAM F CLARK HSGU#66,65,19,32

23

Contact			
Contact	Payment Terms	Due Date	Customer PO
WILLIAM F CLARK	Net 30 Days	9/19/04	

Quantity	Description	Unit	Price	Extension
	DATE OF SERVICE: 08/18/04		i	
	MATERIAL TRANSPORTED BY: APLUS WELL SERVICE - TRUCK#152			
	DISPOSED OF CEMENT			
6.00	DISPOSAL FEE PER YARD		18.00	108.
				- 4
	6-1			#
	0 /			= 27 = 20 Wel
ļ				In Wel
		!		
			,	

FOR BILLING INQUIRIES PLEASE CALL (505) 632-1782

ACCOUNTS ARE DUE NET 30 DAYS, PURCHASER AGREES TO PAY FINANCE CHARGES OF 1.5% PER MONTH (ANNUAL PERCENTAGE RATE OF 18%) OR A MINIMUM CHARGE OF .50 PER MONTH. ACCOUNTS THAT HAVE BEEN PLACED FOR COLLECTION WILL BE CHARGED A \$100.00 COLLECTION FEE IN ADDITION TO REASONABLE ATTORNEY FEES AND COLLECTION CHARGES.

Subtotal Sales Tax

Total Invoice Amount

108.00

108.00

TOTAL

108.00

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979 FARMINGTON, NM 87499 505-325-2627 • FAX: 505-325-1211



August 31, 2004

CAVE Enterprises

PO Box 79 Flora Vista, NM 87415

Invoice #3440

Rig #9

For used tubing from **Horseshoe Gallup Unit** wells, located in T31N, R16W, San Juan County, NM.

This material was credited to NMOCD on the appropriate invoice.

Cost Summary:

	HSGU Well	<u> Feet</u>	Type and Siz	ze	V	alue	Salvage
	#26	1302	42 joints 2-3/8" tubing		\$	1.20	\$ 1,562.40
_	#65	1116	36 joints 2-3/8" tubing		\$	1.20	\$ 1,339.20
_							\$ 2,901.60
	NM TAX Exempt - Resale						

THANK YOU

TOTAL DUE \$ 2,901.60