

RECEIVED

Form 3160- 5  
(August 2007)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

JUN 16 2011

FORM APPROVED  
OMB No 1004-0137  
Expires July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.***SUBMIT IN TRIPLICATE - Other Instructions on page 2.**

## 1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

## 2. Name of Operator

**Black Hills Gas Resources**

## 3a. Address

**3200 N 1st Street Bloomfield, NM 87413**

## 3b. Phone No. (include area code)

**(505) 634-1111**

## 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

**1640 FNL 545 FWL SW/NW (Unit E) Section 27 T29N R2W**

## 5. Lease Serial No.

**MDA 701-98-0013, Tract 2**

## 6. If Indian, Allottee, or Tribe Name

**Jicarilla Apache Tribe**

## 7. If Unit or CA. Agreement Name and/or No

## 8. Well Name and No

**Jicarilla 29-02-27 #21**

## 9. API Well No

**30-039-29397**

## 10. Field and Pool, or Exploratory Area

**East Blanco Pictured Cliffs**

## 11. County or Parish, State

**Rio Arriba, New Mexico***Burro Canyon  
Tertiary*

## 12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input checked="" type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation Clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notice shall be filed only after all requirements, including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

**Black Hills Gas Resources repaired downhole pump and returned the referenced well to production May 17, 2011.**

14. I hereby certify that the foregoing is true and correct Name (Printed/ Typed)

**Daniel Manus****Regulatory Technician**

Title

Signature

Date

**6-16-2011****ACCEPTED FOR RECORD****THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

**JUN 16 2011**

Conditions of approval, if any are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon

Office

**FARMINGTON FIELD OFFICE**  
**BY** *[Signature]*

Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

**NMOCD** *A*