Form 3160-5 (February 2005)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR

JUN 07 2011

FORM APPROVED OMB No 1004-0137 Expires: March 31, 2007

BUREAU OF LAND MANAGEMENT 5 Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELL'Sirmington Field Unisp-078777 Do not use this form for proposals to drill or to revente panand Mana 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7 If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. Rosa 1. Type of Well 8. Well Name and No. Rosa 399A Oil Well Gas Well Other 2. Name of Operator 9. API Well No. Williams Production Company, LLC 30-039-30503 3a. Address 3b Phone No (include area code) 10. Field and Pool or Exploratory Area PO Box 640 Aztec, NM 87410 505-634-4206 Basin Fruitland Coal 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State 1035' FSL & 1025' FEL, section 31, T31N, R4W Rio Arriba 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deepen Production (Start/Resume) Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Other Recomplete Subsequent Report FINAL Change Plans Plug and Abandon Temporarily Abandon CASING/LINER Convert to Final Abandonment Notice Plug Back Water Disposal Injection 13. Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection) 5/25/11- SET WHIPSTOCK ACCEPTED FOR RECORD 5/26/11- MILL WINDOW 3135'-3148' JUN 1 3 2011 5/27/11-5/31/11- BUILD CURVE AND DRILL 6-1/4" LATERAL FARMINGTON FIELD OFFICE 6/1/11- TD 6-1/4" PROD HOLE @ 6200, 0730 HRS RAN 73 JTS, 4-1/2", ,J-55, 11.6#, LT & C, CSG SET @ 6164 MD', TOL @ 3151' 72 pre perf its & 1-blank on top. total=3013' landed @ 6164. NO CEMENT 6/2/11- TOH WITH WHIPSTOCK, SET RBP @ 1578' DRILLING RIG RELEASED ON 6/3/11 @ 0900 HRS 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Larry Higgins Title Permit Supervisor Signature Date 6/7/11 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the

which would entitle the applicant to conduct operations thereon.