Form 3160-5 (April 2004)

RECEIVED **UNITED STATES**

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

AUG 09 2011

FORM APPROVED OM B No 1004-0137 Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

5 Lease Serial No NM-052931

SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well □ □ □ Gas Well □ □ Other			ide. 7. I	7. If Unit or CA/Agreement, Name and/or No. 8 Well Name and No.	
Name of Operator Nacogdoches	Oil & Gas Inc.			9. API Well No.	
3a Address 3b. Ph		3b. Phone No. (include area of 936-560-4747	- July	30-031-20850 Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T, R, M., or Survey Description)			L	Hospah	
660 FSL & 330' FWL Section 6 17N 8W			J	County or Parish, State McKinley County, New Mexico	
12. CHECK AP	PPROPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPOR	T, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF	ACTION		
If the proposal is to deepen direc Attach the Bond under which the following completion of the invo- testing has been completed. Find determined that the site is ready if	tionally or recomplete horizontally, e work will be performed or provide olved operations If the operation real al Abandonment Notices shall be fil	Fracture Treat New Construction Plug and Abandon Plug Back Int details, including estimated signer subsurface locations and in the Bond No on file with BLI sults in a multiple completion of ed only after all requirements, in triand @ 15.1 ppg for bottom.	neasured and true vertic M/BIA Required subset r recompletion in a new including reclamation, his om plug.	Well Integrity Other Dosed work and approximate duration thereof all depths of all pertinent markers and zones. Equent reports shall be filed within 30 days unterval, a Form 3160-4 shall be filed once are been completed, and the operator has	
7-7-11- RIH with WS, tag c	ement at 142'. Mix and Pump 2			SO RECEIVED AUG 20 AUG	
7-7-11- RIH with WS, tag con 7-8-11- Mix and Pump 6 Sk	ts to top off casing and annulus	Cut off casing and place P	&A Marker.	RECEIVE AUG 20 CONS. DIV. I	
7-7-11- RIH with WS, tag of 7-8-11- Mix and Pump 6 Sk	ts to top off casing and annulus		&A Marker.	SECENT LEOE 62 82	
7-7-11- RIH with WS, tag con 7-8-11- Mix and Pump 6 Sk	ts to top off casing and annulus	Cut off casing and place P	&A Marker.		
7-7-11- RIH with WS, tag of 7-8-11- Mix and Pump 6 Sk	ts to top off casing and annulus	Cut off casing and place P Title Engineer	&A Marker. ing 08/08/20		
7-7-11- RIH with WS, tag of 7-8-11- Mix and Pump 6 Sk	oing is true and correct	Cut off casing and place P Title Engineer	&A Marker. ing 08/08/20	11 0E6Z83	

(Instructions on page 2)

which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction