Form 3160-5 (February 2005)

RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR 30 2011 BUREAU OF LAND MANAGEMEN 30

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 200

Expires: March 31, 2007 SUNDRY NOTICES AND REPORTS ON WELLIS and Management Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (ABD) for 5 Lease Serial No NMSF-078770 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. Rosa Unit 1 Type of Well 8. Well Name and No Rosa 322A Oil Well Gas Well Other 2 Name of Operator 9. API Well No. Williams Production Company, LLC 30-039-29290 10. Field and Pool or Exploratory Area 3a. Address 3b Phone No. (include area code) PO Box 640 Basın Fruitland Coal Aztec, NM 87410 505-634-4206 4 Location of Well (Footage. Sec., T.,R,M., or Survey Description) 11. Country or Parish, State Surface: 1945' FNL & 600' FWL - SEC. 23 T31N, R05W Rio Arriba, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other Subsequent Report Resume Production Change Plans Plug and Abandon Temporarily Abandon Convert to Final Abandonment Notice Plug Back Water Disposal

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The Rosa 322A FRT was inactive for a period greater than 90 days, the well resumed production on July 21, 2011.

		365678910172233
		RECEIVED ঠু
	93031	RECEIVED STORY OIL CONS DIV DIST.
14 I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	िंद	2 00/
Ben Mitchell	Title Regulatory Specialist	(29>0 -1/1/10)
Signature B Mill	Date 8/30/2011	PEDESTILITIES
THIS SPACE FOR FEDERA	AL OR STATE OFFICE USE	ACCEPTED FOR RECORD
Approved by		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Title	Date AIIG 3 N 2011
Conditions of approval, if any, are attached Approval of this notice does not warran certify that the applicant holds legal or equitable title to those rights in the subject leads which would entitle the applicant to conduct operations thereon.	• • • • • • • • • • • • • • • • • • •	FARMINGTON FEILD OFFICE
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for a United States any false, fictitious or fraudulent statements or representations as to a		y department or agency of the

(Instructions on page 2)