Submit 1 Copy To Appropriate D	hstrict	State of New Mexic	o		orm C-103
Office <u>District I</u> – (575) 393-6161	Energy,	Minerals and Natural	Resources		ugust 1, 2011
1625 N French Dr., Hobbs, NM	88240			WELL API NO.	
District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			 	30-039-29585	
District III - (505) 334-6178	5. 61., 11.16314, 11.11 (62.10		Dr.	5. Indicate Type of Lease STATE FEE	X
1000 Rio Brazos Rd , Aztec, NM	87410	Santa Fe, NM 8750	_	STATE FEE 6. State Oil & Gas Lease No.	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe,	NM	Sunta 1 0, 1 (1/1 0 / 5 0		o. State Off & Gas Lease No.	
87505					
SUNDRY NOTICES AND REPORTS ON WELLS				Lease Name or Unit Agreen	nent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				El Poso	
PROPOSALS.)	E ATTEICATION FORTE	dwit (roidw c-tot) roids	_		
1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other			+	8. Well Number 5	
2. Name of Operator				9. OGRID Number	
BLUE DOLPHIN PRODUCTION, LLC				226829	
3. Address of Operator				10. Pool name or Wildcat	
609 S. Kelly, Suite F-1, Ed	lmond, OK 73003			WC El Poso Greenhorn	
4. Well Location			5		
Unit LetterD	:550fee	et from theNorth	_ line and975'	feet from the _West	line
Section 23	To	ownship 28N Ra	nge 1E	NMPM Rio Arriba C	ounty
		n (Show whether DR, RK			
	7104' GL				
-					
12. (Check Appropriate	Box to Indicate Natu	re of Notice. R	eport or Other Data	
			10 01 1 (0 1100), 1	oport of other batta	
NOTICE	OF INTENTION	TO:	SUBS	EQUENT REPORT OF	•
			EMEDIAL WORK	☐ ALTERING (CASING 🗌
TEMPORARILY ABANDO	N 🗌 CHANGE PI	LANS 🗌 C	OMMENCE DRIL	_ING OPNS.□ P AND A	\mathbf{X}
PULL OR ALTER CASING	MULTIPLE (COMPL C	ASING/CEMENT	JOB 🗌	
DOMESTICAL COMMISSION	EΠ				
DOWNHOLE COMMINGL					
·		_			
OTHER:			THER:		
OTHER: 13. Describe proposed	or completed operation	ns. (Clearly state all pert	inent details, and	give pertinent dates, including of	estimated date
OTHER: 13. Describe proposed of starting any pro	or completed operation posed work). SEE RUI	ns. (Clearly state all pert	inent details, and	give pertinent dates, including obletions: Attach wellbore diagr	estimated date am of
OTHER: 13. Describe proposed of starting any pro	or completed operation	ns. (Clearly state all pert	inent details, and	give pertinent dates, including en pletions: Attach wellbore diagr	estimated date am of
OTHER: 13. Describe proposed of starting any pro	or completed operation posed work). SEE RUI	ns. (Clearly state all pert	inent details, and	give pertinent dates, including en pletions: Attach wellbore diagr	estimated date am of
OTHER: 13. Describe proposed of starting any proposed completion	or completed operation posed work). SEE RUI on or recompletion.	ns. (Clearly state all pert LE 19.15.7.14 NMAC. I	inent details, and	give pertinent dates, including en pletions: Attach wellbore diagr	estimated date am of
OTHER: 13. Describe proposed of starting any proposed completion. Blue Dolphin plugged and a	or completed operation posed work). SEE RUI on or recompletion.	ns. (Clearly state all pert LE 19.15.7.14 NMAC. In the state of the st	inent details, and For Multiple Com	give pertinent dates, including en pletions: Attach wellbore diagr	estimated date am of
OTHER: 13. Describe proposed of starting any proposed completion	or completed operation posed work). SEE RUI on or recompletion.	ns. (Clearly state all pert LE 19.15.7.14 NMAC. In the state of the st	inent details, and For Multiple Com	give pertinent dates, including e pletions: Attach wellbore diagr	estimated date am of
OTHER: 13. Describe proposed of starting any proposed completion Blue Dolphin plugged and a 10/3/11 Discovered a CIBP	or completed operation posed work). SEE RUI on or recompletion. abandoned this well as fat 1400'. Notified Mr.	ns. (Clearly state all pert LE 19.15.7.14 NMAC. In follows: Powell at NMOCD for c	inent details, and For Multiple Com	pletions: Attach wellbore diagr	am of
OTHER: 13. Describe proposed of starting any proposed completion Blue Dolphin plugged and a 10/3/11 Discovered a CIBP	or completed operation posed work). SEE RUI on or recompletion. abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71	ns. (Clearly state all pert LE 19.15.7.14 NMAC. In follows: Powell at NMOCD for control of the state of the s	inent details, and For Multiple Com change of plans.	pletions: Attach wellbore diagrent with 3% $CaCl_2$ and 25# of contract with 3% $CaCl_2$ and 30 $CaCl_2$ and 30 $CaCl_2$	am of elloflake in
OTHER: 13. Describe proposed of starting any proposed completion Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour	or completed operation posed work). SEE RUI on or recompletion. abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at	ns. (Clearly state all pert LE 19.15.7.14 NMAC. In follows: Powell at NMOCD for co 1' with 86 sx (101.5 cu.fort 1761'. Loaded the hole a	inent details, and For Multiple Com change of plans. t.) of Cl "G" ceme and pressure tested	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proposed completion Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl "	or completed operation posed work). SEE RUI on or recompletion. abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7	ns. (Clearly state all pert LE 19.15.7.14 NMAC. In follows: Powell at NMOCD for control with 86 sx (101.5 cu.f t 761'. Loaded the hole at 49' to 661'. POH to 219	inent details, and For Multiple Community Change of plans. t.) of Cl "G" certourd pressure tested '. Pump 25 sx of Cl	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proposed completion Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl "	or completed operation posed work). SEE RUI on or recompletion. abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Community Change of plans. t.) of Cl "G" certourd pressure tested '. Pump 25 sx of Cl	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proposed completion proposed completion by the proposed and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho	or completed operation posed work). SEE RUI on or recompletion. abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Community Change of plans. t.) of Cl "G" certourd pressure tested '. Pump 25 sx of Cl	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proposed completion proposed completion by the proposed and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Community Change of plans. t.) of Cl "G" certourd pressure tested '. Pump 25 sx of Cl	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proposed completion proposed completion by the proposed and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho	or completed operation posed work). SEE RUI on or recompletion. abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Company Change of plans. t.) of Cl "G" ceme and pressure tested. ' Pump 25 sx of company 25	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proposed completion proposed completion by the proposed and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. I plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Company Change of plans. t.) of Cl "G" ceme and pressure tested. ' Pump 25 sx of company 25	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proposed completion proposed completion by the proposed and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho	or completed operation posed work). SEE RUI on or recompletion. abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subse Plugging) which may be	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Company Change of plans. t.) of Cl "G" ceme and pressure tested. ' Pump 25 sx of company 25	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proproposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP. Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of C1 additional sx of cement. Ho Clean location.	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. I plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms	follows: Powell at NMOCD for control of the total of the	change of plans. t.) of Cl "G" cemend pressure tested. Pump 25 sx of Cl (35.4 cu.ft.) of Cl	ent with 3% CaCl ₂ and 25# of colors to 500 psi – held OK. Spotted	elloflake in a 10 sx (11.8
OTHER: 13. Describe proposed of starting any proposed completion proposed completion by the proposed and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. I plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Company Change of plans. t.) of Cl "G" ceme and pressure tested. ' Pump 25 sx of company 25	ent with 3% CaCl ₂ and 25# of coll to 500 psi – held OK. Spotted tement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proproposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP. Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of C1 additional sx of cement. Ho Clean location.	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. I plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms	follows: Powell at NMOCD for control of the total of the	change of plans. t.) of Cl "G" cemend pressure tested. Pump 25 sx of Cl (35.4 cu.ft.) of Cl	ent with 3% CaCl ₂ and 25# of coll to 500 psi – held OK. Spotted tement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proproposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl "additional sx of cement. Ho Clean location. Spud Date: 8/5/05	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Comparison of Plans. it.) of Cl "G" ceme and pressure tested. Pump 25 sx of Ca (35.4 cu.ft.) of Cl	ent with 3% CaCl ₂ and 25# of coll to 500 psi – held OK. Spotted tement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proproposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP. Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of C1 additional sx of cement. Ho Clean location.	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Comparison of Plans. it.) of Cl "G" ceme and pressure tested. Pump 25 sx of Ca (35.4 cu.ft.) of Cl	ent with 3% CaCl ₂ and 25# of coll to 500 psi – held OK. Spotted tement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proproposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl "additional sx of cement. Ho Clean location. Spud Date: 8/5/05	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Comparison of Plans. it.) of Cl "G" ceme and pressure tested. Pump 25 sx of Ca (35.4 cu.ft.) of Cl	ent with 3% CaCl ₂ and 25# of coll to 500 psi – held OK. Spotted tement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed RECEIV	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proposed completion of starting any proposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three house. Spotted plug of Cl additional sx of cement. How Clean location. Spud Date: 8/5/05	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	change of plans. t.) of Cl "G" ceme and pressure tested. Pump 25 sx of Cl (35.4 cu.ft.) of Cl	ent with 3% CaCl ₂ and 25# of call to 500 psi – held OK. Spotted rement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed RECEIV OL CONS. Diversity of the control	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proproposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl "additional sx of cement. Ho Clean location. Spud Date: 8/5/05	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subser Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	change of plans. t.) of Cl "G" ceme and pressure tested. Pump 25 sx of Cl (35.4 cu.ft.) of Cl	ent with 3% CaCl ₂ and 25# of coll to 500 psi – held OK. Spotted tement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proposed completion proposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho Clean location. Spud Date: 8/5/05 Thereby certify that the information of the start	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subse Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	change of plans. t.) of Cl "G" cemerated pressure tested. Pump 25 sx of Cl (35.4 cu.ft.) of Cl Unknown	ent with 3% CaCl ₂ and 25# of coll to 500 psi – held OK. Spotted tement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed PECEIV OL CONS. Diversity of the collection	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proposed completion of starting any proposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho Clean location. Spud Date: 8/5/05 PAR SIGNATURE Results SIGNATURE Paul Type or print name Paul	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subse Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	change of plans. th.) of Cl "G" ceme and pressure tested. Pump 25 sx of Cl (35.4 cu.ft.) of Cl Unknown Unknown Gray my knowledge Engineer @walsheng.net	ent with 3% CaCl ₂ and 25# of call to 500 psi – held OK. Spotted rement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed PECEIV INCOME. DIVERSITE DATE 10/5/11 PHONE: _(505) 327-4892	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proposed completion proposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho Clean location. Spud Date: 8/5/05 Thereby certify that the information of the start	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subse Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	change of plans. t.) of Cl "G" cemerated pressure tested. Pump 25 sx of Cl (35.4 cu.ft.) of Cl Unknown	ent with 3% CaCl ₂ and 25# of call to 500 psi – held OK. Spotted rement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed PECEIV INCOME. DIVERSITE DATE 10/5/11 PHONE: _(505) 327-4892	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proproposed completion of the starting of t	or completed operation posed work). SEE RUI on or recompletion. Abandoned this well as fat 1400'. Notified Mr. plug from 1370' to 71 rs. Tag top of cement at G' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subse Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	change of plans. th.) of Cl "G" ceme and pressure tested. Pump 25 sx of Cl (35.4 cu.ft.) of Cl Unknown Unknown Gray my knowledge Engineer @walsheng.net	ent with 3% CaCl ₂ and 25# of coll to 500 psi – held OK. Spotted tement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed PECEIV OL CONS. DIVERSITE DATE 10/5/11 PHONE: _(505) 327-4892 Inspector,	elloflake in a 10 sx (11.8 with 5 P&A marker.
OTHER: 13. Describe proposed of starting any proposed completion of starting any proposed completion. Blue Dolphin plugged and a 10/3/11 Discovered a CIBP Spotted a balanced two stages. WOC three hour cu.ft.) balanced plug of Cl additional sx of cement. Ho Clean location. Spud Date: 8/5/05 PAR SIGNATURE Results SIGNATURE Paul Type or print name Paul	or completed operation posed work). SEE RUI on or recompletion. Ibandoned this well as fat 1400'. Notified Mr. I plug from 1370' to 71 rs. Tag top of cement at G'' neat cement from 7 le was staying full. Total Approved for plugging Liability under bond is Receipt of C-103 (Subse Plugging) which may be page under forms www.emnrd.state.us/oc	follows: Powell at NMOCD for control of the total of the	inent details, and For Multiple Com change of plans. t.) of Cl "G" ceme and pressure tested ' Pump 25 sx of C (35.4 cu.ft.) of C Unknown Unknown of my knowledge /Engineer	ent with 3% CaCl ₂ and 25# of call to 500 psi – held OK. Spotted rement. TOH and fill the casing 1 "G" with 3% CaCl ₂ . Installed PECEIV CONS. DIVERS DATE	elloflake in a 10 sx (11.8 with 5 P&A marker.

P&A STATUS

MANCOS - SERFACE

PLUG #3 SURFACE - Z19 30 5x (35,4 cu, ft,) c1 "G" 4/3 ? Caclz

85/10 178

219

661

PLUG #2 661-749 105x(11.8 cu. ft.) C1"G"

PLUG #1 761-1370

865x (101.5 cu. ft)

25 SX CELLO FLAKE

c1"4" w/ 32 Caclet

749 761

986 1006

1016

1636

1068

1088

1110 1140

1150

1160

1370

CIBP @ 1400'

1596

1616

PBTO -1765

5/2" e 1804

GALLUP - 761

SANOSTEE - 1269

CARLISLE - 1352

GREENHORN - 1569

GRANEROS - 1617

Pd 10/5/11