Form 3160-5 (August 2007)

## UNITED STATES

DEPARTMENT	OF	THE	INTERIOR
BUREAU OF LA	ND	MAN	AGEMENT

FORM APPROVED OMB NO 1004-0135 Expires. July 31, 2010 5. Lease Serial No. NMSF078904A

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

abandoned well. Use form 3160-3 (APD) for such		6. If Indian, Allottee of Tribe Name EASTERN NAVAJO				
SUBMIT IN TRIPLICATE - Other instructions on re		7. If Unit or CA/Agreement, Name and/or No. 892000844F				
1 Type of Well ☐ Oil Well ☒ Gas Well ☐ Other	8. Well GAL	8. Well Name and No. GALLEGOS CANYON UNIT 265				
2 Name of Operator Contact. CHERRY H BP AMERICA PRODUCTION CO E-Mail: hlavacl@bp.com		9. API Well No. 30-045-20655-00-S1				
	lo. (include area code) 66.4081	10. Fie BAS	10. Field and Pool, or Exploratory BASIN DAKOTA			
4 Location of Well (Footuge, Sec., T., R., M., or Survey Description)		11. Coi	11. County or Parish, and State			
Sec 25 T28N R12W SESE 0790FSL 0790FEL 36.628080 N Lat, 108.056210 W Lon		SAN	SAN JUAN COUNTY, NM			
12. CHECK APPROPRIATE BOX(ES) TO INDICATE	E NATURE OF N	IOTICE, REPORT,	OR OTHER D	ATA		
TYPE OF SUBMISSION .	TYPE OF ACTION					
Subsequent Report ☐ Casing Repair ☐ Ne ☐ Final Abandonment Notice ☐ Change Plans ☐ Plu	epen acture Treat w Construction ag and Abandon ag Back	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal		Water Shut-Off Well Integrity Other		
13. Describe Proposed or Completed Operation (clearly state all pertinent details, inclusif the proposal is to deepen directionally or recomplete horizontally, give subsurface Attach the Bond under which the work will be performed or provide the Bond No. of following completion of the involved operations. If the operation results in a multiple testing has been completed. Final Abandonment Notices shall be filed only after all determined that the site is ready for final inspection.)  Feb & March Report: Dakota formation is plugged per earlier report 02/06/12 RU Halliburton & Cameron pressure test pmp lines to 250 good. Load tbg w/2% KCL wtr.  02/10/12 Spot equipment; Spot Halliburton frac equipment. Begin F 15% HCL acid flush. Let acid soak on formation. 1# 20/40 Ottowa; 3.5# 20/40 Ottowa; 4# 20/40 Ottowa sand. PAD volume 6350 gal; 1 flush volume 1425 gal. N2 volume 757621 SCF. Got 71% of the said data uploaded to FracFocus when available) CleanUp frac pmps; R 02/11/12 start flowback thru .25" choke.	e locations and measu on file with BLM/BIA ple completion or reco I requirements, includ t.  low & 5000# high Frac job. Load & b 2# 20/40 Ottowa; I# sand thru 3.6# nd placed in Mano	red and true vertical dep. Required subsequent impletion in a new intersing reclamation, have be n; 5 min ea. test  reak 1500 gal of 3# 20/40 Ottowa; sand total 62,000#; cos formation. (frac	ths of all pertinent reports shall be filed val, a Form 3160-4 seen completed, and the RCVD MAR 3  OIL CONS.  DIST.:	narkers and zones. within 30 days hall be filed once he operator has		
14. Thereby certify that the foregoing is true and correct.  Electronic Submission #134097 verific  For BP AMERICA PRODUCTIC  Committed to AFMSS for processing by ST	TEVE MASON on 0	Information System Farmington 3/28/2012 (12SXM123	1 36SE)			
Name (Printed/Typed) CHERRY HLAVA	Title AGENT		·			
Signature (Electronic Submission)	Date 03/28/20	)12				
THIS SPACE FOR FEDERA	AL OR STATE (	OFFICE USE				
Approved By ACCEPTED	STEPHEN TitlePETROLE	MASON JM ENGINEER		Date 03/28/2012		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Farmington				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any pastes any false, fictitious or fraudulent statements or representations as to any matter of the section 1212.	person knowingly and within its jurisdiction.	willfully to make to any	department or agen	cy of the United		

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

## Additional data for EC transaction #134097 that would not fit on the form

## 32. Additional remarks, continued

03/12/12 TIH; set Pmp thru plug set @5380'.
03/14/12 TIH; tag fill @5855'.
03/15/12 Start clean out; well making frac sand; air mist cleanout to 6000'. POH above top perf @5706'.
03/16/12 Chart record tst seals 250 low; 3000 high; good passed. TIH; tag fill; clean out. TIH; land 2 3/8"; J-55; 4.7# Tbg @5804'.
03/19/12 SICP 110 psi; SITP 5 psi; SIBH 0.

Well shut in waiting on facilites and C-104 approval