Form 3160-5 (March 2012)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## RECEIVED

FORM APPROVED OMB No 1004-0137 Expires October 31, 2014

JUN 21 20 1 Lease Serial No.

g. Lease Serial No. NMNM78406C&d/NMNM013654

SUNDRY NOTICES AND REPORTS ON WELLESirmington Field 15 HI Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to Resenter of Cand Managemen abandoned well. Use Form 3160-3 (APD) for such proposals. 7 If Unit of CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Oil Well Gas Well Other Rincon #159R 2. Name of Operator Chevron Midcontinent L.P. 9. API Well No. 30-39-26998 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area Attn Regulatory Specialist 332 Road 3100 Azte Basin Dakota/Blanco Mesaverde Aztec, NM 87410 505-333-1941 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State 3'2026 4'0501 Rio Arriba, New Mexico #990 FSL #90 FEL Sec 27 Twp 25N Rng 5W 18 27N Lew 12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION \_\_ Acidize Deepen Production (Start/Resume) Water Shut-Off ✓ Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity ☑ Other DEICE 29 K 113 New Construction Casing Repair Recomplete Subsequent Report \_\_\_ Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13 Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Project tentatively planned to begin October 1, 2012 1. REMOVE TUBING. 2. SELECTIVELY PERFORATE MESAVERDE FORMATION (4865'-585\$) 5854 DIST. 3 3. FOAM-SAND FRAC STIMULATES THE MESAVERDE. 4. RUN PRODUCTION TUBING AND LAND AT ~ 7659'. 5. INSTALL PLUNGER LIFT EQUIPMENT. 6. DOWNHOLE COMMINGLE MESAVERDE AND EXISTING DAKOTA PRODUCING ZONE PER DHC-879 (211363 DHC 879 AZ 14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) April E. Pohl Title Regulatory Specialist THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Title 18 U S C Section 1001 and Title 43 U S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

entitle the applicant to conduct operations thereon

Conditions of approval, if any are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would



## Rincon Unit # 159R

Rio Arriba County, New Mexico Sec 18 – T 27N – R 6W Field: Basin API: 30-039-26998

- 1. REMOVE TUBING.
- 2. SELECTIVELY PERFORATE MESAVERDE FORMATION (4865'-5855')
- 3. FOAM-SAND FRAC STIMULATES THE MESAVERDE.
- 4. Run Production tubing and land at  $\sim 7659$ '.
- 5. INSTALL PLUNGER LIFT EQUIPMENT.
- 6. DOWNHOLE COMMINGLE MESAVERDE AND EXISTING DAKOTA PRODUCING ZONE.

## See Current Wellbore Diagram:

