## CEIVE

Form 3160-5 (August 2007)

TYPE OF SUBMISSION

## **UNITED STATES**

DEPARTMENT OF THE INTERIOR JUL 19 2012 BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No 1004-0137 Expires July 31, 2010

Lease Serial No

6. If Indian, Allottee or Tribe Name

 м	n	я	-(	•	റ	Λ	•
w	ш	и	-1	•	n	ч	•

Farmington Field Oil Bureau of Land Marsundry NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No 1. Type of Well Oil Well 8 Well Name and No. X Gas Well Other Reese Mesa 9 2. Name of Operator 9 API Well No **Burlington Resources Oil & Gas Company LP** 30-045-24710 3b Phone No (include area code) 10 Field and Pool or Exploratory Area 3a Address **Albino Pictured Cliffs** PO Box 4289, Farmington, NM 87499 (505) 326-9700 4 Location of Well (Footage, Sec., T,R,M., or Survey Description) 11 Country or Parish, State Unit D (NWNW), 790' FNL & 950' FWL, Sec.13, T32N, R8W San Juan **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity X Subsequent Report Casing Repair New Construction Recomplete Other Record Cleanup Plug and Abandon Change Plans Temporarily Abandon Final Abandonment Notice Plug Back Convert to Injection Water Disposal

TYPE OF ACTION

13. Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection )

When reviewing this well file it was discovered that there was a squeeze done in 1981 by Southland Royalty Company that was not reported.

5/8/81 MIRU Drake #25 @ 9:00a.m. PU 1 1/2", 2.90#, J-55, EVE, 10rd tbg & TIH w/ 3 7/8", mill to 3681'. Circ hole clean, POOH. Ran GR-CBL-VDL from 3681' to 2000'. Showed poor bonding in low PIC CL section. Ran log under 1000 psi, bonding ok thru perf interval. Pumped 400sx cmt down 4 1/2" x 8 5/8" annulus displaced to 350'. Final squeeze press 775 psi. WOC. TIH w/ 1 1/2" tbg, sptd 250 gals, 7 1/2% HCL across perf interval. Tested csg to 3500 psi, ok, POOH. Perf'd PIC CL from 3498'-3620' (11 holes). BKDN PIC CL w/ 825gals 15% HC & balls.

> RCVD JUL 25'12 OIL CONS. DIV. DIST. 3

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed)	<del></del>		
Dollie L. Busse	Title	Staff Regulatory Technicia	n
Signature Milia Pause	Date	7/18/12	
THIS SPACE FOR FEE	ERAL O	R STATE OFFICE USE	a made that the proper production arms and the profession and the pro-
Approved by			ASSETTE FOR THE CORD
		Title	JULD2.3 2012
Conditions of approval, if any, are attached Approval of this notice does not warrant o	000	GADARATAN TITI D AFTIGO	
that the applicant holds legal or equitable title to those rights in the subject lease which entitle the applicant to conduct operations thereon	would	Office	PAPAMOŢON FIELD OFFICE
Title 19 H.C.C. Section 1001 and Title 42 H.C.C. Section 1212 make it a prime for any	norson knos	unaly and wellfully to make to any den	artment or agency of the United States and

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. **WMULD** <sub>(v</sub>