	•				
Submit 3 Copies To Appropriate District	State of	New Mex	kico		Form C-103
Office District I	Energy, Minerals and Natural Resources				March 4, 2004
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	0.45 21021
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type	-045-31931 of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.				FEE
District IV	Santa Fe, NM 87505			6. State Oil & Ga	
1220 S. St. Francis Dr., Santa Fe, NM 87505		A 19	2879 70 3	В	3-10889-30
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEP PROPOSE PLUG BACK TO A					
PROPOSALS.)	ON FOR PERMIT (FOR	Or Co	2000		rner B Com
1. Type of Well:		[Ki Ko		8. Well Number	250S
Oil Well Gas Well X C	Other		on I		
2. Name of Operator		The state of the s		9. OGRID Numb	
Burlington Resources Oil & Gas Con	npany LP	9/0	1100711	10. Pool name or	14538
3. Address of Operator P.O. Box 4289, Farmington, NM 874	00_4280	4.31	Platta Charles		r wildcat Fruitland Coal
4. Well Location))-420)			Dasin	Ti ditianu Coai
ii won zoodion					
Unit Letter M:	feet from the _	South	line and	725 feet from the	<u>West</u> line
	T 4.5. 20NI	D	- OW NAME	. C	C - ···
Section 2	Township 30N 1. Elevation (Show w	Rang			County
1	1. Lievation (Show w	neinei DA,	<i>RRD</i> , R1, OR, etc.)		B ARRAGE AND A
12. Check Appropriate Box to In	dicate Nature of	Notice, R	eport or Other D	ata	
•••		Í	•		'DODT OF
NOTICE OF INTE PERFORM REMEDIAL WORK ☐ P		и П	SUB:	SEQUENT RE	:PORTOF: ALTERING CASING □
PERFORM REMEDIAL WORK	LUG AND ADANDOR	'	REWEDIAL WORK	`	ALTERING CASING []
TEMPORARILY ABANDON 🔲 C	HANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND
PULL OR ALTER CASING M	IULTIPLE		CASING TEST AN	1D []	ABANDONMENT
	OMPLETION		CEMENT JOB		
07//50		_	0.711.50		-
OTHER:			<u> </u>	oletion Details	<u>⊠</u>
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
or recompletion.					
2/24/05 MIRU Aztec #471. ND \	NH & NU BOP Te	st - OK P	T casing and blir	nds rams to 1500) # / 30 min OK
2/29/05 RIH w/6-1/4" bit & tagge					
D/O shoe & ahead to 2759' (TD). TD reached 3/1/05. Circ. hole. RIH w/underreamer & underreamed 6-1/4" hole to					
9-1/2" from 2501' - 2759'. Circ. he					
2759' w/ TOL @ 2456' (40' overla		•			
holes. RIH w/mill and milled perf	•				
WH. RIH pump and rods. Load ho	_		_		
3/7/05.		J			
I hereby certify that the information abo	re is true and comple	ata to the he	at of my knowledge	and boliof I four	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.					
Lat. 1	2n $<$ $<$				
SIGNATURE / May (MSTT	TITLE <u>Sr.</u>	Regulatory Specia	<u>list</u> DATE _	3/19/05
Type or print name Patsy Clugs	ton F-mail ad	dress neli	ıgston@br-inc.com	Telenhone No	505-326-9518
(This space for State use)		areos. por	.go.com.com	relephone 140.	505 520 7510
0/1-1	/	@1	IDEDWOOD -		MAR 3 1 2005
APPPROVED BY Charle The		TITLE_St	JPERVISOR DIST	RICT#3	ĎÄŤĖ LUUJ
Conditions of approval, if any:					