
Form 3160-5 (November 1994)

# UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0135 Expires July 31, 1996

BUR	5. Lease Serial No.			
SUNDRY N	SF 079150			
Do not use this	6. If Indian, Allottee or Tribe Name			
abandoned well.	Use Form 3160-3 (APD	) for such proposities 23 AM	10 51	
		DEAGUES	7. If Unit or CA/Agreement, Name and/or N	
SUBMIT IN TRIPLI	CATE – Other instru	octions on reverse side IVED	kt 2154	
1.		OTO PARMING TO	N MM	
Oil Well X Gas Well	8. Well Name and No.			
2. Name of Operator	Duff B Federal #2			
Elm Ridge Resources, Inc.	9. API Well No.			
3a. Address		3b. Phone No. (include area code)	30-043-20591	
P.O. Box 156, Bloomfield, NM 87413		(505) 632-3476 ext. 203	10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Blanco PC South	
			11. County or Parish, State	
860' FSL X 790' FWL Sec.1	Sandoval County, NM			
12. CHECK APPROPRIATE BOX	((ES) TO INDICATE NAT	TURE OF NOTICE, REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent  Subsequent Report	Acidize Alter Casing Casing Repair	Deepen Production Fracture Treat Reclamation New Construction Recomplete		
$\bar{\nu}$	Change Plans	X Plug and Abandon Temporaril	y Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back Water Disp	oosal	
If the proposal is to deepen directionally Attach the Bond under which the work Following completion of the involved ope	or recomplete horizontally, give will be performed or provide the rations. If the operation results is adonment Notices shall be filed	tils, including estimated starting date of any propulsubsurface locations and measured and true vertice Bond No. on file with BLM/BLA. Required sun a multiple completion or recompletion in a new only after all requirements, including reclamation,	al depths of all pertinent markers and zones sequent reports shall be filed within 30 days interval, a Form 3160-4 shall be filed once	
Elm Ridge Resources, Inc. re	equests approval to Pl	ug and Abandon this well accord	ding to the attached procedure.	



(Instructions on reverse)

fraudulent statements or representations as to any matter within its jurisdiction.

# Plugging Program for Duff B Federal #2:

- Plug 1: Set retainer at 2900'. Pump 5 sacks below retainer. Spot 29 sack plug above retainer to cover top of Pictured Cliffs, Fruitland Coal, and Ojo Alamo.
- Plug 2: With end of tubing at 1509, spot 12 sack balanced plug to cover top of Nacimiento from 1509-1409. 1968 / 1368
- Plug 3: Perf 4 holes @ 401'. Tie onto 4-1/2" casing and pump 115 sacks, or sufficient volume to bring cement top surface inside and outside 4-1/2" casing.

Cut off wellhead 3' below surface. Install dry hole marker. Reclaim location.

# **Elm Ridge Resources**

# **Pertinent Data Sheet**

Well Name:

**Duff B Federal #2** 

Footage:

860' FSL and 790' FWL

Location: County:

Section 19, T23N, R1W Sandoval County, NM

API#:

30-043-20591

Field:

South Blanco Pictured Cliffs

Elevation: 7377' KB

TD: 3175' KB

PBTD:

3080' KB

Completed:

11/10/81

#### **Casing Record:**

Hole Size	Casing Size	Wt.	Grade	Depth Set	Cement
12-1/4"	8-5/8"	24#	K-55	351'	300 sacks (Circ. to Surface)
7-7/8"	4-1/2"	10.5#	K-55	3175'	500 sacks TOC 715' (CBL)

#### **Formation Tops:**

Nacimiento 1459' Ojo Alamo 2626' Fruitland 2800' Fruitland Coal 2943' Pictured Cliffs 2975'

Perforations: Pictured Cliffs: 2915-2985'

### Wellbore Diagram Duff B Federal #2 SW/4 Sec. 19, T23N, R1W Sandoval County Co., NM API #30-043-20591

	12-1/4" OH 8-5/8" 24# set @ 351' Circulated cmt to surface
Nacimiento 1459'	TOC 751' (CBL)
Ojo Alamo 2626'	
Fruitland 2800'	
Fruitland Coal 2943'	Perforations: 2915-2985'
Pictured Cliffs 2975'	PBTD: 3080' KB TD: 3175' KB 4-1/2" 10.5# K-55 set @ 3175' KB