Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5. Lease Serial No NMSF078282

abandoned well. Use Form 3160-3 (APD) for இந்த இரும்திக் நிறி 12 06			6. If Indian, Allottee or Tribe Name
SUBMIT IN TR.	PLICATE - Other instructions on r	evasesipeed	7. If Unit or CA/Agreement, Name and/or No. NMNM78415A
☐ Oil Well 🛛 Gas Well 🔲 Other			8. Well Name and No.
2. Name of Operator ConocoPhillips Co.			San Juan 29-5 Unit #32G 9. API Well No.
3a. Address 3b. Phone No. (include area code)			30-039-27537
P.O. Box 2197, WL3-6081 Houston Tx 77252 (832)486-2463 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			10. Field and Pool, or Exploratory Area Blanco Mesaverde/Basin Dakota
Sec 29 T29N R5W NWSW 2270FSL 660FWL			11. County or Parish, State Rio Arriba NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION		
 □ Notice of Intent ☑ Subsequent Report □ Final Abandonment Notice 	☐ Acidize ☐ Deepen ☐ Alter Casing ☐ Fracture T ☐ Casing Repair ☐ New Cons ☐ Change Plans ☐ Plug and A	truction Recomplete Abandon Temporarily Aban	☐ Well Integrity ☑ Other Allocation
	Convert to Injection Plug Back	☐ Water Disposal	
If the proposal is to deepen dire Attach the Bond under which the following completion of the invitesting has been completed. Find determined that the site is ready ConocoPhillips requests a	extionally or recomplete horizontally, give subsurfine work will be performed or provide the Bond Novolved operations. If the operation results in a multiple and Abandonment Notices shall be filed only after a for final inspection.) Illocation on this well as per attached.	ace locations measured and true ver on file with BLM/BIA. Required iple completion or recompletion in all requirements, including reclamat This is in reference to DH	subsequent reports shall be filed within 30 days a new interval, a Form 3160-4 shall be filed once ion, have been completed, and the operator has
Name (Printed/Typed) Christina Gustartis	ng is the mid correct	Title Regulatory Specialist	
Signature) -	Date	
Chris Sustantia 08/09/2005			
Approved by Title Date			
	Jui bobb	Title Petr En	9. Date 8/22/05
Conditions of approval, if any, are certify that the applicant holds lega which would entitle the applicant to	attached. Approval of this notice does not warral of equitable title to those rights in the subject looking the conduct operations thereon.	ant or Office	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Allocation for the SAN JUAN 29-5 32G (API 300392753700)

The SAN JUAN 29-5 32G is an 80-acre Mesaverde/80-acre Dakota infill well located in the southwest quarter of Section 29-T29N-R5W, Rio Arriba County, NM. The well was drilled to a total depth in March 2005, perforated & fracture stimulated in May 2005, and ready for first delivery in July 2005.

Initial flow tests as reported by the field operator indicated:

Mesaverde (2-3/8" tubing set at 5306', perforations from 5414 - 5917' OA, composite plug at 6020') 6/27/05 ½" choke N/A* PSIG tubing pressure 300 PSIG FCP 1716 MCFPD + 0 BOPD + 30 BWPD

Dakota (2-3/8" tubing set at 7436', perforations from 7934 - 8005' OA, PBTD 8033', multi-pass production log) 7/6/05 1/2" choke 45 PSIG FTP 380 PSIG SICP 270** MCFPD + 0 BOPD + 5 BWPD

Based on these initial stabilized flow tests, calculated DHC allocation percentages are:

Fixed Allocation (Gas) Mesaverde 86% Dakota 14%

Fixed Allocation (Oil) Mesaverde 100% Dakota 0%

No oil was produced during these tests. Based on historical production data from offset wells, the Dakota is very dry and is expected to produce no oil. Therefore, 100% of any oil production should be allocated to the Mesaverde.

Please allocate production based on the above estimated percentages and call with any questions.

Thanks
Dan Hensley
832-486-2385

* Annular test - string float in tubing

** Rate measured with a production log, making multiple passes at varying speeds. Casing was shut-in with all production directed up tubing. Tubing set ~100' above the top Dakota perforation makes it possible to gauge a Dakota rate isolated from any Mesaverde influence (log run below the point where the shallower Mesaverde has already turned the corner and is going up tubing).

OF CONS. DA