Form 3160-5 (August 2007)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT


FORM	ΛPI	PRO	VED
OMB N	O. 1	004-	0135
Expires:	July	v 31.	2010


SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMNM01271  6. If Indian, Allotte	1	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/A	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well ☐ Oil Well ☑ Gas Well ☐ Other ☐ Other ☐ Oil Well ☑ Gas Well ☐ Other				8. Well Name and No. FLORANCE G 36E	
Name of Operator Contact: TOYA COLVIN BP AMERICA PRODUCTION CO. E-Mail: Toya.Colvin@bp.com			9. API Well No. 30-045-2413	8-00-S1	
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401	3b. Phone No. (include area code Ph: 281-366-7148		10. Field and Pool, or Exploratory BASIN DAKOTA		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State		
Sec 3 T30N R8W SESE 1060FSL 1045FEL 36.835007 N Lat, 107.656815 W Lon			SAN JUAN C	SAN JUAN COUNTY, NM	
12. СНЕСК АРРЕ	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	□ Temporarily Abandon		
arrho	☐ Convert to Injection	□ Plug Back	□ Water Disposal		
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final At- determined that the site is ready for fi  BP has evaluated the above in permission to plug the entire w	k will be performed or provide it operations. If the operation resulandonment Notices shall be filed nat inspection.)  nentioned well and finds not the provided in the performance of t	ne Bond No. on file with BLM/BL Its in a multiple completion or rec I only after all requirements, inclu	A. Required subsequent reports shall completion in a new interval, a Form 1 ding reclamation, have been complete	be filed within 30 days 3160-4 shall be filed once	
Please see attached P&A procedure.  RCVD FEB 21 '13 OIL CONS. DIV.					
			OIL	DIST. 3	
14. I hereby certify that the foregoing is	Electronic Submission #19 For BP AMERICA I	99212 verified by the BLM We PRODUCTION CO., sent to the ssing by STEVE MASON on the	ne Farmington	·	
Name (Printed/Typed) TOYA CO	LVIN	Title REGUL	ATORY ANALYST		
Signature (Electronic S	ubmission)	Date 02/18/2	2013		
	THIS SPACE FOR	R FEDERAL OR STATE			
Approved By STEPHEN MASON	Approval of this notice does n	<del> </del>	EUM ENGINEER	Date 02/19/2013	
ertify that the applicant holds legal or equenched would entitle the applicant to condu	itable title to those rights in the sect operations thereon.	ubject lease Office Farming		Cha Nina	
itle 18 U.S.C. Section 1001 and Title 43 l	J.S.C. Section 1212, make it a cr	ime for any person knowingly and	i willfully to make to any department	or agency of the United	

FLORANCE G 36E DK DAKOTA API#300-452413800 S03:T30:R08 NM

- 1. MIRU slickline
- 2. Pull RBP & DH gauges
- 3. Run CBL to verify cement in production liner annulus and production casing
- 4. Regulatory Agency to verify MIT of wellbore
- 5. MIRU Coil
- 6. Pump Cliffhouse, Menefee, PL, Mancos plug
  - a. 66102-6781' 6553'- 4595'
  - b. 20.6 bbls
- 7. Pump PC, Chacra plug
- a. 3359'-2980'
- 8. Pump Ojo plug (Kircland + O, Aland)
  - a. 1.9702-18702 2067 1790
  - b. 4-bbls
- Nacimiento pla 585-485 9. Pump surface plug
  - a. 415'-surface
  - b. 16.4 bbls
- 10. Cut off wellhead, verify cement on all annuli, top off as necessary
- 11. Install dryhole marker

BP American Production Co. Florance G 36E API 30-045-24138 Unit letter P SEC. 03, T30N, R08W 1060' FSL, 1045' FEL San Juan, NM **Dakota Formation** Lease number: NM 012711 P&A date - TBD





## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: 36E Florance G

## **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
- a) Bring the top of the Gallup/Mancos/Mesaverde plug to 4595'.
- b) Place the Chacra/7" Casing Shoe/4 ½" Liner Top/Pictured Cliffs plug from 3857' 2980' inside and outside the 4 ½" casing.
- c) Place the Fruitland plug from 2742' 2642'.
- d) Place the Kirtland/Ojo Alamo plug from 2067' 1790'.
- e) Place the Nacimiento plug from 585'- 485'.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.